

Qualifying Residential  
Furnaces

FortisBC

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Advance Comfort System	95G1UH070BE12*-*	95.0	\$500	Air Ease	A95UH2E070B12*-*	95.0	\$500
Advance Comfort System	95G1UH090CE16*-*	95.0	\$500	Air Ease	A95UH2E090C16*-*	95.0	\$500
Advance Comfort System	95G2DF045BE12*	95.0	\$500	Air Ease	A95UH2E110C20*-*	95.0	\$500
Advance Comfort System	95G2DF070BE16*	95.0	\$500	Air Ease	A95UH2E135D20*-*	95.0	\$500
Advance Comfort System	95G2DF090CE16*	95.0	\$500	Air Ease	A95UH2V045B12*-*	95.0	\$500
Advance Comfort System	95G2DF110CE20*	95.0	\$500	Air Ease	A95UH2V070B12*-*	95.0	\$500
Advance Comfort System	95G2UH045BE12*	95.0	\$500	Air Ease	A95UH2V090C12*-*	95.0	\$500
Advance Comfort System	95G2UH045BV12*-*	95.0	\$500	Air Ease	A95UH2V090C16*-*	95.0	\$500
Advance Comfort System	95G2UH070BE12*	95.0	\$500	Air Ease	A95UH2V090C20*-*	95.0	\$500
Advance Comfort System	95G2UH070BV12*-*	95.0	\$500	Air Ease	A95UH2V110C16*-*	95.0	\$500
Advance Comfort System	95G2UH090CE16*	95.0	\$500	Air Ease	A95UH2V110C20*-*	95.0	\$500
Advance Comfort System	95G2UH090CV12*-*	95.0	\$500	Air Ease	A95UH2V135D20*-*	95.0	\$500
Advance Comfort System	95G2UH090CV20*-*	95.0	\$500	Air Ease	A96DS2V045B12S-*	96.0	\$500
Advance Comfort System	95G2UH110CE20*	95.0	\$500	Air Ease	A96DS2V070B16S-*	96.0	\$500
Advance Comfort System	95G2UH110CV20*-*	95.0	\$500	Air Ease	A96DS2V090C20S-*	96.0	\$500
Advance Comfort System	95G2UH135DE20*	95.0	\$500	Air Ease	A96DS2V110C20S-*	96.0	\$500
Advance Comfort System	95G2UH135DV20*-*	95.0	\$500	Air Ease	A96US2V045B12S-*	96.0	\$500
Advance Comfort System	A95DF2V045B12*-*	95.0	\$500	Air Ease	A96US2V070B12S-*	96.0	\$500
Advance Comfort System	A95DF2V070B16*-*	95.0	\$500	Air Ease	A96US2V090C12S-*	96.0	\$500
Advance Comfort System	A95DF2V090C20*-*	95.0	\$500	Air Ease	A96US2V090C16S-*	96.0	\$500
Advance Comfort System	A95DF2V110C20*-*	95.0	\$500	Air Ease	A96US2V090C20S-*	96.0	\$500
Advance Comfort System	A95UH1E070B12*-*	95.0	\$500	Air Ease	A96US2V110C16S-*	96.0	\$500
Advance Comfort System	A95UH1E090C16*-*	95.0	\$500	Air Ease	A96US2V110C20S-*	96.0	\$500
Advance Comfort System	A95UH2E045B12*-*	95.0	\$500	Air Ease	A96US2V135D20S-*	96.0	\$500
Advance Comfort System	A95UH2V045B12*-*	95.0	\$500	Air Ease	A97DSMV070B12S-*	97.0	\$700
Advance Comfort System	A95UH2V070B12*-*	95.0	\$500	Air Ease	A97DSMV090C16S-*	97.0	\$700
Advance Comfort System	A95UH2V090C12*-*	95.0	\$500	Air Ease	A97DSMV090C20S-*	97.0	\$700
Advance Comfort System	A95UH2V090C16*-*	95.0	\$500	Air Ease	A97DSMV110C20S-*	97.0	\$700
Advance Comfort System	A95UH2V090C20*-*	95.0	\$500	Air Ease	A97USMV070B12S-*	97.0	\$700
Advance Comfort System	A95UH2V110C16*-*	95.0	\$500	Air Ease	A97USMV090C12S-*	97.0	\$700
Advance Comfort System	A95UH2V110C20*-*	95.0	\$500	Air Ease	A97USMV090C16S-*	97.0	\$700
Advance Comfort System	A95UH2V135D20*-*	95.0	\$500	Air Ease	A97USMV090C20S-*	97.0	\$700
Advance Comfort System	A97DSMV070B12S-*	97.0	\$700	Air Ease	A97USMV110C20S-*	97.0	\$700
Advance Comfort System	A97DSMV090C16S-*	97.0	\$700	Air Ease	A97USMV135D20S-*	97.0	\$700
Advance Comfort System	A97DSMV090C20S-*	97.0	\$700	Aire-Flo	95AF2DF045V12B-*	95.0	\$500
Advance Comfort System	A97DSMV110C20S-*	97.0	\$700	Aire-Flo	95AF2DF070V16B-*	95.0	\$500
Advance Comfort System	A97USMV070B12S-*	97.0	\$700	Aire-Flo	95AF2DF090V20C-*	95.0	\$500
Advance Comfort System	A97USMV090C12S-*	97.0	\$700	Aire-Flo	95AF2DF110V20C-*	95.0	\$500
Advance Comfort System	A97USMV090C16S-*	97.0	\$700	Aire-Flo	95AF2UH045V12B-*	95.0	\$500
Advance Comfort System	A97USMV090C20S-*	97.0	\$700	Aire-Flo	95AF2UH070V12B-*	95.0	\$500
Advance Comfort System	A97USMV110C20S-*	97.0	\$700	Aire-Flo	95AF2UH090V12C-*	95.0	\$500
Advance Comfort System	A97USMV135D20S-*	97.0	\$700	Aire-Flo	95AF2UH110V20C-*	95.0	\$500
Air Ease	A95DF2E045B12*-*	95.0	\$500	Aire-Flo	95AF2UH135V20D-*	95.0	\$500
Air Ease	A95DF2E070B16*-*	95.0	\$500	Airquest	G9MAC0601714A	97.0	\$700
Air Ease	A95DF2E090C16*-*	95.0	\$500	Airquest	G9MAC0602120A	98.0	\$700
Air Ease	A95DF2E110C20*-*	95.0	\$500	Airquest	G9MAC0801714A	97.0	\$700
Air Ease	A95DF2V045B12*-*	95.0	\$500	Airquest	G9MAC0802120A	97.0	\$700
Air Ease	A95DF2V070B16*-*	95.0	\$500	Airquest	G9MAC1002122A	97.0	\$700
Air Ease	A95DF2V090C20*-*	95.0	\$500	Airquest	G9MAC1202422A	97.0	\$700
Air Ease	A95DF2V110C20*-*	95.0	\$500	Airquest	G9MAE0601714A	97.0	\$700
Air Ease	A95UH1E070B12*-*	95.0	\$500	Airquest	G9MAE0602120A	98.0	\$700
Air Ease	A95UH1E090C16*-*	95.0	\$500	Airquest	G9MAE0801714A	97.0	\$700
Air Ease	A95UH2E045B12*-*	95.0	\$500	Airquest	G9MAE0802120A	97.0	\$700

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Airquest	G9MAE1002122A	97.0	\$700	Allied	A95UH2E110C20*-*	95.0	\$500
Airquest	G9MAE1202422A	97.0	\$700	Allied	A95UH2E135D20*-*	95.0	\$500
Airquest	G9MVE0401410A	96.0	\$500	Allied	A95UH2V045B12*-*	95.0	\$500
Airquest	G9MVE0401712A	96.0	\$500	Allied	A95UH2V070B12*-*	95.0	\$500
Airquest	G9MVE0601412A	95.0	\$500	Allied	A95UH2V090C12*-*	95.0	\$500
Airquest	G9MVE0601714A	96.0	\$500	Allied	A95UH2V090C16*-*	95.0	\$500
Airquest	G9MVE0801716A	96.0	\$500	Allied	A95UH2V090C20*-*	95.0	\$500
Airquest	G9MVE0802120A	96.0	\$500	Allied	A95UH2V110C16*-*	95.0	\$500
Airquest	G9MVE1002116A	96.0	\$500	Allied	A95UH2V110C20*-*	95.0	\$500
Airquest	G9MVE1002120A	96.0	\$500	Allied	A95UH2V135D20*-*	95.0	\$500
Airquest	G9MVE1202422A	96.0	\$500	Allied	A96DS2V045B12S-*	96.0	\$500
Airquest	G9MVT0401410A	96.0	\$500	Allied	A96DS2V070B16S-*	96.0	\$500
Airquest	G9MVT0601714A	96.0	\$500	Allied	A96DS2V090C20S-*	96.0	\$500
Airquest	G9MVT0801716A	96.0	\$500	Allied	A96DS2V110C20S-*	96.0	\$500
Airquest	G9MVT0802120A	96.0	\$500	Allied	A96US2V045B12S-*	96.0	\$500
Airquest	G9MVT1002120A	96.0	\$500	Allied	A96US2V070B12S-*	96.0	\$500
Airquest	G9MVT1202422A	96.0	\$500	Allied	A96US2V090C12S-*	96.0	\$500
Airquest	G9MXE0401410A	96.0	\$500	Allied	A96US2V090C16S-*	96.0	\$500
Airquest	G9MXE0401712A*	96.0	\$500	Allied	A96US2V090C20S-*	96.0	\$500
Airquest	G9MXE0601412A*	95.5	\$500	Allied	A96US2V110C16S-*	96.0	\$500
Airquest	G9MXE0601714A	96.0	\$500	Allied	A96US2V110C20S-*	96.0	\$500
Airquest	G9MXE0801716A	96.0	\$500	Allied	A96US2V135D20S-*	96.0	\$500
Airquest	G9MXE0802120A	96.0	\$500	Allied	A97DSMV070B12S-*	97.0	\$700
Airquest	G9MXT0401410A	96.0	\$500	Allied	A97DSMV090C16S-*	97.0	\$700
Airquest	G9MXT0601714A	96.0	\$500	Allied	A97DSMV090C20S-*	97.0	\$700
Airquest	G9MXT0801716A	96.0	\$500	Allied	A97DSMV110C20S-*	97.0	\$700
Airquest	G9MXT0802120A	96.0	\$500	Allied	A97USMV070B12S-*	97.0	\$700
Airquest	G9MXT1002120A	96.0	\$500	Allied	A97USMV090C12S-*	97.0	\$700
Airquest	G9MXT1202422A	96.0	\$500	Allied	A97USMV090C16S-*	97.0	\$700
Airtemp	VG7TC120*-D*	95.1	\$500	Allied	A97USMV090C20S-*	97.0	\$700
Allied	95G1UH070BE12*-*	95.0	\$500	Allied	A97USMV110C20S-*	97.0	\$700
Allied	95G1UH090CE16*-*	95.0	\$500	Allied	A97USMV135D20S-*	97.0	\$700
Allied	95G2DF045BE12*	95.0	\$500	Allied Air Enterprises	95AF2DF045V12B-*	95.0	\$500
Allied	95G2DF070BE16*	95.0	\$500	Allied Air Enterprises	95AF2DF070V16B-*	95.0	\$500
Allied	95G2DF090CE16*	95.0	\$500	Allied Air Enterprises	95AF2DF090V20C-*	95.0	\$500
Allied	95G2DF110CE20*	95.0	\$500	Allied Air Enterprises	95AF2DF110V20C-*	95.0	\$500
Allied	95G2UH045BE12*	95.0	\$500	Allied Air Enterprises	95AF2UH045V12B-*	95.0	\$500
Allied	95G2UH045BV12*-*	95.0	\$500	Allied Air Enterprises	95AF2UH070V12B-*	95.0	\$500
Allied	95G2UH070BE12*	95.0	\$500	Allied Air Enterprises	95AF2UH090V12C-*	95.0	\$500
Allied	95G2UH070BV12*-*	95.0	\$500	Allied Air Enterprises	95AF2UH110V20C-*	95.0	\$500
Allied	95G2UH090CE16*	95.0	\$500	Allied Air Enterprises	95AF2UH135V20D-*	95.0	\$500
Allied	95G2UH090CV12*-*	95.0	\$500	Allied Air Enterprises	95G1UH045BE12*-*	95.0	\$500
Allied	95G2UH090CV20*-*	95.0	\$500	Allied Air Enterprises	95G1UH070BE12*-*	95.0	\$500
Allied	95G2UH110CE20*	95.0	\$500	Allied Air Enterprises	95G1UH090CE16*-*	95.0	\$500
Allied	95G2UH110CV20*-*	95.0	\$500	Allied Air Enterprises	95G1UH110CE20*-*	95.0	\$500
Allied	95G2UH135DE20*	95.0	\$500	Allied Air Enterprises	95G2DF045BE12*	95.0	\$500
Allied	95G2UH135DV20*-*	95.0	\$500	Allied Air Enterprises	95G2DF070BE16*	95.0	\$500
Allied	A95DF2E045B12*-*	95.0	\$500	Allied Air Enterprises	95G2DF090CE16*	95.0	\$500
Allied	A95DF2E070B16*-*	95.0	\$500	Allied Air Enterprises	95G2DF110CE20*	95.0	\$500
Allied	A95DF2E090C16*-*	95.0	\$500	Allied Air Enterprises	95G2UH045BE12*	95.0	\$500
Allied	A95DF2E110C20*-*	95.0	\$500	Allied Air Enterprises	95G2UH045BV12*-*	95.0	\$500
Allied	A95DF2V045B12*-*	95.0	\$500	Allied Air Enterprises	95G2UH070BE12*	95.0	\$500
Allied	A95DF2V070B16*-*	95.0	\$500	Allied Air Enterprises	95G2UH070BV12*-*	95.0	\$500
Allied	A95DF2V090C20*-*	95.0	\$500	Allied Air Enterprises	95G2UH090CE16*	95.0	\$500
Allied	A95DF2V110C20*-*	95.0	\$500	Allied Air Enterprises	95G2UH090CV12*-*	95.0	\$500
Allied	A95UH1E070B12*-*	95.0	\$500	Allied Air Enterprises	95G2UH090CV20*-*	95.0	\$500
Allied	A95UH1E090C16*-*	95.0	\$500	Allied Air Enterprises	95G2UH110CE20*	95.0	\$500
Allied	A95UH2E045B12*-*	95.0	\$500	Allied Air Enterprises	95G2UH110CV20*-*	95.0	\$500
Allied	A95UH2E070B12*-*	95.0	\$500	Allied Air Enterprises	95G2UH135DE20*	95.0	\$500
Allied	A95UH2E090C16*-*	95.0	\$500	Allied Air Enterprises	95G2UH135DV20*-*	95.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Allied Air Enterprises	96G1UH030E08-*	96.1	\$500	Allied Air Enterprises	A97USMV070B12S-*	97.0	\$700
Allied Air Enterprises	96G1UH070BE12-*	96.1	\$500	Allied Air Enterprises	A97USMV090C12S-*	97.0	\$700
Allied Air Enterprises	96G1UH090BE16-*	96.3	\$500	Allied Air Enterprises	A97USMV090C16S-*	97.0	\$700
Allied Air Enterprises	96G1UH110BE20-*	96.4	\$500	Allied Air Enterprises	A97USMV090C20S-*	97.0	\$700
Allied Air Enterprises	A95DF2E045B12-*	95.0	\$500	Allied Air Enterprises	A97USMV110C20S-*	97.0	\$700
Allied Air Enterprises	A95DF2E070B16-*	95.0	\$500	Allied Air Enterprises	A97USMV135D20S-*	97.0	\$700
Allied Air Enterprises	A95DF2E090C16-*	95.0	\$500	Amana	ACVC950714CX	95.0	\$500
Allied Air Enterprises	A95DF2E110C20-*	95.0	\$500	Amana	ACVC950915DX	95.0	\$500
Allied Air Enterprises	A95DF2V045B12-*	95.0	\$500	Amana	ACVC960403BN	96.1	\$500
Allied Air Enterprises	A95DF2V070B16-*	95.0	\$500	Amana	ACVC960603BN	96.1	\$500
Allied Air Enterprises	A95DF2V090C20-*	95.0	\$500	Amana	ACVC960804CN	96.1	\$500
Allied Air Enterprises	A95DF2V110C20-*	95.0	\$500	Amana	ACVC961005CN	96.1	\$500
Allied Air Enterprises	A95UH1E045B12-*	95.0	\$500	Amana	ACVC961205DN	96.1	\$500
Allied Air Enterprises	A95UH1E070B12-*	95.0	\$500	Amana	ACVM960604CX	96.1	\$500
Allied Air Enterprises	A95UH1E090C16-*	95.0	\$500	Amana	ACVM960805DX	96.1	\$500
Allied Air Enterprises	A95UH1E110C20-*	95.0	\$500	Amana	ACVM961005DX	96.1	\$500
Allied Air Enterprises	A95UH1E135D20-*	95.0	\$500	Amana	ACVM970603BN	97.0	\$700
Allied Air Enterprises	A95UH2E045B12-*	95.0	\$500	Amana	ACVM970803BN	97.0	\$700
Allied Air Enterprises	A95UH2E070B12-*	95.0	\$500	Amana	ACVM970804CN	97.0	\$700
Allied Air Enterprises	A95UH2E090C16-*	95.0	\$500	Amana	ACVM971005CN	97.0	\$700
Allied Air Enterprises	A95UH2E110C20-*	95.0	\$500	Amana	AMEC960302BN	96.1	\$500
Allied Air Enterprises	A95UH2E135D20-*	95.0	\$500	Amana	AMEC960603BN	96.0	\$500
Allied Air Enterprises	A95UH2V045B12-*	95.0	\$500	Amana	AMEC961004CN	96.1	\$500
Allied Air Enterprises	A95UH2V070B12-*	95.0	\$500	Amana	AMEC961205DN	96.1	\$500
Allied Air Enterprises	A95UH2V090C12-*	95.0	\$500	Amana	AMVC950453BX	96.1	\$500
Allied Air Enterprises	A95UH2V090C16-*	95.0	\$500	Amana	AMVC950704CX	96.1	\$500
Allied Air Enterprises	A95UH2V090C20-*	95.0	\$500	Amana	AMVC950905CX**	96.1	\$500
Allied Air Enterprises	A95UH2V110C16-*	95.0	\$500	Amana	AMVC950905DX	96.1	\$500
Allied Air Enterprises	A95UH2V110C20-*	95.0	\$500	Amana	AMVC951155DX	96.1	\$500
Allied Air Enterprises	A95UH2V135D20-*	95.0	\$500	Amana	AMVC960403BN	96.1	\$500
Allied Air Enterprises	A96DF2E045B12-*	96.0	\$500	Amana	AMVC960603BN	96.1	\$500
Allied Air Enterprises	A96DF2E070B16-*	96.0	\$500	Amana	AMVC960803BN	96.1	\$500
Allied Air Enterprises	A96DF2E090C16-*	96.0	\$500	Amana	AMVC960804CN	96.1	\$500
Allied Air Enterprises	A96DF2E110C20-*	96.0	\$500	Amana	AMVC961005CN	96.1	\$500
Allied Air Enterprises	A96DS2V045B12-*	96.0	\$500	Amana	AMVC961205DN	96.1	\$500
Allied Air Enterprises	A96DS2V070B16-*	96.0	\$500	Amana	AMVM960603BX	96.1	\$500
Allied Air Enterprises	A96DS2V090C20-*	96.0	\$500	Amana	AMVM960805CX	96.1	\$500
Allied Air Enterprises	A96DS2V110C20-*	96.0	\$500	Amana	AMVM961005DX	96.1	\$500
Allied Air Enterprises	A96UH2E030B08-*	96.0	\$500	Amana	AMVM961155DX	96.1	\$500
Allied Air Enterprises	A96UH2E045B12-*	95.0	\$500	Amana	AMVM970603BN	97.0	\$700
Allied Air Enterprises	A96UH2E070B12-*	96.0	\$500	Amana	AMVM970803BN	97.0	\$700
Allied Air Enterprises	A96UH2E090C16-*	96.0	\$500	Amana	AMVM970804CN	97.0	\$700
Allied Air Enterprises	A96UH2E110C20-*	96.0	\$500	Amana	AMVM971005CN	97.0	\$700
Allied Air Enterprises	A96UH2E135D20-*	96.0	\$500	Amana	AMVM971205DN	97.0	\$700
Allied Air Enterprises	A96US2V045B12-*	96.0	\$500	American Standard	ADH2B060A9V3VB*	96.0	\$500
Allied Air Enterprises	A96US2V070B12-*	96.0	\$500	American Standard	ADH2B080A9V3VB*	96.0	\$500
Allied Air Enterprises	A96US2V090C12-*	96.0	\$500	American Standard	ADH2B080A9V4VB*	95.0	\$500
Allied Air Enterprises	A96US2V090C16-*	96.0	\$500	American Standard	ADH2C100A9V4VB*	96.0	\$500
Allied Air Enterprises	A96US2V090C20-*	96.0	\$500	American Standard	ADH2D120A9V5VB*	96.0	\$500
Allied Air Enterprises	A96US2V110C16-*	96.0	\$500	American Standard	ADHMB060BCV3VB*	95.0	\$500
Allied Air Enterprises	A96US2V110C20-*	96.0	\$500	American Standard	ADHMB080ACV3VB*	96.0	\$500
Allied Air Enterprises	A96US2V135D20-*	96.0	\$500	American Standard	ADHMC100ACV4VB*	96.0	\$500
Allied Air Enterprises	A97DSMV070B12S-*	97.0	\$700	American Standard	ADHMD120BCV5VB*	95.0	\$500
Allied Air Enterprises	A97DSMV090B16S-*	97.0	\$700	American Standard	AUH1D120A9H51B*	95.0	\$500
Allied Air Enterprises	A97DSMV090B20S-*	97.0	\$700	American Standard	AUH2B060A9V3VB*	97.0	\$700
Allied Air Enterprises	A97DSMV110B20S-*	97.0	\$700	American Standard	AUH2B080A9V3VB*	97.0	\$700
Allied Air Enterprises	A97US2V040B12X-*	97.5	\$700	American Standard	AUH2B080A9V4VB*	97.0	\$700
Allied Air Enterprises	A97US2V060B12X-**	97.5	\$700	American Standard	AUH2C100A9V4VB*	96.7	\$500
Allied Air Enterprises	A97US2V080C16X-*	97.5	\$700	American Standard	AUH2C100A9V5VB*	96.7	\$500
Allied Air Enterprises	A97US2V080C20X-*	97.5	\$700	American Standard	AUH2D120A9V5VB*	96.7	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
American Standard	AUHMB060ACV3VB*	97.3	\$700	Arcoaire	F9MXT0801716A	96.0	\$500
American Standard	AUHMB080ACV3VB*	96.7	\$500	Arcoaire	F9MXT0802120A	96.0	\$500
American Standard	AUHMD120ACV5VB*	97.0	\$700	Arcoaire	F9MXT1002120A	96.0	\$500
American Standard	S9V2B040D3PSAA*	96.0	\$500	Arcoaire	F9MXT1202422A	96.0	\$500
American Standard	S9V2B040U3PSAA*	96.0	\$500	Armstrong	A95DF2E045B12*-*	95.0	\$500
American Standard	S9V2B060D3PSAA*	96.0	\$500	Armstrong	A95DF2E070B16*-*	95.0	\$500
American Standard	S9V2B060U3PSAA*	96.0	\$500	Armstrong	A95DF2E090C16*-*	95.0	\$500
American Standard	S9V2B060U4PSAA*	96.0	\$500	Armstrong	A95DF2E110C20*-*	95.0	\$500
American Standard	S9V2B080D3PSAA*	96.0	\$500	Armstrong	A95DF2V045B12*-*	95.0	\$500
American Standard	S9V2B080D4PSAA*	96.0	\$500	Armstrong	A95DF2V070B16*-*	95.0	\$500
American Standard	S9V2B080U3PSAA*	96.0	\$500	Armstrong	A95DF2V090C20*-*	95.0	\$500
American Standard	S9V2B080U4PSAA*	96.0	\$500	Armstrong	A95DF2V110C20*-*	95.0	\$500
American Standard	S9V2C080U5PSAA*	96.0	\$500	Armstrong	A95UH2E045B12*-*	95.0	\$500
American Standard	S9V2C100D4PSAA*	96.0	\$500	Armstrong	A95UH2E070B12*-*	95.0	\$500
American Standard	S9V2C100D5PSAA*	96.0	\$500	Armstrong	A95UH2E090C16*-*	95.0	\$500
American Standard	S9V2C100U4PSAA*	96.0	\$500	Armstrong	A95UH2E110C20*-*	95.0	\$500
American Standard	S9V2C100U5PSAA*	96.0	\$500	Armstrong	A95UH2E135D20*-*	95.0	\$500
American Standard	S9V2D120D5PSAA*	96.0	\$500	Armstrong	A95UH2V045B12*-*	95.0	\$500
American Standard	S9V2D120U5PSAA*	96.0	\$500	Armstrong	A95UH2V070B12*-*	95.0	\$500
Ameristar	M952V060BD36AA*	96.0	\$500	Armstrong	A95UH2V090C12*-*	95.0	\$500
Ameristar	M952V060BU36AA*	97.0	\$700	Armstrong	A95UH2V090C16*-*	95.0	\$500
Ameristar	M952V080BD36AA*	96.0	\$500	Armstrong	A95UH2V090C20*-*	95.0	\$500
Ameristar	M952V080BU36AA*	97.0	\$700	Armstrong	A95UH2V110C16*-*	95.0	\$500
Ameristar	M952V100CD48AA*	96.0	\$500	Armstrong	A95UH2V110C20*-*	95.0	\$500
Ameristar	M952V100CU48AA*	96.7	\$500	Armstrong	A95UH2V135D20*-*	95.0	\$500
Ameristar	M952V120DD60AA*	96.0	\$500	Armstrong Air	A95UH1E070B12*-*	95.0	\$500
Ameristar	M952V120DU60AA*	96.7	\$500	Armstrong Air	A95UH1E090C16*-*	95.0	\$500
Arcoaire	F9MAC0601714A	97.0	\$700	Armstrong Air	A96DS2V045B12S*-*	96.0	\$500
Arcoaire	F9MAC0602120A	98.0	\$700	Armstrong Air	A96DS2V070B16S*-*	96.0	\$500
Arcoaire	F9MAC0801714A	97.0	\$700	Armstrong Air	A96DS2V090C20S*-*	96.0	\$500
Arcoaire	F9MAC0802120A	97.0	\$700	Armstrong Air	A96DS2V110C20S*-*	96.0	\$500
Arcoaire	F9MAC1002122A	97.0	\$700	Armstrong Air	A96US2V045B12S*-*	96.0	\$500
Arcoaire	F9MAC1202422A	97.0	\$700	Armstrong Air	A96US2V070B12S*-*	96.0	\$500
Arcoaire	F9MAE0601714A	97.0	\$700	Armstrong Air	A96US2V090C12S*-*	96.0	\$500
Arcoaire	F9MAE0602120A	98.0	\$700	Armstrong Air	A96US2V090C16S*-*	96.0	\$500
Arcoaire	F9MAE0801714A	97.0	\$700	Armstrong Air	A96US2V090C20S*-*	96.0	\$500
Arcoaire	F9MAE0802120A	97.0	\$700	Armstrong Air	A96US2V110C16S*-*	96.0	\$500
Arcoaire	F9MAE1002122A	97.0	\$700	Armstrong Air	A96US2V110C20S*-*	96.0	\$500
Arcoaire	F9MAE1202422A	97.0	\$700	Armstrong Air	A96US2V135D20S*-*	96.0	\$500
Arcoaire	F9MVE0401410A	96.0	\$500	Armstrong Air	A97DSMV070B12S*-*	97.0	\$700
Arcoaire	F9MVE0401712A	96.0	\$500	Armstrong Air	A97DSMV090C16S*-*	97.0	\$700
Arcoaire	F9MVE0601412A	95.0	\$500	Armstrong Air	A97DSMV090C20S*-*	97.0	\$700
Arcoaire	F9MVE0601714A	96.0	\$500	Armstrong Air	A97DSMV110C20S*-*	97.0	\$700
Arcoaire	F9MVE0801716A	96.0	\$500	Armstrong Air	A97USMV070B12S*-*	97.0	\$700
Arcoaire	F9MVE0802120A	96.0	\$500	Armstrong Air	A97USMV090C12S*-*	97.0	\$700
Arcoaire	F9MVE1002120A	96.0	\$500	Armstrong Air	A97USMV090C16S*-*	97.0	\$700
Arcoaire	F9MVE1202422A	96.0	\$500	Armstrong Air	A97USMV090C20S*-*	97.0	\$700
Arcoaire	F9MVT0401410A	96.0	\$500	Armstrong Air	A97USMV110C20S*-*	97.0	\$700
Arcoaire	F9MVT0601714A	96.0	\$500	Armstrong Air	A97USMV135D20S*-*	97.0	\$700
Arcoaire	F9MVT0801716A	96.0	\$500	Broan	FG7MQ060*-VB	97.0	\$700
Arcoaire	F9MVT0802120A	96.0	\$500	Broan	FG7MQ080*-VC	97.2	\$700
Arcoaire	F9MVT1002120A	96.0	\$500	Broan	FG7MQ100*-VC	97.4	\$700
Arcoaire	F9MVT1202422A	96.0	\$500	Broan	FG7MQ120*-VD	97.0	\$700
Arcoaire	F9MXE0401712A	96.0	\$500	Broan	FG7TC120*-D*	95.1	\$500
Arcoaire	F9MXE0601412A	95.5	\$500	Broan	KG7TC120*-D*	95.1	\$500
Arcoaire	F9MXE1002120A*	96.0	\$500	Bryant	922SA30040E14	92.0	\$500
Arcoaire	F9MXT0401410A	96.0	\$500	Bryant	922SA36040E17	92.0	\$500
Arcoaire	F9MXT0401712A	96.0	\$500	Bryant	922SA36060E14	92.0	\$500
Arcoaire	F9MXT0601412A	95.0	\$500	Bryant	922SA42060E17	92.0	\$500
Arcoaire	F9MXT0601714A	96.0	\$500	Bryant	922SA48080E17	92.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Bryant	922SA60080E21	92.0	\$500	Bryant	987MA66120V24*D	95.0	\$500
Bryant	922SA60100E21	92.0	\$500	Bryant	987MA66120V24A	97.0	\$700
Bryant	922SA60120E24	92.0	\$500	Bryant (Carrier)	925SA30024E14	96.0	\$500
Bryant	925SA30024E14	96.0	\$500	Bryant (Carrier)	925SA30026E14*D	95.0	\$500
Bryant	925SA30026E14*D	95.0	\$500	Bryant (Carrier)	925SA30040E14*D	95.0	\$500
Bryant	925SA30040E14*D	95.0	\$500	Bryant (Carrier)	925SA30040E14A	96.0	\$500
Bryant	925SA30040E14A	96.0	\$500	Bryant (Carrier)	925SA36040E17*D	95.0	\$500
Bryant	925SA36040E17	96.5	\$500	Bryant (Carrier)	925SA36040E17A	96.0	\$500
Bryant	925SA36040E17*D	95.0	\$500	Bryant (Carrier)	925SA42060E17*D	95.0	\$500
Bryant	925SA36060E14	95.5	\$500	Bryant (Carrier)	925SA42060E17A	96.0	\$500
Bryant	925SA42060E17*D	95.0	\$500	Bryant (Carrier)	925SA48080E17	96.0	\$500
Bryant	925SA42060E17A	96.0	\$500	Bryant (Carrier)	925SA60080E21	96.0	\$500
Bryant	925SA48080E17	96.0	\$500	Bryant (Carrier)	925SA60080E21*D	95.0	\$500
Bryant	925SA60080E21	96.0	\$500	Bryant (Carrier)	925SA60100E21	96.0	\$500
Bryant	925SA60080E21*D	95.0	\$500	Bryant (Carrier)	926TA30040V14	97.0	\$700
Bryant	925SA60100E21	96.0	\$500	Bryant (Carrier)	926TA30040V14*D	95.0	\$500
Bryant	925TA30040E14A	96.2	\$500	Bryant (Carrier)	926TA36040V17	96.0	\$500
Bryant	925TA36040E17	96.0	\$500	Bryant (Carrier)	926TA36040V17*D	95.0	\$500
Bryant	925TA36060E14	95.0	\$500	Bryant (Carrier)	926TA36060V14	95.0	\$500
Bryant	925TA42060E17A	96.2	\$500	Bryant (Carrier)	926TA36060V14*D	95.0	\$500
Bryant	925TA48080E17A	96.2	\$500	Bryant (Carrier)	926TA42060V17	96.0	\$500
Bryant	925TA60080E21	96.2	\$500	Bryant (Carrier)	926TA42060V17*D	95.0	\$500
Bryant	925TA60100E21	96.1	\$500	Bryant (Carrier)	926TA48080V17	96.0	\$500
Bryant	925TA66120E24A	96.2	\$500	Bryant (Carrier)	926TA48080V17*D	95.0	\$500
Bryant	926TA30040V14	97.0	\$700	Bryant (Carrier)	926TA60080V21	97.0	\$700
Bryant	926TA30040V14*D	95.0	\$500	Bryant (Carrier)	926TA60080V21*D	95.0	\$500
Bryant	926TA36040V17	96.0	\$500	Bryant (Carrier)	926TA60100V21	96.0	\$500
Bryant	926TA36040V17*D	95.0	\$500	Bryant (Carrier)	926TA60100V21*D	95.0	\$500
Bryant	926TA36060V14	95.0	\$500	Bryant (Carrier)	926TA66120V24	97.0	\$700
Bryant	926TA36060V14*D	95.0	\$500	Bryant (Carrier)	926TA66120V24*D	95.0	\$500
Bryant	926TA42060V17	96.0	\$500	Bryant (Carrier)	986TB42060V17	96.0	\$500
Bryant	926TA42060V17*D	95.0	\$500	Bryant (Carrier)	986TB42060V17*D	95.0	\$500
Bryant	926TA48080V17	96.0	\$500	Bryant (Carrier)	986TB42080V17	96.0	\$500
Bryant	926TA48080V17*D	95.0	\$500	Bryant (Carrier)	986TB42080V17*D	95.0	\$500
Bryant	926TA60080V21	97.0	\$700	Bryant (Carrier)	986TB60080V21	97.0	\$700
Bryant	926TA60080V21*D	95.0	\$500	Bryant (Carrier)	986TB60080V21*D	95.0	\$500
Bryant	926TA60100V21	96.0	\$500	Bryant (Carrier)	986TB66100V21	96.0	\$500
Bryant	926TA60100V21*D	95.0	\$500	Bryant (Carrier)	986TB66100V21*D	95.0	\$500
Bryant	926TA66120V24	97.0	\$700	Bryant (Carrier)	986TB66120V24	97.0	\$700
Bryant	926TA66120V24*D	95.0	\$500	Bryant (Carrier)	986TB66120V24*D	95.0	\$500
Bryant	986TA42060V17A-A	96.7	\$500	Bryant (Carrier)	987MA42060V17*D	95.0	\$500
Bryant	986TB42060V17	96.0	\$500	Bryant (Carrier)	987MA42060V17A	97.0	\$700
Bryant	986TB42060V17*D	95.0	\$500	Bryant (Carrier)	987MA42080V17*D	95.0	\$500
Bryant	986TB42080V17	96.0	\$500	Bryant (Carrier)	987MA42080V17A	97.0	\$700
Bryant	986TB42080V17*D	95.0	\$500	Bryant (Carrier)	987MA60060V21	98.0	\$700
Bryant	986TB60080V21	97.0	\$700	Bryant (Carrier)	987MA60060V21*D	97.0	\$700
Bryant	986TB60080V21*D	95.0	\$500	Bryant (Carrier)	987MA60080V21	97.0	\$700
Bryant	986TB66100V21	96.0	\$500	Bryant (Carrier)	987MA60080V21*D	95.0	\$500
Bryant	986TB66100V21*D	95.0	\$500	Bryant (Carrier)	987MA66100V21	97.0	\$700
Bryant	986TB66120V24	97.0	\$700	Bryant (Carrier)	987MA66120V24*D	95.0	\$500
Bryant	986TB66120V24*D	95.0	\$500	Bryant (Carrier)	987MA66120V24A	97.0	\$700
Bryant	987MA42060V17*D	95.0	\$500	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA30026E14	96.0	\$500
Bryant	987MA42060V17A	97.0	\$700	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA36060E14*D	95.0	\$500
Bryant	987MA42080V17*D	95.0	\$500	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA48080E17*D	95.0	\$500
Bryant	987MA42080V17A	97.0	\$700	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA60100E21*D	95.0	\$500
Bryant	987MA60060V21	98.0	\$700	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA66120E24*D	95.0	\$500
Bryant	987MA60060V21*D	97.0	\$700	Bryant Heating and Cooling Systems (Carrier Corporation)	925SA66120E24A	96.2	\$500
Bryant	987MA60080V21	97.0	\$700				
Bryant	987MA60080V21*D	95.0	\$500				
Bryant	987MA66100V21	97.0	\$700				

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Bryant Heating and Cooling Systems (Carrier Corporation)	987MA66100V21*D	95.0	\$500	Carrier	59TP6A060E14--12*D	95.0	\$500
Carrier	59MN7A060V17--14	97.0	\$700	Carrier	59TP6A060E17--14	96.0	\$500
Carrier	59MN7A060V17--14*D	95.0	\$500	Carrier	59TP6A060E17--14*D	95.0	\$500
Carrier	59MN7A060V21--20	99.0	\$700	Carrier	59TP6A080E17--16	96.0	\$500
Carrier	59MN7A060V21--20*D	97.0	\$700	Carrier	59TP6A080E17--16*D	95.0	\$500
Carrier	59MN7A080V17--14	97.0	\$700	Carrier	59TP6A080E21--20	97.0	\$700
Carrier	59MN7A080V17--14*D	95.0	\$500	Carrier	59TP6A080E21--20*D	95.0	\$500
Carrier	59MN7A080V21--20	97.0	\$700	Carrier	59TP6A100E21--20	96.0	\$500
Carrier	59MN7A080V21--20*D	95.0	\$500	Carrier	59TP6A100E21--20*D	95.0	\$500
Carrier	59MN7A100V21--22	97.0	\$700	Carrier	59TP6A120E24--22	97.0	\$700
Carrier	59MN7A120V24--22	97.0	\$700	Carrier	59TP6A120E24--22*D	95.0	\$500
Carrier	59MN7A120V24--22*D	95.0	\$500	Carrier	A2X95-030040	96.2	\$500
Carrier	59SP2A040E14--10	92.0	\$500	Carrier	A2X95-036040E17	96.0	\$500
Carrier	59SP2A040E17--12	92.0	\$500	Carrier	A2X95-036060E14	95.0	\$500
Carrier	59SP2A060E17--14	92.0	\$500	Carrier	A2X95-048060	96.2	\$500
Carrier	59SP2A080E17--16	92.0	\$500	Carrier	A2X95-048080	96.2	\$500
Carrier	59SP2A080E21--20	92.0	\$500	Carrier	A2X95-060080	96.2	\$500
Carrier	59SP2A100E21--20	96.0	\$500	Carrier	A2X95-060080**	95.5	\$500
Carrier	59SP2A120E24--20	96.0	\$500	Carrier	A2X95-060100	96.1	\$500
Carrier	59SP5A026E14--10	96.0	\$500	Carrier	A2X95-060100**	95.5	\$500
Carrier	59SP5A026E14--10*D	95.0	\$500	Carrier	A2X95-066120	96.2	\$500
Carrier	59SP5A040E14--10	97.0	\$700	Carrier	A2X95-30040	95.5	\$500
Carrier	59SP5A040E14--10*	96.5	\$500	Carrier	A2X95-48060	95.5	\$500
Carrier	59SP5A040E14--10*D	95.0	\$500	Carrier	A2X95-48080	95.5	\$500
Carrier	59SP5A040E17--12	97.0	\$700	Carrier	A2X95-66120	95.5	\$500
Carrier	59SP5A040E17--12*D	95.0	\$500	Carrier	AMV098-066120	97.0	\$700
Carrier	59SP5A060E14--12	95.5	\$500	Carrier	AMV98-042060	97.0	\$700
Carrier	59SP5A060E17--14	97.0	\$700	Carrier	AMV98-042080	97.0	\$700
Carrier	59SP5A060E17--14*	96.5	\$500	Carrier	AMV98-060060	98.3	\$700
Carrier	59SP5A060E17--14*D	95.0	\$500	Carrier	AMV98-060080	97.0	\$700
Carrier	59SP5A080E17--16	97.0	\$700	Carrier	AMV98-066100*	97.0	\$700
Carrier	59SP5A080E17--16*	96.5	\$500	Carrier	PG95XAT30040A	95.0	\$500
Carrier	59SP5A080E21--20	97.0	\$700	Carrier	PG95XAT30040A*D	95.0	\$500
Carrier	59SP5A080E21--20*	96.5	\$500	Carrier	PG95XAT36040B*	96.0	\$500
Carrier	59SP5A080E21--20*D	95.0	\$500	Carrier	PG95XAT36040B**D	95.0	\$500
Carrier	59SP5A100E21--20*	96.3	\$500	Carrier	PG95XAT36060A*	95.0	\$500
Carrier	59TN6A060V17--14	96.0	\$500	Carrier	PG95XAT36060A**D	95.0	\$500
Carrier	59TN6A060V17--14*D	95.0	\$500	Carrier	PG95XAT42060B	95.0	\$500
Carrier	59TN6A080V17--14	96.0	\$500	Carrier	PG95XAT42060B*D	95.0	\$500
Carrier	59TN6A080V17--14*D	95.0	\$500	Carrier	PG95XAT48080B	95.0	\$500
Carrier	59TN6A080V21--20	97.0	\$700	Carrier	PG95XAT48080B*D	95.0	\$500
Carrier	59TN6A080V21--20*D	95.0	\$500	Carrier	PG95XAT60080C	95.0	\$500
Carrier	59TN6A100V21--22	96.0	\$500	Carrier	PG95XAT60080C*D	95.0	\$500
Carrier	59TN6A100V21--22*D	95.0	\$500	Carrier	PG95XAT60100C	95.0	\$500
Carrier	59TN6A120V24--22	97.0	\$700	Carrier	PG95XAT60100C*D	95.0	\$500
Carrier	59TN6A120V24--22*D	95.0	\$500	Carrier	PG95XAT66120D	95.0	\$500
Carrier	59TP5A040E14--10	96.5	\$500	Carrier	PG95XAT66120D*D	95.0	\$500
Carrier	59TP5A040E17--12	96.0	\$500	Carrier	PG96VAT30040A	96.0	\$500
Carrier	59TP5A060E14--12	95.0	\$500	Carrier	PG96VAT42060B	96.0	\$500
Carrier	59TP5A060E17--14	96.3	\$500	Carrier	PG96VAT48080B	96.0	\$500
Carrier	59TP5A080E17--16	96.2	\$500	Carrier	PG96VAT60080C	96.0	\$500
Carrier	59TP5A080E21--20	96.7	\$500	Carrier	PG96VAT60100C	96.0	\$500
Carrier	59TP5A100E21--20	96.1	\$500	Carrier	PG96VAT66120D	96.0	\$500
Carrier	59TP5A120E24--22	96.7	\$500	Carrier Corporation	59MN7A100V21--22*D	95.0	\$500
Carrier	59TP6A040E14--10	97.0	\$700	Carrier Corporation	59SP5A026E14--10	96.0	\$500
Carrier	59TP6A040E14--10*D	95.0	\$500	Carrier Corporation	59TP6A040E14--10	97.0	\$700
Carrier	59TP6A040E17--12	96.0	\$500	Carrier Corporation	59TP6A040E17--12	96.0	\$500
Carrier	59TP6A040E17--12*D	95.0	\$500	Carrier Corporation	59TP6A060E14--12	95.0	\$500
Carrier	59TP6A060E14--12	95.0	\$500	Carrier Corporation	59TP6A060E17--14	96.0	\$500
Carrier	59TP6A060E17--14	96.0	\$500	Carrier Corporation	59TP6A080E17--16	96.0	\$500
Carrier	59TP6A060E17--14*	95.0	\$500				

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Carrier Corporation	59TP6A080E21--20	97.0	\$700	Concord	95G2DF045BE12*	95.0	\$500
Carrier Corporation	59TP6A100E21--20	96.0	\$500	Concord	95G2DF070BE16*	95.0	\$500
Carrier Corporation	59TP6A120E24--22	97.0	\$700	Concord	95G2DF090CE16*	95.0	\$500
Century	GUH95T120D5XE	95.1	\$500	Concord	95G2DF110CE20*	95.0	\$500
Coleman	CP9C060B12MP12	97.5	\$700	Concord	95G2UH045BE12*	95.0	\$500
Coleman	CP9C060B12MP12CA	97.5	\$700	Concord	95G2UH045BV12-*	95.0	\$500
Coleman	CP9C080B12MP12	97.5	\$700	Concord	95G2UH070BE12*	95.0	\$500
Coleman	CP9C080B12MP12CA	97.5	\$700	Concord	95G2UH070BV12-*	95.0	\$500
Coleman	CP9C080C16MP12	97.7	\$700	Concord	95G2UH090CE16*	95.0	\$500
Coleman	CP9C080C16MP12CA	97.7	\$700	Concord	95G2UH090CV12-*	95.0	\$500
Coleman	CP9C100C16MP12	97.7	\$700	Concord	95G2UH090CV20-*	95.0	\$500
Coleman	CP9C100C16MP12CA	97.7	\$700	Concord	95G2UH110CE20*	95.0	\$500
Coleman	CP9C100C20MP12	97.7	\$700	Concord	95G2UH110CV20-*	95.0	\$500
Coleman	CP9C100C20MP12CA	97.7	\$700	Concord	95G2UH135DE20*	95.0	\$500
Coleman	CP9C120D20MP12	98.0	\$700	Concord	95G2UH135DV20-*	95.0	\$500
Coleman	CP9C120D20MP12CA	98.0	\$700	Continental	CPV040T2B	96.0	\$500
Coleman	MG9S060B12MP11B	95.5	\$500	Continental	CPV060T3B	96.0	\$500
Coleman	TP9C120D20MP12	98.0	\$700	Continental	CPV080T3B	96.0	\$500
Comfort-Aire	GUH95T120D5XE	95.1	\$500	Continental	CPV080T4B	96.0	\$500
Comfortmaker	G9MAC0601714A	97.0	\$700	Continental	CPV100T5B	96.0	\$500
Comfortmaker	G9MAC0602120A	98.0	\$700	Continental	CPV120T5B	96.0	\$500
Comfortmaker	G9MAC0801714A	97.0	\$700	Continental	CPX030S2B	95.0	\$500
Comfortmaker	G9MAC0802120A	97.0	\$700	Continental	CPX040S2B	95.0	\$500
Comfortmaker	G9MAC1002122A	97.0	\$700	Continental	CPX060S3B	95.0	\$500
Comfortmaker	G9MAC1202422A	97.0	\$700	Continental	CPX080S3B	95.0	\$500
Comfortmaker	G9MAE0601714A	97.0	\$700	Continental	CPX080S4B	95.0	\$500
Comfortmaker	G9MAE0602120A	98.0	\$700	Continental	CPX100S5B	95.0	\$500
Comfortmaker	G9MAE0801714A	97.0	\$700	Continental	CPX120AS5A	95.0	\$500
Comfortmaker	G9MAE0802120A	97.0	\$700	Continental	CPX120S5A	95.0	\$500
Comfortmaker	G9MAE1002122A	97.0	\$700	Continental	CPX120S5B	95.0	\$500
Comfortmaker	G9MAE1202422A	97.0	\$700	Continental	CTV040T2B	97.0	\$700
Comfortmaker	G9MVE0401410A	96.0	\$500	Continental	CTV060T3B	97.0	\$700
Comfortmaker	G9MVE0401712A	96.0	\$500	Continental	CTV080T3B	97.0	\$700
Comfortmaker	G9MVE0601412A	95.0	\$500	Continental	CTV080T4B	97.0	\$700
Comfortmaker	G9MVE0601714A	96.0	\$500	Continental	CTV100T5B	97.0	\$700
Comfortmaker	G9MVE0801716A	96.0	\$500	Continental	CTV120T5B	97.0	\$700
Comfortmaker	G9MVE0802120A	96.0	\$500	Daikin	DC96MC0604CX	96.1	\$500
Comfortmaker	G9MVE1002116A	96.0	\$500	Daikin	DC96MC0805DX	96.1	\$500
Comfortmaker	G9MVE1002120A	96.0	\$500	Daikin	DC96MC1005DX	96.1	\$500
Comfortmaker	G9MVE1202422A	96.0	\$500	Daikin	DC96VC0403BN	96.1	\$500
Comfortmaker	G9MVT0401410A	96.0	\$500	Daikin	DC96VC0603BN	96.1	\$500
Comfortmaker	G9MVT0601714A	96.0	\$500	Daikin	DC96VC0714CX	95.0	\$500
Comfortmaker	G9MVT0801716A	96.0	\$500	Daikin	DC96VC0804CN	96.1	\$500
Comfortmaker	G9MVT0802120A	96.0	\$500	Daikin	DC96VC0915DX	95.0	\$500
Comfortmaker	G9MVT1002120A	96.0	\$500	Daikin	DC96VC1005CN	96.1	\$500
Comfortmaker	G9MVT1202422A	96.0	\$500	Daikin	DC96VC1205DN	96.1	\$500
Comfortmaker	G9MXE0401410A	96.0	\$500	Daikin	DC97MC0603BN	97.0	\$700
Comfortmaker	G9MXE0401712A*	96.0	\$500	Daikin	DC97MC0803BN	97.0	\$700
Comfortmaker	G9MXE0601412A*	95.5	\$500	Daikin	DC97MC0804CN	97.0	\$700
Comfortmaker	G9MXE0601714A	96.0	\$500	Daikin	DC97MC1005CN	97.0	\$700
Comfortmaker	G9MXE0801716A	96.0	\$500	Daikin	DM96MC0603BX	96.1	\$500
Comfortmaker	G9MXE0802120A	96.0	\$500	Daikin	DM96MC0805CX	96.1	\$500
Comfortmaker	G9MXT0401410A	96.0	\$500	Daikin	DM96MC1005DX	96.1	\$500
Comfortmaker	G9MXT0601714A	96.0	\$500	Daikin	DM96MC1155DX	96.1	\$500
Comfortmaker	G9MXT0801716A	96.0	\$500	Daikin	DM96VC0403BN	96.1	\$500
Comfortmaker	G9MXT0802120A	96.0	\$500	Daikin	DM96VC0453BX	96.1	\$500
Comfortmaker	G9MXT1002120A	96.0	\$500	Daikin	DM96VC0603BN	96.1	\$500
Comfortmaker	G9MXT1202422A	96.0	\$500	Daikin	DM96VC0704CX	96.1	\$500
Concord	95G1UH070BE12-*	95.0	\$500	Daikin	DM96VC0803BN	96.1	\$500
Concord	95G1UH090CE16-*	95.0	\$500	Daikin	DM96VC0804CN	96.1	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Daikin	DM96VC0905CX	96.1	\$500	Dettson	C120-2-V*	95.7	\$500
Daikin	DM96VC0905DX	96.1	\$500	Dettson	C120-M-V	97.0	\$700
Daikin	DM96VC1005CN	96.1	\$500	Dettson	C120-M-V*	97.0	\$700
Daikin	DM96VC1155DX	96.1	\$500	Dettson	C30-M-V	95.3	\$500
Daikin	DM96VC1205DN	96.1	\$500	Dettson	C30-M-V*	95.3	\$500
Daikin	DM96VE0302BN	96.1	\$500	Dettson	C45-2-V	95.0	\$500
Daikin	DM96VE0603BN	96.1	\$500	Dettson	C45-2-V*	95.0	\$500
Daikin	DM96VE0803BN	96.1	\$500	Dettson	C45-M-V	96.0	\$500
Daikin	DM97MC1005CN	97.0	\$700	Dettson	C45-M-V*	95.7	\$500
Daikin	DM97MC1205DN	97.0	\$700	Dettson	C60-2-V	95.0	\$500
Day & Night	G9MAC0601714A	97.0	\$700	Dettson	C60-2-V*	95.1	\$500
Day & Night	G9MAC0602120A	98.0	\$700	Dettson	C60-M-V	96.0	\$500
Day & Night	G9MAC0801714A	97.0	\$700	Dettson	C60-M-V*	96.0	\$500
Day & Night	G9MAC0802120A	97.0	\$700	Dettson	C75-2-V	95.0	\$500
Day & Night	G9MAC1002122A	97.0	\$700	Dettson	C75-2-V*	95.3	\$500
Day & Night	G9MAC1202422A	97.0	\$700	Dettson	C75-M-V	96.0	\$500
Day & Night	G9MAE0601714A	97.0	\$700	Dettson	C75-M-V*	96.0	\$500
Day & Night	G9MAE0602120A	98.0	\$700	Dettson Industries Inc.	C15-M-V	97.3	\$700
Day & Night	G9MAE0801714A	97.0	\$700	Ducane	95G1UH070BE12-*	95.0	\$500
Day & Night	G9MAE0802120A	97.0	\$700	Ducane	95G1UH090CE16-*	95.0	\$500
Day & Night	G9MAE1002122A	97.0	\$700	Ducane	95G2DF045BE12*	95.0	\$500
Day & Night	G9MAE1202422A	97.0	\$700	Ducane	95G2DF070BE16*	95.0	\$500
Day & Night	G9MVE0401410A	96.0	\$500	Ducane	95G2DF090CE16*	95.0	\$500
Day & Night	G9MVE0401712A	96.0	\$500	Ducane	95G2DF110CE20*	95.0	\$500
Day & Night	G9MVE0601412A	95.0	\$500	Ducane	95G2UH045BE12*	95.0	\$500
Day & Night	G9MVE0601714A	96.0	\$500	Ducane	95G2UH045BV12-*	95.0	\$500
Day & Night	G9MVE0801716A	96.0	\$500	Ducane	95G2UH070BE12*	95.0	\$500
Day & Night	G9MVE0802120A	96.0	\$500	Ducane	95G2UH070BV12-*	95.0	\$500
Day & Night	G9MVE1002116A	96.0	\$500	Ducane	95G2UH090CE16*	95.0	\$500
Day & Night	G9MVE1002120A	96.0	\$500	Ducane	95G2UH090CV12-*	95.0	\$500
Day & Night	G9MVE1202422A	96.0	\$500	Ducane	95G2UH090CV20-*	95.0	\$500
Day & Night	G9MVT0401410A	96.0	\$500	Ducane	95G2UH110CE20*	95.0	\$500
Day & Night	G9MVT0601714A	96.0	\$500	Ducane	95G2UH110CV20-*	95.0	\$500
Day & Night	G9MVT0801716A	96.0	\$500	Ducane	95G2UH135DE20*	95.0	\$500
Day & Night	G9MVT0802120A	96.0	\$500	Ducane	95G2UH135DV20-*	95.0	\$500
Day & Night	G9MVT1002120A	96.0	\$500	DuroGuard	D95TA0601317MSA	95.0	\$500
Day & Night	G9MVT1202422A	96.0	\$500	DuroGuard	D95TA1151524MSA	95.0	\$500
Day & Night	G9MXE0401410A	96.0	\$500	DuroGuard	D96VA0402317MSA	96.0	\$500
Day & Night	G9MXE0401712A*	96.0	\$500	DuroGuard	D96VA0602317MSA	96.0	\$500
Day & Night	G9MXE0601412A*	95.5	\$500	DuroGuard	D96VA0702317MSA	96.0	\$500
Day & Night	G9MXE0601714A	96.0	\$500	DuroGuard	D96VA0852521MSA	96.0	\$500
Day & Night	G9MXE0801716A	96.0	\$500	DuroGuard	D96VA1002521MSA	96.0	\$500
Day & Night	G9MXE0802120A	96.0	\$500	Elect-Aire	KG7TC120*-D*	95.1	\$500
Day & Night	G9MXT0401410A	96.0	\$500	Evcon	RGF19060BE12MP12	95.0	\$500
Day & Night	G9MXT0601714A	96.0	\$500	Evcon	RGF19080BE12MP12	95.0	\$500
Day & Night	G9MXT0801716A	96.0	\$500	Evcon	RGF19080CE16MP12	95.0	\$500
Day & Night	G9MXT0802120A	96.0	\$500	Evcon	RGF19100CE16MP12	95.0	\$500
Day & Night	G9MXT1002120A	96.0	\$500	Evcon	RGF19100CE20MP12	95.0	\$500
Day & Night	G9MXT1202422A	96.0	\$500	Evcon	RGF19120DE20MP12	95.0	\$500
Dettson	60-M-V*	96.0	\$500	Evcon	TP9C060B12MP12CA	97.5	\$700
Dettson	75-M-V*	95.7	\$500	Evcon	TP9C080B12MP12CA	97.5	\$700
Dettson	C030-M-V*	95.3	\$500	Evcon	TP9C080C16MP12CA	97.7	\$700
Dettson	C045-2-V	95.1	\$500	Evcon	TP9C100C16MP12CA	97.7	\$700
Dettson	C060-2-V	95.1	\$500	Evcon	TP9C100C20MP12CA	97.7	\$700
Dettson	C075-2-V	96.3	\$500	Evcon	TP9C120D20MP12	98.0	\$700
Dettson	C105-2-V	95.0	\$500	Evcon	TP9C120D20MP12CA	98.0	\$700
Dettson	C105-2-V*	95.0	\$500	Fraser - Johnston	TP9C060B12MP12CA	97.5	\$700
Dettson	C105-M-V	96.0	\$500	Fraser - Johnston	TP9C080B12MP12CA	97.5	\$700
Dettson	C105-M-V*	96.0	\$500	Fraser - Johnston	TP9C080C16MP12CA	97.7	\$700
Dettson	C120-2-V	96.0	\$500	Fraser - Johnston	TP9C100C16MP12CA	97.7	\$700



Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Fraser - Johnston	TP9C100C20MP12CA	97.7	\$700	Goodman	DM96VE1004CN	96.0	\$500
Fraser - Johnston	TP9C120D20MP12	98.0	\$700	Goodman	DM96VE1005CN	96.0	\$500
Fraser - Johnston	TP9C120D20MP12CA	98.0	\$700	Goodman	DM96VE1205DN	96.0	\$500
Frigidaire	FG7MQ060*-VB	97.0	\$700	Goodman	DM97MC0603BN	98.0	\$700
Frigidaire	FG7MQ080*-VC	97.2	\$700	Goodman	DM97MC0803BN	97.0	\$700
Frigidaire	FG7MQ100*-VC	97.4	\$700	Goodman	DM97MC0804CN	98.0	\$700
Frigidaire	FG7MQ120*-VD	97.0	\$700	Goodman	DM97MC1005CN	97.0	\$700
Frigidaire	FG7TC120*-D*	95.1	\$500	Goodman	DM97MC1205DN	97.0	\$700
Frigidaire	KG7TC120*-D*	95.1	\$500	Goodman	GCVC950714CX**	95.0	\$500
Garrison	KG7TC120*-D*	95.1	\$500	Goodman	GCVC950915DX**	95.0	\$500
Gibson	KG7TC120*-D*	95.1	\$500	Goodman	GCVC960403BN	96.0	\$500
Goodman	ACVC960403BN	96.0	\$500	Goodman	GCVC960603BN	96.0	\$500
Goodman	ACVC960603BN	96.0	\$500	Goodman	GCVC960804CN	96.0	\$500
Goodman	ACVC960804CN	96.0	\$500	Goodman	GCVC961005CN	96.0	\$500
Goodman	ACVC961005CN	96.0	\$500	Goodman	GCVC961205DN	96.0	\$500
Goodman	ACVC961205DN	96.0	\$500	Goodman	GCVM960604CX	96.1	\$500
Goodman	ACVM970603BN	97.0	\$700	Goodman	GCVM960805DX	96.1	\$500
Goodman	ACVM970803BN	97.0	\$700	Goodman	GCVM961005DX	96.1	\$500
Goodman	ACVM970804CN	97.0	\$700	Goodman	GCVM970603BN	97.0	\$700
Goodman	ACVM971005CN	97.0	\$700	Goodman	GCVM970803BN	97.0	\$700
Goodman	AMEC960302BN	96.0	\$500	Goodman	GCVM970804CN	97.0	\$700
Goodman	AMEC960402BN	96.0	\$500	Goodman	GCVM971005CN	97.0	\$700
Goodman	AMEC960603BN	96.0	\$500	Goodman	GMEC960302BN	96.0	\$500
Goodman	AMEC960803BN	96.0	\$500	Goodman	GMEC960402BN	96.0	\$500
Goodman	AMEC960804CN	96.0	\$500	Goodman	GMEC960603BN	96.0	\$500
Goodman	AMEC961004CN	96.0	\$500	Goodman	GMEC960803BN	96.0	\$500
Goodman	AMEC961005CN	96.0	\$500	Goodman	GMEC960804CN	96.0	\$500
Goodman	AMEC961205DN	96.0	\$500	Goodman	GMEC961004CN	96.0	\$500
Goodman	AMVC960403BN	96.0	\$500	Goodman	GMEC961005CN	96.0	\$500
Goodman	AMVC960603BN	96.0	\$500	Goodman	GMEC961205DN	96.0	\$500
Goodman	AMVC960803BN	96.0	\$500	Goodman	GMVC950453BX*	96.1	\$500
Goodman	AMVC960804CN	96.0	\$500	Goodman	GMVC950704CX*	96.1	\$500
Goodman	AMVC961005CN	96.0	\$500	Goodman	GMVC950905DX*	96.1	\$500
Goodman	AMVC961205DN	96.0	\$500	Goodman	GMVC951155DX*	96.1	\$500
Goodman	AMVM970603BN	98.0	\$700	Goodman	GMVC960403BN	96.0	\$500
Goodman	AMVM970803BN	97.0	\$700	Goodman	GMVC960603BN	96.0	\$500
Goodman	AMVM970804CN	98.0	\$700	Goodman	GMVC960803BN	96.0	\$500
Goodman	AMVM971005CN	97.0	\$700	Goodman	GMVC960804CN	96.0	\$500
Goodman	AMVM971205DN	97.0	\$700	Goodman	GMVC961005CN	96.0	\$500
Goodman	DC96VC0403BN	96.0	\$500	Goodman	GMVC961005DN	96.0	\$500
Goodman	DC96VC0603BN	96.0	\$500	Goodman	GMVC961205DN	96.0	\$500
Goodman	DC96VC0804CN	96.0	\$500	Goodman	GMVM960603BX	96.1	\$500
Goodman	DC96VC1005CN	96.0	\$500	Goodman	GMVM960805CX	96.1	\$500
Goodman	DC96VC1205DN	96.0	\$500	Goodman	GMVM961005DX	96.1	\$500
Goodman	DC97MC0603BN	97.0	\$700	Goodman	GMVM961155DX	96.1	\$500
Goodman	DC97MC0803BN	97.0	\$700	Goodman	GMVM970603BN	98.0	\$700
Goodman	DC97MC0804CN	97.0	\$700	Goodman	GMVM970803BN	97.0	\$700
Goodman	DC97MC1005CN	97.0	\$700	Goodman	GMVM970804CN	98.0	\$700
Goodman	DM96VC0403BN	96.0	\$500	Goodman	GMVM971005CN	97.0	\$700
Goodman	DM96VC0603BN	96.0	\$500	Goodman	GMVM971205DN	97.0	\$700
Goodman	DM96VC0803BN	96.0	\$500	Goodman Manufacturing Company L.P.	ACEC960403BN	96.1	\$500
Goodman	DM96VC0804CN	96.0	\$500	Goodman Manufacturing Company L.P.	ACEC960603BN	96.1	\$500
Goodman	DM96VC1005CN	96.0	\$500	Goodman Manufacturing Company L.P.	ACEC960803BN	96.1	\$500
Goodman	DM96VC1005DN	96.0	\$500	Goodman Manufacturing Company L.P.	ACEC961005CN	96.1	\$500
Goodman	DM96VE0302BN	96.0	\$500	Goodman Manufacturing Company L.P.	AMEC960303AN	96.1	\$500
Goodman	DM96VE0402BN	96.0	\$500	Goodman Manufacturing Company L.P.	AMEC960403AN	96.1	\$500
Goodman	DM96VE0603BN	96.0	\$500	Goodman Manufacturing Company L.P.	AMEC960603AN	96.1	\$500
Goodman	DM96VE0803BN	96.0	\$500	Goodman Manufacturing Company L.P.	AMEC960803AN	96.1	\$500
Goodman	DM96VE0804CN	96.0	\$500	Goodman Manufacturing Company L.P.	AMEC960903AN	96.1	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Company L.P.				Goodman Manufacturing Company, L.P.	AMVM971005CN	97.0	\$700
Goodman Manufacturing Company L.P.	DC96VE0403BN	96.1	\$500	Goodman Manufacturing Company, L.P.	AMVM971205DN	97.0	\$700
Goodman Manufacturing Company L.P.	DC96VE0603BN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC96VC0403BN	96.0	\$500
Goodman Manufacturing Company L.P.	DC96VE0803BN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC96VC0603BN	96.0	\$500
Goodman Manufacturing Company L.P.	DC96VE1005CN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC96VC0804CN	96.0	\$500
Goodman Manufacturing Company L.P.	DM96VE0603AN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC96VC1005CN	96.0	\$500
Goodman Manufacturing Company L.P.	GCEC960403BN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC96VC1205DN	96.0	\$500
Goodman Manufacturing Company L.P.	GCEC960603BN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC97MC0603BN	97.0	\$700
Goodman Manufacturing Company L.P.	GCEC960803BN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC97MC0803BN	97.0	\$700
Goodman Manufacturing Company L.P.	GCEC961005CN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC97MC0804CN	97.0	\$700
Goodman Manufacturing Company L.P.	GMEC960303AN	96.1	\$500	Goodman Manufacturing Company, L.P.	DC97MC1005CN	97.0	\$700
Goodman Manufacturing Company L.P.	GMEC960403AN	96.1	\$500	Goodman Manufacturing Company, L.P.	DM96VE0603BN	96.0	\$500
Goodman Manufacturing Company L.P.	GMEC960603AN	96.1	\$500	Grandaire	KG7TC120*-D*	95.1	\$500
Goodman Manufacturing Company, L.P.	ACVC960403BN	96.0	\$500	Great Lakes	95G1UH070BE12-*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVC960603BN	96.0	\$500	Great Lakes	95G1UH090CE16-*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVC960804CN	96.0	\$500	Great Lakes	95G2DF045BE12*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVC961005CN	96.0	\$500	Great Lakes	95G2DF070BE16*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVC961205DN	96.0	\$500	Great Lakes	95G2DF090CE16*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVM970603BN	97.0	\$700	Great Lakes	95G2DF110CE20*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVM970803BN	97.0	\$700	Great Lakes	95G2UH045BE12*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVM970804CN	97.0	\$700	Great Lakes	95G2UH045BV12-*	95.0	\$500
Goodman Manufacturing Company, L.P.	ACVM971005CN	97.0	\$700	Great Lakes	95G2UH070BE12*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC960302BN	96.0	\$500	Great Lakes	95G2UH070BV12-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC960402BN	96.0	\$500	Great Lakes	95G2UH090CE16*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC960603BN	96.0	\$500	Great Lakes	95G2UH090CV12-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC960803BN	96.0	\$500	Great Lakes	95G2UH090CV20-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC960804CN	96.0	\$500	Great Lakes	95G2UH110CE20*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC961004CN	96.0	\$500	Great Lakes	95G2UH110CV20-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC961005CN	96.0	\$500	Great Lakes	95G2UH135DE20*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMEC961205DN	96.0	\$500	Great Lakes	95G2UH135DV20-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960403BN	96.0	\$500	Great Lakes	A95DF2V045B12*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960603BN	96.0	\$500	Great Lakes	A95DF2V070B16*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960803BN	96.0	\$500	Great Lakes	A95DF2V090C20*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960804CN	96.0	\$500	Great Lakes	A95DF2V110C20*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961005CN	96.0	\$500	Great Lakes	A95UH1E070B12-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961005DN	96.0	\$500	Great Lakes	A95UH1E090C16-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961205DN	96.0	\$500	Great Lakes	A95UH2E045B12*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960403BN	96.0	\$500	Great Lakes	A95UH2V045B12*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960603BN	96.0	\$500	Great Lakes	A95UH2V070B12*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960803BN	96.0	\$500	Great Lakes	A95UH2V090C12*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC960804CN	96.0	\$500	Great Lakes	A95UH2V090C16*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961005CN	96.0	\$500	Great Lakes	A95UH2V090C20*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961005DN	96.0	\$500	Great Lakes	A95UH2V110C16*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961205DN	96.0	\$500	Great Lakes	A95UH2V110C20*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVC961205DN	96.0	\$500	Great Lakes	A95UH2V135D20*-*	95.0	\$500
Goodman Manufacturing Company, L.P.	AMVM970603BN	98.0	\$700	Great Lakes	A97DSMV070B12S-*	97.0	\$700
Goodman Manufacturing Company, L.P.	AMVM970803BN	97.0	\$700	Great Lakes	A97DSMV090C16S-*	97.0	\$700
Goodman Manufacturing Company, L.P.	AMVM970804CN	98.0	\$700	Great Lakes	A97DSMV090C20S-*	97.0	\$700
				Great Lakes	A97DSMV110C20S-*	97.0	\$700
				Great Lakes	A97USMV070B12S-*	97.0	\$700
				Great Lakes	A97USMV090C12S-*	97.0	\$700
				Great Lakes	A97USMV090C16S-*	97.0	\$700
				Great Lakes	A97USMV090C20S-*	97.0	\$700
				Great Lakes	A97USMV110C20S-*	97.0	\$700

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Great Lakes	A97USMV135D20S-*	97.0	\$700	Heil	G9MXE0801716A	96.0	\$500
Guardian	RGF19060BE12MP12	95.0	\$500	Heil	G9MXE0802120A	96.0	\$500
Guardian	RGF19080BE12MP12	95.0	\$500	Heil	G9MXT0401410A	96.0	\$500
Guardian	RGF19080CE16MP12	95.0	\$500	Heil	G9MXT0601714A	96.0	\$500
Guardian	RGF19100CE16MP12	95.0	\$500	Heil	G9MXT0801716A	96.0	\$500
Guardian	RGF19100CE20MP12	95.0	\$500	Heil	G9MXT0802120A	96.0	\$500
Guardian	RGF19120DE20MP12	95.0	\$500	Heil	G9MXT1002120A	96.0	\$500
Heat Controller Inc.	GDD95C045B3*	95.0	\$500	Heil	G9MXT1202422A	96.0	\$500
Heat Controller Inc.	GDD95C070B4*	95.0	\$500	ICP Commercial	F9MAC0601714A	97.0	\$700
Heat Controller Inc.	GDD95C090C4*	95.0	\$500	ICP Commercial	F9MAC0801714A	97.0	\$700
Heat Controller Inc.	GDD95C110C5*	95.0	\$500	ICP Commercial	F9MAC1202422A	97.0	\$700
Heat Controller Inc.	GDD95T070B4*	96.0	\$500	ICP Commercial	F9MAE0601714A	97.0	\$700
Heat Controller Inc.	GDD95T090C5*	96.0	\$500	ICP Commercial	F9MAE0801714A	97.0	\$700
Heat Controller Inc.	GDD95T110C5*	96.0	\$500	ICP Commercial	F9MAE1202422A	97.0	\$700
Heat Controller Inc.	GUH95C045B3*	95.0	\$500	ICP Commercial	F9MVE0401410A	96.0	\$500
Heat Controller Inc.	GUH95C070B3*	95.0	\$500	ICP Commercial	F9MVE0401712A	96.0	\$500
Heat Controller Inc.	GUH95C090C4*	95.0	\$500	ICP Commercial	F9MVE0601412A	95.0	\$500
Heat Controller Inc.	GUH95C110C5*	95.0	\$500	ICP Commercial	F9MVE0601714A	96.0	\$500
Heat Controller Inc.	GUH95C135D5*	95.0	\$500	ICP Commercial	F9MVE0801716A	96.0	\$500
Heat Controller Inc.	GUH95T045B3*	96.0	\$500	ICP Commercial	F9MVE1202422A	96.0	\$500
Heat Controller Inc.	GUH95T060B4XE	96.0	\$500	ICP Commercial	F9MVT0401410A	96.0	\$500
Heat Controller Inc.	GUH95T070B3*	96.0	\$500	ICP Commercial	F9MVT0601714A	96.0	\$500
Heat Controller Inc.	GUH95T080C5XE	96.0	\$500	ICP Commercial	F9MVT0801716A	96.0	\$500
Heat Controller Inc.	GUH95T090C3*	96.0	\$500	ICP Commercial	F9MVT1202422A	96.0	\$500
Heat Controller Inc.	GUH95T090C5*	96.0	\$500	ICP Commercial	F9MXE0401410A*	96.0	\$500
Heat Controller Inc.	GUH95T100C5XE	96.0	\$500	ICP Commercial	F9MXE0401712A	96.0	\$500
Heat Controller Inc.	GUH95T110C5*	96.0	\$500	ICP Commercial	F9MXE0601412A	95.5	\$500
Heat Controller Inc.	GUH95T120D5XE	96.0	\$500	ICP Commercial	F9MXE0601714A*	96.0	\$500
Heat Controller Inc.	GUH95T135D5*	96.0	\$500	ICP Commercial	F9MXE0801716A*	96.0	\$500
Heil	G9MAC0601714A	97.0	\$700	ICP Commercial	F9MXT0401410A	96.0	\$500
Heil	G9MAC0602120A	98.0	\$700	ICP Commercial	F9MXT0401712A	96.0	\$500
Heil	G9MAC0801714A	97.0	\$700	ICP Commercial	F9MXT0601412A	95.0	\$500
Heil	G9MAC0802120A	97.0	\$700	ICP Commercial	F9MXT0601714A	96.0	\$500
Heil	G9MAC1002122A	97.0	\$700	ICP Commercial	F9MXT0801716A	96.0	\$500
Heil	G9MAC1202422A	97.0	\$700	ICP Commercial	F9MXT1202422A	96.0	\$500
Heil	G9MAE0601714A	97.0	\$700	ICP Commercial	G9MAC0601714A	97.0	\$700
Heil	G9MAE0602120A	98.0	\$700	ICP Commercial	G9MAC0801714A	97.0	\$700
Heil	G9MAE0801714A	97.0	\$700	ICP Commercial	G9MAC1202422A	97.0	\$700
Heil	G9MAE0802120A	97.0	\$700	ICP Commercial	G9MAE0601714A	97.0	\$700
Heil	G9MAE1002122A	97.0	\$700	ICP Commercial	G9MAE0801714A	97.0	\$700
Heil	G9MAE1202422A	97.0	\$700	ICP Commercial	G9MAE1202422A	97.0	\$700
Heil	G9MVE0401410A	96.0	\$500	ICP Commercial	G9MVE0401410A	96.0	\$500
Heil	G9MVE0401712A	96.0	\$500	ICP Commercial	G9MVE0601714A	96.0	\$500
Heil	G9MVE0601412A	95.0	\$500	ICP Commercial	G9MVE0801716A	96.0	\$500
Heil	G9MVE0601714A	96.0	\$500	ICP Commercial	G9MVE1002116A	96.0	\$500
Heil	G9MVE0801716A	96.0	\$500	ICP Commercial	G9MVE1202422A	96.0	\$500
Heil	G9MVE0802120A	96.0	\$500	ICP Commercial	G9MVT0401410A	96.0	\$500
Heil	G9MVE1002116A	96.0	\$500	ICP Commercial	G9MVT0601714A	96.0	\$500
Heil	G9MVE1002120A	96.0	\$500	ICP Commercial	G9MVT0801716A	96.0	\$500
Heil	G9MVE1202422A	96.0	\$500	ICP Commercial	G9MVT1202422A	96.0	\$500
Heil	G9MVT0401410A	96.0	\$500	ICP Commercial	G9MXE0401410A	96.0	\$500
Heil	G9MVT0601714A	96.0	\$500	ICP Commercial	G9MXE0601714A	96.0	\$500
Heil	G9MVT0801716A	96.0	\$500	ICP Commercial	G9MXE0801716A	96.0	\$500
Heil	G9MVT0802120A	96.0	\$500	ICP Commercial	G9MXE0802120A	96.0	\$500
Heil	G9MVT1002120A	96.0	\$500	ICP Commercial	G9MXT0401410A	96.0	\$500
Heil	G9MVT1202422A	96.0	\$500	ICP Commercial	G9MXT0601714A	96.0	\$500
Heil	G9MXE0401410A	96.0	\$500	ICP Commercial	G9MXT0801716A	96.0	\$500
Heil	G9MXE0401712A*	96.0	\$500	ICP Commercial	G9MXT1202422A	96.0	\$500
Heil	G9MXE0601412A*	95.5	\$500	International Comfort Products (ICP)	926TA30040V14A	97.0	\$700
Heil	G9MXE0601714A	96.0	\$500				



Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
International Comfort Products (ICP)	G9MVE0401712A	96.0	\$500	International Comfort Products (ICP)	G9MXT0801716A	96.0	\$500
International Comfort Products (ICP)	G9MVE0401712A*D	95.0	\$500	International Comfort Products (ICP)	G9MXT0801716A*D	95.0	\$500
International Comfort Products (ICP)	G9MVE0601412A	95.0	\$500	International Comfort Products (ICP)	G9MXT0802120A	96.0	\$500
International Comfort Products (ICP)	G9MVE0601412A*D	95.0	\$500	International Comfort Products (ICP)	G9MXT0802120A*D	95.0	\$500
International Comfort Products (ICP)	G9MVE0601714A	96.0	\$500	International Comfort Products (ICP)	G9MXT1002120A	96.0	\$500
International Comfort Products (ICP)	G9MVE0601714A*D	95.0	\$500	International Comfort Products (ICP)	G9MXT1002120A*D	95.0	\$500
International Comfort Products (ICP)	G9MVE0801716A	96.0	\$500	International Comfort Products (ICP)	G9MXT1202422A	96.0	\$500
International Comfort Products (ICP)	G9MVE0801716A*D	95.0	\$500	International Comfort Products (ICP)	G9MXT1202422A*D	95.0	\$500
International Comfort Products (ICP)	G9MVE0802120A	96.0	\$500	International Comfort Products (ICP)	PG96VAT30040A	96.0	\$500
International Comfort Products (ICP)	G9MVE0802120A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT30040A*D	95.0	\$500
International Comfort Products (ICP)	G9MVE1002120A	96.0	\$500	International Comfort Products (ICP)	PG96VAT42060B	96.0	\$500
International Comfort Products (ICP)	G9MVE1002120A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT42060B*D	95.0	\$500
International Comfort Products (ICP)	G9MVE1202422A	96.0	\$500	International Comfort Products (ICP)	PG96VAT48080B	96.0	\$500
International Comfort Products (ICP)	G9MVE1202422A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT48080B*D	95.0	\$500
International Comfort Products (ICP)	G9MXE0261410A	96.0	\$500	International Comfort Products (ICP)	PG96VAT60080C	96.0	\$500
International Comfort Products (ICP)	G9MXE0261410A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT60080C*D	95.0	\$500
International Comfort Products (ICP)	G9MXE0401410A	96.0	\$500	International Comfort Products (ICP)	PG96VAT60100C	96.0	\$500
International Comfort Products (ICP)	G9MXE0401410A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT60100C*D	95.0	\$500
International Comfort Products (ICP)	G9MXE0401712A	96.0	\$500	International Comfort Products (ICP)	PG96VAT66120D	96.0	\$500
International Comfort Products (ICP)	G9MXE0401712A*D	95.0	\$500	International Comfort Products (ICP)	PG96VAT66120D*D	95.0	\$500
International Comfort Products (ICP)	G9MXE0601412A	95.5	\$500	Interttherm	FG7TC120*-D*	95.1	\$500
International Comfort Products (ICP)	G9MXE0601412A*D	95.0	\$500	Keeprite	G9MAC0601714A	97.0	\$700
International Comfort Products (ICP)	G9MXE0601714A	96.0	\$500	Keeprite	G9MAC0602120A	98.0	\$700
International Comfort Products (ICP)	G9MXE0601714A*D	95.0	\$500	Keeprite	G9MAC0801714A	97.0	\$700
International Comfort Products (ICP)	G9MXE0601714A*D	95.0	\$500	Keeprite	G9MAC0802120A	97.0	\$700
International Comfort Products (ICP)	G9MXE0801716A	96.0	\$500	Keeprite	G9MAC1002122A	97.0	\$700
International Comfort Products (ICP)	G9MXE0801716A*D	95.0	\$500	Keeprite	G9MAC1202422A	97.0	\$700
International Comfort Products (ICP)	G9MXE0802120A	96.0	\$500	Keeprite	G9MAE0601714A	97.0	\$700
International Comfort Products (ICP)	G9MXE0802120A*D	95.0	\$500	Keeprite	G9MAE0602120A	98.0	\$700
International Comfort Products (ICP)	G9MXE0802120A	96.0	\$500	Keeprite	G9MAE0801714A	97.0	\$700
International Comfort Products (ICP)	G9MXE0802120A*D	95.0	\$500	Keeprite	G9MAE0802120A	97.0	\$700
International Comfort Products (ICP)	G9MXE1002120A	96.0	\$500	Keeprite	G9MAE1002122A	97.0	\$700
International Comfort Products (ICP)	G9MXE1002120A*D	95.0	\$500	Keeprite	G9MAE1202422A	97.0	\$700
International Comfort Products (ICP)	G9MXE1202422A	96.0	\$500	Keeprite	G9MVE0401410A	96.0	\$500
International Comfort Products (ICP)	G9MXE1202422A*D	95.0	\$500	Keeprite	G9MVE0401712A	96.0	\$500
International Comfort Products (ICP)	G9MXT0401410A	96.0	\$500	Keeprite	G9MVE0601412A	95.0	\$500
International Comfort Products (ICP)	G9MXT0401410A*D	95.0	\$500	Keeprite	G9MVE0601714A	96.0	\$500
International Comfort Products (ICP)	G9MXT0401712A*	96.0	\$500	Keeprite	G9MVE0801716A	96.0	\$500
International Comfort Products (ICP)	G9MXT0401712A*D	95.0	\$500	Keeprite	G9MVE0802120A	96.0	\$500
International Comfort Products (ICP)	G9MXT0601412A*	95.0	\$500	Keeprite	G9MVE1002116A	96.0	\$500
International Comfort Products (ICP)	G9MXT0601412A*D	95.0	\$500	Keeprite	G9MVE1002120A	96.0	\$500
International Comfort Products (ICP)	G9MXT0601714A	96.0	\$500	Keeprite	G9MVE1202422A	96.0	\$500
International Comfort Products (ICP)	G9MXT0601714A*D	95.0	\$500	Keeprite	G9MVT0401410A	96.0	\$500
				Keeprite	G9MVT0601714A	96.0	\$500
				Keeprite	G9MVT0801716A	96.0	\$500
				Keeprite	G9MVT0802120A	96.0	\$500
				Keeprite	G9MVT1002120A	96.0	\$500
				Keeprite	G9MVT1202422A	96.0	\$500
				Keeprite	G9MXE0401410A	96.0	\$500
				Keeprite	G9MXE0401712A*	96.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Keeprite	G9MXE0601412A*	95.5	\$500	Kenmore	G9MVE0401410A	96.0	\$500
Keeprite	G9MXE0601714A	96.0	\$500	Kenmore	G9MVE0401712A	96.0	\$500
Keeprite	G9MXE0801716A	96.0	\$500	Kenmore	G9MVE0601412A	95.0	\$500
Keeprite	G9MXE0802120A	96.0	\$500	Kenmore	G9MVE0601714A	96.0	\$500
Keeprite	G9MXT0401410A	96.0	\$500	Kenmore	G9MVE0801716A	96.0	\$500
Keeprite	G9MXT0601714A	96.0	\$500	Kenmore	G9MVE0802120A	96.0	\$500
Keeprite	G9MXT0801716A	96.0	\$500	Kenmore	G9MVE1002116A	96.0	\$500
Keeprite	G9MXT0802120A	96.0	\$500	Kenmore	G9MVE1002120A	96.0	\$500
Keeprite	G9MXT1002120A	96.0	\$500	Kenmore	G9MVE1202422A	96.0	\$500
Keeprite	G9MXT1202422A	96.0	\$500	Kenmore	G9MVT0401410A	96.0	\$500
Kelvinator	KG7TC120*-D*	95.1	\$500	Kenmore	G9MVT0601714A	96.0	\$500
Kenmore	F9MAC0601714A	97.0	\$700	Kenmore	G9MVT0801716A	96.0	\$500
Kenmore	F9MAC0602120A	98.0	\$700	Kenmore	G9MVT0802120A	96.0	\$500
Kenmore	F9MAC0801714A	97.0	\$700	Kenmore	G9MVT1002120A	96.0	\$500
Kenmore	F9MAC0802120A	97.0	\$700	Kenmore	G9MVT1202422A	96.0	\$500
Kenmore	F9MAC1002122A	97.0	\$700	Kenmore	G9MXE0401410A	96.0	\$500
Kenmore	F9MAC1202422A	97.0	\$700	Kenmore	G9MXE0401712A*	96.0	\$500
Kenmore	F9MAE0601714A	97.0	\$700	Kenmore	G9MXE0601412A*	95.5	\$500
Kenmore	F9MAE0602120A	98.0	\$700	Kenmore	G9MXE0601714A	96.0	\$500
Kenmore	F9MAE0801714A	97.0	\$700	Kenmore	G9MXE0801716A	96.0	\$500
Kenmore	F9MAE0802120A	97.0	\$700	Kenmore	G9MXE0802120A	96.0	\$500
Kenmore	F9MAE1002122A	97.0	\$700	Kenmore	G9MXT0401410A	96.0	\$500
Kenmore	F9MAE1202422A	97.0	\$700	Kenmore	G9MXT0601714A	96.0	\$500
Kenmore	F9MVE0401410A	96.0	\$500	Kenmore	G9MXT0801716A	96.0	\$500
Kenmore	F9MVE0401712A	96.0	\$500	Kenmore	G9MXT0802120A	96.0	\$500
Kenmore	F9MVE0601412A	95.0	\$500	Kenmore	G9MXT1002120A	96.0	\$500
Kenmore	F9MVE0601714A	96.0	\$500	Kenmore	G9MXT1202422A	96.0	\$500
Kenmore	F9MVE0801716A	96.0	\$500	Lennox	95G2DF045BV12-*	95.0	\$500
Kenmore	F9MVE0802120A	96.0	\$500	Lennox	95G2DF070BV16-*	95.0	\$500
Kenmore	F9MVE1002120A	96.0	\$500	Lennox	95G2DF090CV20-*	95.0	\$500
Kenmore	F9MVE1202422A	96.0	\$500	Lennox	95G2DF110CV20-*	95.0	\$500
Kenmore	F9MVT0401410A	96.0	\$500	Lennox	EL195UH030XE24B*	95.0	\$500
Kenmore	F9MVT0601714A	96.0	\$500	Lennox	EL195UH045XE24B*	95.0	\$500
Kenmore	F9MVT0801716A	96.0	\$500	Lennox	EL195UH045XE36B	95.0	\$500
Kenmore	F9MVT0802120A	96.0	\$500	Lennox	EL195UH045XE36B-*	95.0	\$500
Kenmore	F9MVT1002120A	96.0	\$500	Lennox	EL195UH070XE36B-*	95.0	\$500
Kenmore	F9MVT1202422A	96.0	\$500	Lennox	EL195UH090XE48C-*	95.0	\$500
Kenmore	F9MXE0401712A	96.0	\$500	Lennox	EL195UH110XE60C-*	95.0	\$500
Kenmore	F9MXE0601412A	95.5	\$500	Lennox	EL195UH110XE60C-06	95.0	\$500
Kenmore	F9MXE1002120A*	96.0	\$500	Lennox	EL195UH135XE60D-*	95.0	\$500
Kenmore	F9MXT0401410A	96.0	\$500	Lennox	EL296DF045XE36B-*	96.0	\$500
Kenmore	F9MXT0401712A	96.0	\$500	Lennox	EL296DF045XV36B-*	96.0	\$500
Kenmore	F9MXT0601412A	95.0	\$500	Lennox	EL296DF070XE48B-*	96.0	\$500
Kenmore	F9MXT0601714A	96.0	\$500	Lennox	EL296DF070XV48B-*	96.0	\$500
Kenmore	F9MXT0801716A	96.0	\$500	Lennox	EL296DF090XE48C-*	96.0	\$500
Kenmore	F9MXT0802120A	96.0	\$500	Lennox	EL296DF090XV60C-*	96.0	\$500
Kenmore	F9MXT1002120A	96.0	\$500	Lennox	EL296DF110XE60C-*	96.0	\$500
Kenmore	F9MXT1202422A	96.0	\$500	Lennox	EL296DF110XV60C-*	96.0	\$500
Kenmore	G9MAC0601714A	97.0	\$700	Lennox	EL296UH045XE36B-*	96.0	\$500
Kenmore	G9MAC0602120A	98.0	\$700	Lennox	EL296UH045XV36B-*	96.0	\$500
Kenmore	G9MAC0801714A	97.0	\$700	Lennox	EL296UH070XE36B-*	96.0	\$500
Kenmore	G9MAC0802120A	97.0	\$700	Lennox	EL296UH070XV36B-*	96.0	\$500
Kenmore	G9MAC1002122A	97.0	\$700	Lennox	EL296UH090XE48C-*	96.0	\$500
Kenmore	G9MAC1202422A	97.0	\$700	Lennox	EL296UH090XV36C-*	96.0	\$500
Kenmore	G9MAE0601714A	97.0	\$700	Lennox	EL296UH090XV48C-*	96.0	\$500
Kenmore	G9MAE0602120A	98.0	\$700	Lennox	EL296UH090XV60C-*	96.0	\$500
Kenmore	G9MAE0801714A	97.0	\$700	Lennox	EL296UH110XE60C-*	96.0	\$500
Kenmore	G9MAE0802120A	97.0	\$700	Lennox	EL296UH110XV48C-*	96.0	\$500
Kenmore	G9MAE1002122A	97.0	\$700	Lennox	EL296UH110XV60C-*	96.0	\$500
Kenmore	G9MAE1202422A	97.0	\$700	Lennox	EL296UH135XE60D-*	96.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Lennox	EL296UH135XV60D-*	96.0	\$500	Lennox Industries	SL297UH060NV36B-*	97.5	\$700
Lennox	SLP98DF070XV36B-*	97.5	\$700	Lennox Industries	SL297UH080NV48C-*	97.5	\$700
Lennox	SLP98DF090XV36C-*	98.0	\$700	Lennox Industries	SL297UH080NV60C-*	97.5	\$700
Lennox	SLP98DF090XV36C-*	97.5	\$700	Luxaire	LP9C060B12MP12	97.5	\$700
Lennox	SLP98DF090XV48C-*	98.0	\$700	Luxaire	LP9C060B12MP12CA	97.5	\$700
Lennox	SLP98DF090XV48C-*	97.5	\$700	Luxaire	LP9C080B12MP12	97.5	\$700
Lennox	SLP98DF090XV60C-*	98.0	\$700	Luxaire	LP9C080B12MP12CA	97.5	\$700
Lennox	SLP98DF090XV60C-*	97.5	\$700	Luxaire	LP9C080C16MP12	97.7	\$700
Lennox	SLP98DF110XV60C-*	98.0	\$700	Luxaire	LP9C080C16MP12CA	97.7	\$700
Lennox	SLP98DF110XV60C-*	98.2	\$700	Luxaire	LP9C100C16MP12	97.7	\$700
Lennox	SLP98UH070XV36B-*	98.0	\$700	Luxaire	LP9C100C16MP12CA	97.7	\$700
Lennox	SLP98UH070XV36B-*	97.4	\$700	Luxaire	LP9C100C20MP12	97.7	\$700
Lennox	SLP98UH090XV36C-*	98.0	\$700	Luxaire	LP9C100C20MP12CA	97.7	\$700
Lennox	SLP98UH090XV36C-*	98.0	\$700	Luxaire	LP9C120D20MP12	98.0	\$700
Lennox	SLP98UH090XV48C-*	98.0	\$700	Luxaire	LP9C120D20MP12CA	98.0	\$700
Lennox	SLP98UH090XV48C-*	97.5	\$700	Luxaire	TP9C120D20MP12	98.0	\$700
Lennox	SLP98UH090XV60C-*	99.0	\$700	Maytag	MGC2TC120D-*D*	95.1	\$500
Lennox	SLP98UH090XV60C-*	98.2	\$700	Maytag	PGC2MQ060*-VB	97.0	\$700
Lennox	SLP98UH110XV60C-*	98.0	\$700	Maytag	PGC2MQ080*-VC	97.2	\$700
Lennox	SLP98UH110XV60C-*	97.5	\$700	Maytag	PGC2MQ100*-VC	97.4	\$700
Lennox	SLP98UH135XV60D-*	98.0	\$700	Maytag	PGC2MQ120*-VD	97.0	\$700
Lennox	SLP98UH135XV60D-*	97.5	\$700	Maytag	PGC2TC120*-D*	95.1	\$500
Lennox Elite 90	EL195UH070XE36B-*	95.0	\$500	Miller	FG7TC120*-D*	95.1	\$500
Lennox Elite 90	EL195UH090XE48C-*	95.0	\$500	Napoleon	NPV040T2B	96.0	\$500
Lennox Elite 90	EL296DF045XE36B-*	96.0	\$500	Napoleon	NPV060T3B	96.0	\$500
Lennox Elite 90	EL296DF045XV36B-*	96.0	\$500	Napoleon	NPV080T3B	96.0	\$500
Lennox Elite 90	EL296DF070XE48B-*	95.9	\$500	Napoleon	NPV080T4B	96.0	\$500
Lennox Elite 90	EL296DF070XV48B-*	96.0	\$500	Napoleon	NPV100T5B	96.0	\$500
Lennox Elite 90	EL296DF090XE48C-*	96.0	\$500	Napoleon	NPV120T5B	96.0	\$500
Lennox Elite 90	EL296DF090XV60C-*	96.0	\$500	Napoleon	NPX030S2B	95.0	\$500
Lennox Elite 90	EL296DF110XE60C-*	96.0	\$500	Napoleon	NPX040S2B	95.0	\$500
Lennox Elite 90	EL296DF110XV60C-*	96.0	\$500	Napoleon	NPX060S3B	95.0	\$500
Lennox Elite 90	EL296UH045XE36B-*	96.0	\$500	Napoleon	NPX080S3B	95.0	\$500
Lennox Elite 90	EL296UH045XV36B-*	96.0	\$500	Napoleon	NPX080S4B	95.0	\$500
Lennox Elite 90	EL296UH070XE36B-*	95.5	\$500	Napoleon	NPX100S5B	95.0	\$500
Lennox Elite 90	EL296UH070XV36B-*	96.0	\$500	Napoleon	NPX120S5B	95.0	\$500
Lennox Elite 90	EL296UH090XE48C-*	96.0	\$500	Napoleon	NUV040T2B	97.0	\$700
Lennox Elite 90	EL296UH090XV36C-*	96.0	\$500	Napoleon	NUV060T3B	97.0	\$700
Lennox Elite 90	EL296UH090XV48C-*	96.0	\$500	Napoleon	NUV080T3B	97.0	\$700
Lennox Elite 90	EL296UH090XV60C-*	96.0	\$500	Napoleon	NUV080T4B	97.0	\$700
Lennox Elite 90	EL296UH110XE60C-*	96.0	\$500	Napoleon	NUV100T5B	97.0	\$700
Lennox Elite 90	EL296UH110XV48C-*	96.0	\$500	Napoleon	NUV120T5B	97.0	\$700
Lennox Elite 90	EL296UH110XV60C-*	96.0	\$500	Nordyne	FG7MQ060*-VB	97.0	\$700
Lennox Elite 90	EL296UH135XE60D-*	96.0	\$500	Nordyne	FG7MQ080*-VC	97.2	\$700
Lennox Elite 90	EL296UH135XV60D-*	96.0	\$500	Nordyne	FG7MQ100*-VC	97.4	\$700
Lennox Industries	95G2DF045BV12-*	95.0	\$500	Nordyne	FG7MQ120*-VD	97.0	\$700
Lennox Industries	95G2DF070BV16-*	95.0	\$500	Nordyne	FG7TC120*-D*	95.1	\$500
Lennox Industries	95G2DF090CV20-*	95.0	\$500	Nordyne	KG7MQ060*-VB	97.0	\$700
Lennox Industries	95G2DF110CV20-*	95.0	\$500	Nordyne	KG7MQ080*-VC	97.2	\$700
Lennox Industries	96G1UH030BE08-*	96.1	\$500	Nordyne	KG7MQ100*-VC	97.4	\$700
Lennox Industries	EL196DF045XE36B-*	96.1	\$500	Nordyne	KG7MQ120*-VD	97.0	\$700
Lennox Industries	EL196DF070XE48B-*	96.1	\$500	Nordyne	KG7TC120*-D*	95.1	\$500
Lennox Industries	EL196DF090XE48C-*	96.1	\$500	Nortek Global HVAC	FG7MQ 060*-VB	97.0	\$700
Lennox Industries	EL196UH030XE24B-*	96.1	\$500	Nortek Global HVAC	FG7MQ 080*-VC	97.0	\$700
Lennox Industries	EL196UH045XE24B-*	96.4	\$500	Nortek Global HVAC	FG7MQ 100*-VC	97.0	\$700
Lennox Industries	EL196UH045XE36B-*	96.6	\$500	Nortek Global HVAC	FG7MQ 120*-VD	97.0	\$700
Lennox Industries	EL196UH070XE36B-*	96.1	\$500	Nortek Global HVAC	FG7TC 060*-B*	95.0	\$500
Lennox Industries	EL196UH090XE48C-*	96.3	\$500	Nortek Global HVAC	FG7TC 080*-C*	95.0	\$500
Lennox Industries	EL196UH110XE60C-*	96.4	\$500	Nortek Global HVAC	FG7TC 100*-C*	95.0	\$500
Lennox Industries	SL297UH040NV36B-*	97.5	\$700	Nortek Global HVAC	FG7TC 120*-D*	95.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Nortek Global HVAC	FG7TL 060*-B*	95.0	\$500	Philco	KG7TC120*-*D*	95.1	\$500
Nortek Global HVAC	FG7TL 080*-C*	95.0	\$500	Rheem	D96VA0852521MSA	96.0	\$500
Nortek Global HVAC	FG7TL 100*-C*	95.0	\$500	Rheem	R95TA0601317MSA	95.0	\$500
Nortek Global HVAC	KG7TC 060*-B*	95.0	\$500	Rheem	R95TA1151524MSA	95.0	\$500
Nortek Global HVAC	KG7TC 080*-C*	95.0	\$500	Rheem	R96VA0402317MSA	96.0	\$500
Nortek Global HVAC	KG7TC 100*-C*	95.0	\$500	Rheem	R96VA0602317MSA	96.0	\$500
Nortek Global HVAC	KG7TC 120*-*D*	95.0	\$500	Rheem	R96VA0702317MSA	96.0	\$500
Nortek Global HVAC	KG7TL 060*-B*	95.0	\$500	Rheem	R96VA0852521MSB	96.0	\$500
Nortek Global HVAC	KG7TL 080*-C*	95.0	\$500	Rheem	R96VA1002521MSA	95.0	\$500
Nortek Global HVAC	KG7TL 100*-C*	95.0	\$500	Rheem	R96VA1152524MSA	96.0	\$500
Nortek Global HVAC	MGC2TC060D-*B*	95.0	\$500	Rheem	R97VA060M317KSA	97.0	\$700
Nortek Global HVAC	MGC2TC080D-*C*	95.0	\$500	Rheem	R97VA060M317USA	97.0	\$700
Nortek Global HVAC	MGC2TC100D-*C*	95.0	\$500	Rheem	R97VA070M317KSA	97.0	\$700
Nortek Global HVAC	MGC2TC120D-*D*	95.0	\$500	Rheem	R97VA070M317USA	97.0	\$700
Nortek Global HVAC	MGC2TL060*-*B*	95.0	\$500	Rheem	R97VA085M521KSA	97.0	\$700
Nortek Global HVAC	MGC2TL080*-*C*	95.0	\$500	Rheem	R97VA085M521USA	97.0	\$700
Nortek Global HVAC	MGC2TL100*-*C*	95.0	\$500	Rheem	R97VA100M521KSA	97.0	\$700
Nortek Global HVAC	PGC2MQ 060*-VB	97.0	\$700	Rheem	R97VA100M521USA	97.0	\$700
Nortek Global HVAC	PGC2MQ 080*-VC	97.0	\$700	Rheem	R97VA115M524KSA	97.0	\$700
Nortek Global HVAC	PGC2MQ 100*-VC	97.0	\$700	Rheem	R97VA115M524USA	97.0	\$700
Nortek Global HVAC	PGC2MQ 120*-VD	97.0	\$700	Rheem	R97VA115M524USA	97.0	\$700
Nortek Global HVAC	PGC2TC060*-*B*	95.0	\$500	Rheem	R98VA060M317USA	98.7	\$700
Nortek Global HVAC	PGC2TC080*-*C*	95.0	\$500	Rheem	R98VA070M317USA	98.3	\$700
Nortek Global HVAC	PGC2TC100*-*C*	95.0	\$500	Rheem	R98VA085M521USA	98.1	\$700
Nortek Global HVAC	PGC2TC120*-*D*	95.0	\$500	Rheem	R98VA100M521USA	98.1	\$700
Nortek Global HVAC	PGC2TL060D*-*B*	95.0	\$500	Rheem	R98VA115M524USA	98.6	\$700
Nortek Global HVAC	PGC2TL080D*-*C*	95.0	\$500	Rheem	RGFG-06EMCKS	96.0	\$500
Nortek Global HVAC	PGC2TL100D*-*C*	95.0	\$500	Rheem	RGFG-07EMCKS	95.3	\$500
Nortek Global HVAC	VG7TC 060*-B*	95.0	\$500	Rheem	RGFG-09EZCMS	95.1	\$500
Nortek Global HVAC	VG7TC 080*-C*	95.0	\$500	Rheem	RGRM-06(E,N)MAES	95.0	\$500
Nortek Global HVAC	VG7TC 100*-C*	95.0	\$500	Rheem	RGRM-07(E,N)MAES	95.0	\$500
Nortek Global HVAC	VG7TC 120*-*D*	95.0	\$500	Rheem	RGRM-10(E,N)ZAJ	95.0	\$500
NTI	GF 200	97.1	\$700	Rheem	S96VA0852521MSA	96.0	\$500
NuTone	FG7MQ060*-VB	97.0	\$700	Rheem	U96VA0852521MSA	96.0	\$500
NuTone	FG7MQ080*-VC	97.2	\$700	Rheem	W96VA0852521MSA	96.0	\$500
NuTone	FG7MQ100*-VC	97.4	\$700	Rheem Ruud	R95TC0601317MSA	95.0	\$500
NuTone	FG7MQ120*-VD	97.0	\$700	Rheem Ruud	R95TC1151524MSA	95.0	\$500
NuTone	FG7TC120*-*D*	95.1	\$500	Rheem-Ruud	D95TA0601317MSA	95.0	\$500
NuTone	KG7TC120*-*D*	95.1	\$500	Rheem-Ruud	D95TA1151524MSA	95.0	\$500
NY Thermal Inc.	GF 200	97.1	\$700	Rheem-Ruud	D95TC0601317MSA	95.0	\$500
Olsen	G95V100-5	95.0	\$500	Rheem-Ruud	D95TC1151524MSA	95.0	\$500
Payne	PG95XAT30040A	95.5	\$500	Rheem-Ruud	D96VA0402317MSA	96.0	\$500
Payne	PG95XAT36040B	96.0	\$500	Rheem-Ruud	D96VA0602317MSA	96.0	\$500
Payne	PG95XAT36060A	95.0	\$500	Rheem-Ruud	D96VA0702317MSA	96.0	\$500
Payne	PG95XAT42060B	95.5	\$500	Rheem-Ruud	D96VA1002521MSA	95.0	\$500
Payne	PG95XAT48080B	95.5	\$500	Rheem-Ruud	D96VA1152524MSA	96.0	\$500
Payne	PG95XAT60080C	95.5	\$500	Rheem-Ruud	R95TA0601317MSA	95.0	\$500
Payne	PG95XAT60100C	95.5	\$500	Rheem-Ruud	R95TA1151524MSA	95.0	\$500
Payne	PG95XAT66120D	95.5	\$500	Rheem-Ruud	R95TC0601317MSA	95.0	\$500
Payne	PG96VAT30040A	96.0	\$500	Rheem-Ruud	R95TC1151524MSA	95.0	\$500
Payne	PG96VAT42060B	96.0	\$500	Rheem-Ruud	R96VA0402317MSA	96.0	\$500
Payne	PG96VAT48080B	96.0	\$500	Rheem-Ruud	R96VA0602317MSA	96.0	\$500
Payne	PG96VAT60080C	96.0	\$500	Rheem-Ruud	R96VA0702317MSA	96.0	\$500
Payne	PG96VAT60100C	96.0	\$500	Rheem-Ruud	R96VA1002521MSA	95.0	\$500
Payne	PG96VAT66120D	96.0	\$500	Rheem-Ruud	R96VA1152524MSA	96.0	\$500
Philco	FG7MQ060*-VB	97.0	\$700	Rheem-Ruud	R97VA060M317USA	97.0	\$700
Philco	FG7MQ080*-VC	97.2	\$700	Rheem-Ruud	R97VA070M317USA	97.0	\$700
Philco	FG7MQ100*-VC	97.4	\$700	Rheem-Ruud	R97VA085M521USA	97.0	\$700
Philco	FG7MQ120*-VD	97.0	\$700	Rheem-Ruud	R97VA100M521USA	97.0	\$700
Philco	FG7TC120*-*D*	95.1	\$500	Rheem-Ruud	R97VA115M524USA	97.0	\$700



Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Rheem-Ruud	RGFG-06EMCKS	96.0	\$500	Rheem-Ruud Manufacturing	R92TA1151524MSA	95.0	\$500
Rheem-Ruud	RGFG-07EMCKS	95.0	\$500	Rheem-Ruud Manufacturing	R95TC0601317MSA	95.0	\$500
Rheem-Ruud	RGFG-09EZCMS	95.0	\$500	Rheem-Ruud Manufacturing	R95TC1151524MSA	95.0	\$500
Rheem-Ruud	RGJF-06(E,N)MCKS	95.0	\$500	Rheem-Ruud Manufacturing	R96VA0402317MSA	96.0	\$500
Rheem-Ruud	S95TA0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	R96VA0602317MSA	96.0	\$500
Rheem-Ruud	S95TA1151524MSA	95.0	\$500	Rheem-Ruud Manufacturing	R96VA0702317MSA	96.0	\$500
Rheem-Ruud	S95TC0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	R96VA1002521MSA	95.0	\$500
Rheem-Ruud	S95TC1151524MSA	95.0	\$500	Rheem-Ruud Manufacturing	R96VA1152524MSA	96.0	\$500
Rheem-Ruud	S96VA0402317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R97VA060M317USA	97.0	\$700
Rheem-Ruud	S96VA0602317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R97VA070M317USA	97.0	\$700
Rheem-Ruud	S96VA0702317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R97VA085M521USA	97.0	\$700
Rheem-Ruud	S96VA1002521MSA	95.0	\$500	Rheem-Ruud Manufacturing	R97VA100M521USA	97.0	\$700
Rheem-Ruud	S96VA1152524MSA	96.0	\$500	Rheem-Ruud Manufacturing	R97VA115M524USA	97.0	\$700
Rheem-Ruud	TZ95MSX060B30C	95.0	\$500	Rheem-Ruud Manufacturing	R97VB060M317USA	97.0	\$700
Rheem-Ruud	TZ95MSX115D50C	95.0	\$500	Rheem-Ruud Manufacturing	R97VB070M317USA	97.0	\$700
Rheem-Ruud	TZ96MDV040B30A	96.0	\$500	Rheem-Ruud Manufacturing	R97VB085M521USA	97.0	\$700
Rheem-Ruud	TZ96MDV115D50A	96.0	\$500	Rheem-Ruud Manufacturing	R97VB100M521USA	97.0	\$700
Rheem-Ruud	U96VA0402317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R97VB115M524USA	97.0	\$700
Rheem-Ruud	U96VA0602317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R98VB060M317USA	98.7	\$700
Rheem-Ruud	U96VA0702317MSA	96.0	\$500	Rheem-Ruud Manufacturing	R98VB070M317USA	98.3	\$700
Rheem-Ruud	U96VA1002521MSA	95.0	\$500	Rheem-Ruud Manufacturing	R98VB085M521USA	98.1	\$700
Rheem-Ruud	U96VA1152524MSA	96.0	\$500	Rheem-Ruud Manufacturing	R98VB100M521USA	98.1	\$700
Rheem-Ruud	U97VA060M317USA	97.0	\$700	Rheem-Ruud Manufacturing	R98VB115M524USA	98.6	\$700
Rheem-Ruud	U97VA070M317USA	97.0	\$700	Rheem-Ruud Manufacturing	RGFG-06EMCKS	96.0	\$500
Rheem-Ruud	U97VA085M521USA	97.0	\$700	Rheem-Ruud Manufacturing	RGFG-07EMCKS	95.0	\$500
Rheem-Ruud	U97VA100M521USA	97.0	\$700	Rheem-Ruud Manufacturing	RGGE-06(E,N)MCKS	92.0	\$500
Rheem-Ruud	U97VA115M524USA	97.0	\$700	Rheem-Ruud Manufacturing	RGGE-07(E,N)MCKS	90.0	\$500
Rheem-Ruud	W95TA0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGGE-09(E,N)ZCMS	92.0	\$500
Rheem-Ruud	W95TA1151524MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGGE-10(E,N)ZCMS	91.0	\$500
Rheem-Ruud	W95TC0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGGE-12(E,N)RCMS	92.0	\$500
Rheem-Ruud	W95TC1151524MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGJF-06(E,N)MCKS	95.0	\$500
Rheem-Ruud Manufacturing	D92TA0401317MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGJF-07(E,N)MCKS	93.0	\$500
Rheem-Ruud Manufacturing	D92TA0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGJF-09(E,N)ZCMS	90.0	\$500
Rheem-Ruud Manufacturing	D92TA0701317MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGJF-10(E,N)ZCMS	90.0	\$500
Rheem-Ruud Manufacturing	D92TA0851521MSA	95.0	\$500	Rheem-Ruud Manufacturing	RGJF-12(E,N)RCMS	92.0	\$500
Rheem-Ruud Manufacturing	D92TA1001521MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA0401317MSA	95.0	\$500
Rheem-Ruud Manufacturing	D92TA11515241MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA0601317MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC0401317MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA0701317MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA0851521MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC0701317MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA1001521MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC0851521MSA	95.0	\$500	Rheem-Ruud Manufacturing	S92TA1151524MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC1001521MSA	95.0	\$500	Rheem-Ruud Manufacturing	S95TC0601317MSA	95.0	\$500
Rheem-Ruud Manufacturing	D95TC1151524MSA	95.0	\$500	Rheem-Ruud Manufacturing	S95TC0701317MSA	95.0	\$500
Rheem-Ruud Manufacturing	D96TA0402317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S95TC1001521MSA	95.0	\$500
Rheem-Ruud Manufacturing	D96TA0602317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S95TC1151524MSA	95.0	\$500
Rheem-Ruud Manufacturing	D96TA0702317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA0402317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96TA0852521MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA0602317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96TA1002521MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA0702317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96TA11525241MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA0852521MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96TA1152524MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA1002521MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96VA0402317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96TA1152524MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96VA0602317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96VA0402317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96VA0702317MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96VA0602317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96VA1002521MSA	95.0	\$500	Rheem-Ruud Manufacturing	S96VA0702317MSA	96.0	\$500
Rheem-Ruud Manufacturing	D96VA1152524MSA	96.0	\$500	Rheem-Ruud Manufacturing	S96VA1002521MSA	95.0	\$500
Rheem-Ruud Manufacturing	R92TA0401317MSA	95.0	\$500	Rheem-Ruud Manufacturing	S96VA1152524MSA	96.0	\$500
Rheem-Ruud Manufacturing	R92TA0601317MSA	95.0	\$500	Rheem-Ruud Manufacturing	TZ92MSX040B30A	95.0	\$500
Rheem-Ruud Manufacturing	R92TA0701317MSA	95.0	\$500	Rheem-Ruud Manufacturing	TZ92MSX060B30A	95.0	\$500
Rheem-Ruud Manufacturing	R92TA0851521MSA	95.0	\$500	Rheem-Ruud Manufacturing	TZ92MSX070B30A	95.0	\$500
Rheem-Ruud Manufacturing	R92TA1001521MSA	95.0	\$500	Rheem-Ruud Manufacturing	TZ92MSX085C50A	95.0	\$500

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Rheem-Ruud Manufacturing	TZ92MSX100C50A	95.0	\$500	Rheem/RUUD	R96TA1152524MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ92MSX115D50A	95.0	\$500	Ruud	R95TA0601317MSA	95.0	\$500
Rheem-Ruud Manufacturing	TZ95MSX040B30C	95.0	\$500	Ruud	R95TA1151524MSA	95.0	\$500
Rheem-Ruud Manufacturing	TZ95MSX060B30C	95.0	\$500	Ruud	RGFG-06EMCKS	96.0	\$500
Rheem-Ruud Manufacturing	TZ95MSX070B30C	95.0	\$500	Ruud	RGFG-07EMCKS	95.3	\$500
Rheem-Ruud Manufacturing	TZ95MSX085C50C	95.0	\$500	Ruud	RGFG-09EZCMS	95.1	\$500
Rheem-Ruud Manufacturing	TZ95MSX100C50C	95.0	\$500	Ruud	RGRM-06(E,N)MAES	95.0	\$500
Rheem-Ruud Manufacturing	TZ95MSX115D50C	95.0	\$500	Ruud	RGRM-07(E,N)MAES	95.0	\$500
Rheem-Ruud Manufacturing	TZ96MDV040B30A	96.0	\$500	Ruud	RGRM-10(E,N)ZAJ	95.0	\$500
Rheem-Ruud Manufacturing	TZ96MDV085C50B	96.0	\$500	Ruud	U96VA0402317MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDV115D50A	96.0	\$500	Ruud	U96VA0602317MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDX040B30A	96.0	\$500	Ruud	U96VA0702317MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDX060B30A	96.0	\$500	RUUD	U96VA0852521MSB	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDX070B30A	96.0	\$500	Ruud	U96VA1002521MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDX085C50A	96.0	\$500	Ruud	U96VA1152524MSA	96.0	\$500
Rheem-Ruud Manufacturing	TZ96MDX100C50A	96.0	\$500	RUUD	U97VA060M317KSA	97.0	\$700
Rheem-Ruud Manufacturing	TZ96MDX115D50A	96.0	\$500	Ruud	U97VA060M317USA	97.0	\$700
Rheem-Ruud Manufacturing	U96VA0402317MSA	96.0	\$500	RUUD	U97VA070M317KSA	97.0	\$700
Rheem-Ruud Manufacturing	U96VA0602317MSA	96.0	\$500	Ruud	U97VA070M317USA	97.0	\$700
Rheem-Ruud Manufacturing	U96VA0702317MSA	96.0	\$500	RUUD	U97VA085M521KSA	97.0	\$700
Rheem-Ruud Manufacturing	U96VA1002521MSA	95.0	\$500	Ruud	U97VA085M521USA	97.0	\$700
Rheem-Ruud Manufacturing	U96VA1152524MSA	96.0	\$500	RUUD	U97VA100M521KSA	97.0	\$700
Rheem-Ruud Manufacturing	U97VA060M317USA	97.0	\$700	Ruud	U97VA100M521USA	97.0	\$700
Rheem-Ruud Manufacturing	U97VA070M317USA	97.0	\$700	RUUD	U97VA115M524KSA	97.0	\$700
Rheem-Ruud Manufacturing	U97VA085M521USA	97.0	\$700	Ruud	U97VA115M524USA	97.0	\$700
Rheem-Ruud Manufacturing	U97VA100M521USA	97.0	\$700	RUUD	U98VA060M317USA	98.7	\$700
Rheem-Ruud Manufacturing	U97VA115M524USA	97.0	\$700	RUUD	U98VA070M317USA	98.3	\$700
Rheem-Ruud Manufacturing	U97VB060M317USA	97.0	\$700	RUUD	U98VA085M521USA	98.1	\$700
Rheem-Ruud Manufacturing	U97VB070M317USA	97.0	\$700	RUUD	U98VA100M521USA	98.1	\$700
Rheem-Ruud Manufacturing	U97VB085M521USA	97.0	\$700	RUUD	U98VA115M524USA	98.6	\$700
Rheem-Ruud Manufacturing	U97VB100M521USA	97.0	\$700	Style Crest Inc.	VMC1-50DV3	95.0	\$500
Rheem-Ruud Manufacturing	U97VB115M524USA	97.0	\$700	Style Crest Inc.	VMC1-75DV3	95.0	\$500
Rheem-Ruud Manufacturing	U98VB060M317USA	98.7	\$700	Stylecrest Inc.	VMA1-75N	95.0	\$500
Rheem-Ruud Manufacturing	U98VB070M317USA	98.3	\$700	Sure	B96VA0602317MSA	96.0	\$500
Rheem-Ruud Manufacturing	U98VB085M521USA	98.1	\$700	Sure	B96VA0702317MSA	96.0	\$500
Rheem-Ruud Manufacturing	U98VB100M521USA	98.1	\$700	Sure	B96VA0852521MSA	96.0	\$500
Rheem-Ruud Manufacturing	U98VB115M524USA	98.6	\$700	Sure	B96VA1002521MSA	96.0	\$500
Rheem-Ruud Manufacturing	W92TA0401317MSA	95.0	\$500	Sure	GF902U060CS36	95.0	\$500
Rheem-Ruud Manufacturing	W92TA0601317MSA	95.0	\$500	Sure	GF902U075CS36	95.0	\$500
Rheem-Ruud Manufacturing	W92TA0701317MSA	95.0	\$500	Sure	GF902U105CS60	95.0	\$500
Rheem-Ruud Manufacturing	W92TA0851521MSA	95.0	\$500	Sure	S95TA0601317MSA	95.0	\$500
Rheem-Ruud Manufacturing	W92TA1001521MSA	95.0	\$500	Sure	S95TA1151524MSA	95.0	\$500
Rheem-Ruud Manufacturing	W92TA1151524MSA	95.0	\$500	Sure	S96VA0402317MSA	96.0	\$500
Rheem-Ruud Manufacturing	W95TC0601317MSA	95.0	\$500	Tappan	FG7MQ060*-VB	97.0	\$700
Rheem-Ruud Manufacturing	W95TC1151524MSA	95.0	\$500	Tappan	FG7MQ080*-VC	97.2	\$700
Rheem-Ruud Manufacturing	W96TA0402317MSA	96.0	\$500	Tappan	FG7MQ100*-VC	97.4	\$700
Rheem-Ruud Manufacturing	W96TA0602317MSA	96.0	\$500	Tappan	FG7MQ120*-VD	97.0	\$700
Rheem-Ruud Manufacturing	W96TA0702317MSA	96.0	\$500	Tappan	FG7TC120*-D*	95.1	\$500
Rheem-Ruud Manufacturing	W96TA0852521MSA	96.0	\$500	Tappan	KG7TC120*-D*	95.1	\$500
Rheem-Ruud Manufacturing	W96TA1002521MSA	96.0	\$500	Tempstar	F9MAC0601714A	97.0	\$700
Rheem-Ruud Manufacturing	W96TA1152524MSA	96.0	\$500	Tempstar	F9MAC0602120A	98.0	\$700
Rheem/RUUD	R95TC0401317MSA	95.0	\$500	Tempstar	F9MAC0801714A	97.0	\$700
Rheem/RUUD	R95TC0701317MSA	95.0	\$500	Tempstar	F9MAC0802120A	97.0	\$700
Rheem/RUUD	R95TC0851521MSA	95.0	\$500	Tempstar	F9MAC1002122A	97.0	\$700
Rheem/RUUD	R95TC1001521MSA	95.0	\$500	Tempstar	F9MAC1202422A	97.0	\$700
Rheem/RUUD	R96TA0402317MSA	96.0	\$500	Tempstar	F9MAE0601714A	97.0	\$700
Rheem/RUUD	R96TA0602317MSA	96.0	\$500	Tempstar	F9MAE0602120A	98.0	\$700
Rheem/RUUD	R96TA0702317MSA	96.0	\$500	Tempstar	F9MAE0801714A	97.0	\$700
Rheem/RUUD	R96TA0852521MSA	96.0	\$500	Tempstar	F9MAE0802120A	97.0	\$700
Rheem/RUUD	R96TA1002521MSA	96.0	\$500	Tempstar	F9MAE1002122A	97.0	\$700

Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Tempstar	F9MAE1202422A	97.0	\$700	Trane	S9V2D120U5PS***	96.0	\$500
Tempstar	F9MVE0401410A	96.0	\$500	Trane	TDH2B060A9V3VB*	96.0	\$500
Tempstar	F9MVE0401712A	96.0	\$500	Trane	TDH2B080A9V3VB*	96.0	\$500
Tempstar	F9MVE0601412A	95.0	\$500	Trane	TDH2B080A9V4VB*	95.0	\$500
Tempstar	F9MVE0601714A	96.0	\$500	Trane	TDH2C100A9V4VB*	96.0	\$500
Tempstar	F9MVE0801716A	96.0	\$500	Trane	TDH2D120A9V5VB*	96.0	\$500
Tempstar	F9MVE0802120A	96.0	\$500	Trane	TDHMB060BCV3VB*	95.0	\$500
Tempstar	F9MVE1002120A	96.0	\$500	Trane	TDHMB080ACV3VB*	96.0	\$500
Tempstar	F9MVE1202422A	96.0	\$500	Trane	TDHMC100ACV4VB*	96.0	\$500
Tempstar	F9MVT0401410A	96.0	\$500	Trane	TDHMD120BCV5VB*	95.0	\$500
Tempstar	F9MVT0601714A	96.0	\$500	Trane	TUH1D120A9H51B*	95.0	\$500
Tempstar	F9MVT0801716A	96.0	\$500	Trane	TUH2B060A9V3VB*	97.0	\$700
Tempstar	F9MVT0802120A	96.0	\$500	Trane	TUH2B080A9V3VB*	97.0	\$700
Tempstar	F9MVT1002120A	96.0	\$500	Trane	TUH2B080A9V4VB*	97.0	\$700
Tempstar	F9MVT1202422A	96.0	\$500	Trane	TUH2C100A9V4VB*	96.7	\$500
Tempstar	F9MXE0401712A	96.0	\$500	Trane	TUH2C100A9V5VB*	96.7	\$500
Tempstar	F9MXE0601412A	95.5	\$500	Trane	TUH2D120A9V5VB*	96.7	\$500
Tempstar	F9MXE1002120A*	96.0	\$500	Trane	TUHMB060ACV3VB*	97.3	\$700
Tempstar	F9MXT0401410A	96.0	\$500	Trane	TUHMB080ACV3VB*	96.7	\$500
Tempstar	F9MXT0401712A	96.0	\$500	Trane	TUHMD120ACV5VB*	97.0	\$700
Tempstar	F9MXT0601412A	95.0	\$500	Trane & American Standard	ADH2B060A9V3VB*	96.0	\$500
Tempstar	F9MXT0601714A	96.0	\$500	Trane & American Standard	ADH2B080A9V3VB*	96.0	\$500
Tempstar	F9MXT0801716A	96.0	\$500	Trane & American Standard	ADH2B080A9V4VB*	95.0	\$500
Tempstar	F9MXT0802120A	96.0	\$500	Trane & American Standard	ADH2C100A9V4VB*	96.0	\$500
Tempstar	F9MXT1002120A	96.0	\$500	Trane & American Standard	ADH2D120A9V5VB*	96.0	\$500
Tempstar	F9MXT1202422A	96.0	\$500	Trane & American Standard	ADHMB060BCV3VB*	95.0	\$500
Thermal Zone	TZ92UP105T(A,AX)	95.0	\$500	Trane & American Standard	ADHMB080ACV3VB*	96.0	\$500
Thermal Zone	TZ92UP603T(A,AX)	95.0	\$500	Trane & American Standard	ADHMD120BCV5VB*	95.0	\$500
Thermal Zone	TZ95MSX060B30A	95.0	\$500	Trane & American Standard	AUH1D120A9H51B*	95.0	\$500
Thermal Zone	TZ95MSX115D50A	95.0	\$500	Trane & American Standard	AUH2B060A9V3VB*	97.0	\$700
Thermal Zone	TZ96MDV040B30A	96.0	\$500	Trane & American Standard	AUH2B080A9V3VB*	97.0	\$700
Thermal Zone	TZ96MDV060B30A	96.0	\$500	Trane & American Standard	AUH2B080A9V4VB*	97.0	\$700
Thermal Zone	TZ96MDV070B30A	96.0	\$500	Trane & American Standard	AUH2C100A9V4VB*	97.0	\$700
Thermal Zone	TZ96MDV100C50A	96.0	\$500	Trane & American Standard	AUH2C100A9V5VB*	97.0	\$700
Thermal Zone	TZ96MDVA060B30A	96.0	\$500	Trane & American Standard	AUH2D120A9V5VB*	97.0	\$700
Thermal Zone	TZ96MDVA070B30A	96.0	\$500	Trane & American Standard	AUHMB060ACV3VB*	97.0	\$700
Thermal Zone	TZ96MDVA100C50A	96.0	\$500	Trane & American Standard	AUHMB080ACV3VB*	97.0	\$700
Thermo Products	CLHS1-075T42N	95.0	\$500	Trane & American Standard	AUHMD120ACV5VB*	97.0	\$700
Thermo Products	CLHS1-100T48N	95.0	\$500	Trane & American Standard	M952V060BD36AB*	96.0	\$500
Thermo Products	CMC1-50DV3	95.0	\$500	Trane & American Standard	M952V060BU36AB*	97.0	\$700
Thermo Products	CMC1-75DV3	95.0	\$500	Trane & American Standard	M952V080BD36AB*	96.0	\$500
Thermo Products LLC	CLQS1-050T36N	95.0	\$500	Trane & American Standard	M952V080BU36AB*	97.0	\$700
Thermo Products LLC	CLQS1-075T42N	95.0	\$500	Trane & American Standard	M952V100CD48AB*	96.0	\$500
Thermo Products LLC	CLQS1-100T48N	95.0	\$500	Trane & American Standard	M952V100CU48AB*	97.0	\$700
Thermo Products LLC	CLQS1-125T60N	95.0	\$500	Trane & American Standard	M952V120DD60AB*	96.0	\$500
Trane	S9V2B040D3PS***	96.0	\$500	Trane & American Standard	M952V120DU60AB*	97.0	\$700
Trane	S9V2B040U3PS***	96.0	\$500	Trane & American Standard	TDH2B060A9V3VB*	96.0	\$500
Trane	S9V2B060D3PS***	96.0	\$500	Trane & American Standard	TDH2B080A9V3VB*	96.0	\$500
Trane	S9V2B060U3PS***	96.0	\$500	Trane & American Standard	TDH2B080A9V4VB*	95.0	\$500
Trane	S9V2B060U4PS***	96.0	\$500	Trane & American Standard	TDH2C100A9V4VB*	96.0	\$500
Trane	S9V2B080D3PS***	96.0	\$500	Trane & American Standard	TDH2D120A9V5VB*	96.0	\$500
Trane	S9V2B080D4PS***	96.0	\$500	Trane & American Standard	TDHMB060BCV3VB*	95.0	\$500
Trane	S9V2B080U3PS***	96.0	\$500	Trane & American Standard	TDHMB080ACV3VB*	96.0	\$500
Trane	S9V2B080U4PS***	96.0	\$500	Trane & American Standard	TDHMD120BCV5VB*	95.0	\$500
Trane	S9V2C080U5PS***	96.0	\$500	Trane & American Standard	TUH1D120A9H51B*	95.0	\$500
Trane	S9V2C100D4PS***	96.0	\$500	Trane & American Standard	TUH2B060A9V3VB*	97.0	\$700
Trane	S9V2C100D5PS***	96.0	\$500	Trane & American Standard	TUH2B080A9V4VB*	97.0	\$700
Trane	S9V2C100U4PS***	96.0	\$500	Trane & American Standard	TUH2C100A9V4VB*	97.0	\$700
Trane	S9V2C100U5PS***	96.0	\$500	Trane & American Standard	TUH2C100A9V5VB*	97.0	\$700
Trane	S9V2D120D5PS***	96.0	\$500	Trane & American Standard	TUH2D120A9V5VB*	97.0	\$700



Manufacturer	Model	AFUE	Rebate	Manufacturer	Model	AFUE	Rebate
Heating and Air Conditioning				Wolf Steel	CTV040T2B	97.0	\$700
Trane and American Standard Heating and Air Conditioning	TDH1D110A9H51B*	95.0	\$500	Wolf Steel	CTV060T3A	97.1	\$700
Trane and American Standard Heating and Air Conditioning	TUH1B060A9H31**	95.0	\$500	Wolf Steel	CTV060T3B	97.0	\$700
Trane and American Standard Heating and Air Conditioning	TUH1B080A9H31**	95.0	\$500	Wolf Steel	CTV080T3A	97.0	\$700
Trane and American Standard Heating and Air Conditioning	TUH1C100A9H41**	95.0	\$500	Wolf Steel	CTV080T3B	97.0	\$700
Trane and American Standard Heating and Air Conditioning	TUHMC100ACV4V**	96.0	\$500	Wolf Steel	CTV100T5A	97.0	\$700
United Refrigeration	TZ96MDVA085C50A	96.0	\$500	Wolf Steel	CTV100T5B	97.0	\$700
Weatherking	W95TA0601317MSA	95.0	\$500	Wolf Steel	CTV120T5A	97.0	\$700
Weatherking	W95TA1151524MSA	95.0	\$500	Wolf Steel	CTV120T5B	97.0	\$700
WeatherKing	W95TC0401317MSA	95.0	\$500	Wolf Steel	NEV040T2A	95.0	\$500
WeatherKing	W95TC0601317MSA	95.0	\$500	Wolf Steel	NEV060T3A	95.0	\$500
WeatherKing	W95TC0701317MSA	95.0	\$500	Wolf Steel	NEV080T3A	95.0	\$500
WeatherKing	W95TC0851521MSA	95.0	\$500	Wolf Steel	NEV080T4A	95.0	\$500
WeatherKing	W95TC1001521MSA	95.0	\$500	Wolf Steel	NEV100T5A	95.0	\$500
WeatherKing	W95TC1151524MSA	95.0	\$500	Wolf Steel	NEV120T5A	95.0	\$500
Weatherking	W96VA0402317MSA	96.0	\$500	Wolf Steel	NPV040T2B	96.0	\$500
Weatherking	W96VA0602317MSA	96.0	\$500	Wolf Steel	NPV045T2A	95.3	\$500
Weatherking	W96VA0702317MSA	96.0	\$500	Wolf Steel	NPV060T3A	95.3	\$500
Weatherking	W96VA1002521MSA	96.0	\$500	Wolf Steel	NPV060T3B	96.0	\$500
Westinghouse	FG7MQ060*-VB	97.0	\$700	Wolf Steel	NPV080T3A	95.3	\$500
Westinghouse	FG7MQ080*-VC	97.2	\$700	Wolf Steel	NPV080T3B	96.0	\$500
Westinghouse	FG7MQ100*-VC	97.4	\$700	Wolf Steel	NPV080T4B	96.0	\$500
Westinghouse	FG7MQ120*-VD	97.0	\$700	Wolf Steel	NPV100T5A	96.0	\$500
Westinghouse	FG7TC120*-D*	95.1	\$500	Wolf Steel	NPV100T5B	96.0	\$500
Westinghouse	KG7TC120*-D*	95.1	\$500	Wolf Steel	NPV120T5A	95.3	\$500
Whirlpool Gold	WGFM295090V5C	96.1	\$500	Wolf Steel	NPV120T5B	96.0	\$500
Wolf Steel	CEV040T2A	95.0	\$500	Wolf Steel	NPX030S2B	95.0	\$500
Wolf Steel	CEV060T3A	95.0	\$500	Wolf Steel	NPX040S2B	95.0	\$500
Wolf Steel	CEV080T3A	95.0	\$500	Wolf Steel	NPX045S2A	95.0	\$500
Wolf Steel	CEV080T4A	95.0	\$500	Wolf Steel	NPX060S3A	95.0	\$500
Wolf Steel	CEV100T5A	95.0	\$500	Wolf Steel	NPX060S3B	95.0	\$500
Wolf Steel	CEV120T5A	95.0	\$500	Wolf Steel	NPX080S3A	95.0	\$500
Wolf Steel	CPV045T2A	95.3	\$500	Wolf Steel	NPX080S3B	95.0	\$500
Wolf Steel	CPV060T3A	95.3	\$500	Wolf Steel	NPX100S5A	95.0	\$500
Wolf Steel	CPV060T3B	96.0	\$500	Wolf Steel	NPX100S5B	95.0	\$500
Wolf Steel	CPV080T3A	95.3	\$500	Wolf Steel	NPX120S5A	95.0	\$500
Wolf Steel	CPV080T3B	96.0	\$500	Wolf Steel	NPX120S5B	95.0	\$500
Wolf Steel	CPV100T5A	96.0	\$500	Wolf Steel	NSX045T2A	95.3	\$500
Wolf Steel	CPV100T5B	96.0	\$500	Wolf Steel	NSX060T3A	95.3	\$500
Wolf Steel	CPV120T5A	95.3	\$500	Wolf Steel	NSX080T3A	95.3	\$500
Wolf Steel	CPV120T5B	96.0	\$500	Wolf Steel	NSX100T5A	96.0	\$500
Wolf Steel	CPX030S2B	95.0	\$500	Wolf Steel	NSX120T5A	95.3	\$500
Wolf Steel	CPX040S2B	95.0	\$500	Wolf Steel	NUV040T2B	97.0	\$700
Wolf Steel	CPX045S2A	95.0	\$500	Wolf Steel	NUV060T3A	97.1	\$700
Wolf Steel	CPX060S3A	95.0	\$500	Wolf Steel	NUV060T3B	97.0	\$700
Wolf Steel	CPX060S3B	95.0	\$500	Wolf Steel	NUV080T3A	97.0	\$700
Wolf Steel	CPX080S3A	95.0	\$500	Wolf Steel	NUV080T3B	97.0	\$700
Wolf Steel	CPX080S3B	95.0	\$500	Wolf Steel	NUV100T5A	97.0	\$700
Wolf Steel	CPX100S5A	95.0	\$500	Wolf Steel	NUV120T5A	97.0	\$700
Wolf Steel	CPX100S5B	95.0	\$500	York	CP9C060B12MP12	98.0	\$700
Wolf Steel	CPX120S5A	95.0	\$500	York	CP9C080B12MP12	98.0	\$700
Wolf Steel	CPX120S5B	95.0	\$500	York	CP9C080C16MP12	98.0	\$700
Wolf Steel	CSX045T2A	95.3	\$500	York	CP9C100C16MP12	98.0	\$700
Wolf Steel	CSX060T3A	95.3	\$500	York	CP9C100C20MP12	98.0	\$700
Wolf Steel	CSX080T3A	95.3	\$500	York	LP9C060B12MP12	98.0	\$700
Wolf Steel	CSX100T5A	96.0	\$500	York	LP9C080B12MP12	98.0	\$700
Wolf Steel	CSX120T5A	95.3	\$500	York	LP9C080C16MP12	98.0	\$700
				York	LP9C100C16MP12	98.0	\$700
				York	LP9C100C20MP12	98.0	\$700
				York	TM9E040A10MP11	95.0	\$500

