

Qualifying Residential
Furnaces

FortisBC

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|------------------------|------------------|------|--------|--------------|------------------|------|--------|
| Advance Comfort System | 95G1UH070BE12*-* | 95.0 | \$500 | Air Ease | A95UH2E070B12*-* | 95.0 | \$500 |
| Advance Comfort System | 95G1UH090CE16*-* | 95.0 | \$500 | Air Ease | A95UH2E090C16*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2DF045BE12* | 95.0 | \$500 | Air Ease | A95UH2E110C20*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2DF070BE16* | 95.0 | \$500 | Air Ease | A95UH2E135D20*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2DF090CE16* | 95.0 | \$500 | Air Ease | A95UH2V045B12*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2DF110CE20* | 95.0 | \$500 | Air Ease | A95UH2V070B12*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH045BE12* | 95.0 | \$500 | Air Ease | A95UH2V090C12*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH045BV12*-* | 95.0 | \$500 | Air Ease | A95UH2V090C16*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH070BE12* | 95.0 | \$500 | Air Ease | A95UH2V090C20*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH070BV12*-* | 95.0 | \$500 | Air Ease | A95UH2V110C16*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH090CE16* | 95.0 | \$500 | Air Ease | A95UH2V110C20*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH090CV12*-* | 95.0 | \$500 | Air Ease | A95UH2V135D20*-* | 95.0 | \$500 |
| Advance Comfort System | 95G2UH090CV20*-* | 95.0 | \$500 | Air Ease | A96DS2V045B12S-* | 96.0 | \$500 |
| Advance Comfort System | 95G2UH110CE20* | 95.0 | \$500 | Air Ease | A96DS2V070B16S-* | 96.0 | \$500 |
| Advance Comfort System | 95G2UH110CV20*-* | 95.0 | \$500 | Air Ease | A96DS2V090C20S-* | 96.0 | \$500 |
| Advance Comfort System | 95G2UH135DE20* | 95.0 | \$500 | Air Ease | A96DS2V110C20S-* | 96.0 | \$500 |
| Advance Comfort System | 95G2UH135DV20*-* | 95.0 | \$500 | Air Ease | A96US2V045B12S-* | 96.0 | \$500 |
| Advance Comfort System | A95DF2V045B12*-* | 95.0 | \$500 | Air Ease | A96US2V070B12S-* | 96.0 | \$500 |
| Advance Comfort System | A95DF2V070B16*-* | 95.0 | \$500 | Air Ease | A96US2V090C12S-* | 96.0 | \$500 |
| Advance Comfort System | A95DF2V090C20*-* | 95.0 | \$500 | Air Ease | A96US2V090C16S-* | 96.0 | \$500 |
| Advance Comfort System | A95DF2V110C20*-* | 95.0 | \$500 | Air Ease | A96US2V090C20S-* | 96.0 | \$500 |
| Advance Comfort System | A95UH1E070B12*-* | 95.0 | \$500 | Air Ease | A96US2V110C16S-* | 96.0 | \$500 |
| Advance Comfort System | A95UH1E090C16*-* | 95.0 | \$500 | Air Ease | A96US2V110C20S-* | 96.0 | \$500 |
| Advance Comfort System | A95UH2E045B12*-* | 95.0 | \$500 | Air Ease | A96US2V135D20S-* | 96.0 | \$500 |
| Advance Comfort System | A95UH2V045B12*-* | 95.0 | \$500 | Air Ease | A97DSMV070B12S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V070B12*-* | 95.0 | \$500 | Air Ease | A97DSMV090C16S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V090C12*-* | 95.0 | \$500 | Air Ease | A97DSMV090C20S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V090C16*-* | 95.0 | \$500 | Air Ease | A97DSMV110C20S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V090C20*-* | 95.0 | \$500 | Air Ease | A97USMV070B12S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V110C16*-* | 95.0 | \$500 | Air Ease | A97USMV090C12S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V110C20*-* | 95.0 | \$500 | Air Ease | A97USMV090C16S-* | 97.0 | \$700 |
| Advance Comfort System | A95UH2V135D20*-* | 95.0 | \$500 | Air Ease | A97USMV090C20S-* | 97.0 | \$700 |
| Advance Comfort System | A97DSMV070B12S-* | 97.0 | \$700 | Air Ease | A97USMV110C20S-* | 97.0 | \$700 |
| Advance Comfort System | A97DSMV090C16S-* | 97.0 | \$700 | Air Ease | A97USMV135D20S-* | 97.0 | \$700 |
| Advance Comfort System | A97DSMV090C20S-* | 97.0 | \$700 | Aire-Flo | 95AF2DF045V12B-* | 95.0 | \$500 |
| Advance Comfort System | A97DSMV110C20S-* | 97.0 | \$700 | Aire-Flo | 95AF2DF070V16B-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV070B12S-* | 97.0 | \$700 | Aire-Flo | 95AF2DF090V20C-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV090C12S-* | 97.0 | \$700 | Aire-Flo | 95AF2DF110V20C-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV090C16S-* | 97.0 | \$700 | Aire-Flo | 95AF2UH045V12B-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV090C20S-* | 97.0 | \$700 | Aire-Flo | 95AF2UH070V12B-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV110C20S-* | 97.0 | \$700 | Aire-Flo | 95AF2UH090V12C-* | 95.0 | \$500 |
| Advance Comfort System | A97USMV135D20S-* | 97.0 | \$700 | Aire-Flo | 95AF2UH110V20C-* | 95.0 | \$500 |
| Air Ease | A95DF2E045B12*-* | 95.0 | \$500 | Aire-Flo | 95AF2UH135V20D-* | 95.0 | \$500 |
| Air Ease | A95DF2E070B16*-* | 95.0 | \$500 | Airquest | G9MAC0601714A | 97.0 | \$700 |
| Air Ease | A95DF2E090C16*-* | 95.0 | \$500 | Airquest | G9MAC0602120A | 98.0 | \$700 |
| Air Ease | A95DF2E110C20*-* | 95.0 | \$500 | Airquest | G9MAC0801714A | 97.0 | \$700 |
| Air Ease | A95DF2V045B12*-* | 95.0 | \$500 | Airquest | G9MAC0802120A | 97.0 | \$700 |
| Air Ease | A95DF2V070B16*-* | 95.0 | \$500 | Airquest | G9MAC1002122A | 97.0 | \$700 |
| Air Ease | A95DF2V090C20*-* | 95.0 | \$500 | Airquest | G9MAC1202422A | 97.0 | \$700 |
| Air Ease | A95DF2V110C20*-* | 95.0 | \$500 | Airquest | G9MAE0601714A | 97.0 | \$700 |
| Air Ease | A95UH1E070B12*-* | 95.0 | \$500 | Airquest | G9MAE0602120A | 98.0 | \$700 |
| Air Ease | A95UH1E090C16*-* | 95.0 | \$500 | Airquest | G9MAE0801714A | 97.0 | \$700 |
| Air Ease | A95UH2E045B12*-* | 95.0 | \$500 | Airquest | G9MAE0802120A | 97.0 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------|------------------|------|--------|------------------------|------------------|------|--------|
| Airquest | G9MAE1002122A | 97.0 | \$700 | Allied | A95UH2E110C20*-* | 95.0 | \$500 |
| Airquest | G9MAE1202422A | 97.0 | \$700 | Allied | A95UH2E135D20*-* | 95.0 | \$500 |
| Airquest | G9MVE0401410A | 96.0 | \$500 | Allied | A95UH2V045B12*-* | 95.0 | \$500 |
| Airquest | G9MVE0401712A | 96.0 | \$500 | Allied | A95UH2V070B12*-* | 95.0 | \$500 |
| Airquest | G9MVE0601412A | 95.0 | \$500 | Allied | A95UH2V090C12*-* | 95.0 | \$500 |
| Airquest | G9MVE0601714A | 96.0 | \$500 | Allied | A95UH2V090C16*-* | 95.0 | \$500 |
| Airquest | G9MVE0801716A | 96.0 | \$500 | Allied | A95UH2V090C20*-* | 95.0 | \$500 |
| Airquest | G9MVE0802120A | 96.0 | \$500 | Allied | A95UH2V110C16*-* | 95.0 | \$500 |
| Airquest | G9MVE1002116A | 96.0 | \$500 | Allied | A95UH2V110C20*-* | 95.0 | \$500 |
| Airquest | G9MVE1002120A | 96.0 | \$500 | Allied | A95UH2V135D20*-* | 95.0 | \$500 |
| Airquest | G9MVE1202422A | 96.0 | \$500 | Allied | A96DS2V045B12S-* | 96.0 | \$500 |
| Airquest | G9MVT0401410A | 96.0 | \$500 | Allied | A96DS2V070B16S-* | 96.0 | \$500 |
| Airquest | G9MVT0601714A | 96.0 | \$500 | Allied | A96DS2V090C20S-* | 96.0 | \$500 |
| Airquest | G9MVT0801716A | 96.0 | \$500 | Allied | A96DS2V110C20S-* | 96.0 | \$500 |
| Airquest | G9MVT0802120A | 96.0 | \$500 | Allied | A96US2V045B12S-* | 96.0 | \$500 |
| Airquest | G9MVT1002120A | 96.0 | \$500 | Allied | A96US2V070B12S-* | 96.0 | \$500 |
| Airquest | G9MVT1202422A | 96.0 | \$500 | Allied | A96US2V090C12S-* | 96.0 | \$500 |
| Airquest | G9MXE0401410A | 96.0 | \$500 | Allied | A96US2V090C16S-* | 96.0 | \$500 |
| Airquest | G9MXE0401712A* | 96.0 | \$500 | Allied | A96US2V090C20S-* | 96.0 | \$500 |
| Airquest | G9MXE0601412A* | 95.5 | \$500 | Allied | A96US2V110C16S-* | 96.0 | \$500 |
| Airquest | G9MXE0601714A | 96.0 | \$500 | Allied | A96US2V110C20S-* | 96.0 | \$500 |
| Airquest | G9MXE0801716A | 96.0 | \$500 | Allied | A96US2V135D20S-* | 96.0 | \$500 |
| Airquest | G9MXE0802120A | 96.0 | \$500 | Allied | A97DSMV070B12S-* | 97.0 | \$700 |
| Airquest | G9MXT0401410A | 96.0 | \$500 | Allied | A97DSMV090C16S-* | 97.0 | \$700 |
| Airquest | G9MXT0601714A | 96.0 | \$500 | Allied | A97DSMV090C20S-* | 97.0 | \$700 |
| Airquest | G9MXT0801716A | 96.0 | \$500 | Allied | A97DSMV110C20S-* | 97.0 | \$700 |
| Airquest | G9MXT0802120A | 96.0 | \$500 | Allied | A97USMV070B12S-* | 97.0 | \$700 |
| Airquest | G9MXT1002120A | 96.0 | \$500 | Allied | A97USMV090C12S-* | 97.0 | \$700 |
| Airquest | G9MXT1202422A | 96.0 | \$500 | Allied | A97USMV090C16S-* | 97.0 | \$700 |
| Airtemp | VG7TC120*-D* | 95.1 | \$500 | Allied | A97USMV090C20S-* | 97.0 | \$700 |
| Allied | 95G1UH070BE12*-* | 95.0 | \$500 | Allied | A97USMV110C20S-* | 97.0 | \$700 |
| Allied | 95G1UH090CE16*-* | 95.0 | \$500 | Allied | A97USMV135D20S-* | 97.0 | \$700 |
| Allied | 95G2DF045BE12* | 95.0 | \$500 | Allied Air Enterprises | 95AF2DF045V12B-* | 95.0 | \$500 |
| Allied | 95G2DF070BE16* | 95.0 | \$500 | Allied Air Enterprises | 95AF2DF070V16B-* | 95.0 | \$500 |
| Allied | 95G2DF090CE16* | 95.0 | \$500 | Allied Air Enterprises | 95AF2DF090V20C-* | 95.0 | \$500 |
| Allied | 95G2DF110CE20* | 95.0 | \$500 | Allied Air Enterprises | 95AF2DF110V20C-* | 95.0 | \$500 |
| Allied | 95G2UH045BE12* | 95.0 | \$500 | Allied Air Enterprises | 95AF2UH045V12B-* | 95.0 | \$500 |
| Allied | 95G2UH045BV12*-* | 95.0 | \$500 | Allied Air Enterprises | 95AF2UH070V12B-* | 95.0 | \$500 |
| Allied | 95G2UH070BE12* | 95.0 | \$500 | Allied Air Enterprises | 95AF2UH090V12C-* | 95.0 | \$500 |
| Allied | 95G2UH070BV12*-* | 95.0 | \$500 | Allied Air Enterprises | 95AF2UH110V20C-* | 95.0 | \$500 |
| Allied | 95G2UH090CE16* | 95.0 | \$500 | Allied Air Enterprises | 95AF2UH135V20D-* | 95.0 | \$500 |
| Allied | 95G2UH090CV12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G1UH045BE12*-* | 95.0 | \$500 |
| Allied | 95G2UH090CV20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G1UH070BE12*-* | 95.0 | \$500 |
| Allied | 95G2UH110CE20* | 95.0 | \$500 | Allied Air Enterprises | 95G1UH090CE16*-* | 95.0 | \$500 |
| Allied | 95G2UH110CV20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G1UH110CE20*-* | 95.0 | \$500 |
| Allied | 95G2UH135DE20* | 95.0 | \$500 | Allied Air Enterprises | 95G2DF045BE12* | 95.0 | \$500 |
| Allied | 95G2UH135DV20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2DF070BE16* | 95.0 | \$500 |
| Allied | A95DF2E045B12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2DF090CE16* | 95.0 | \$500 |
| Allied | A95DF2E070B16*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2DF110CE20* | 95.0 | \$500 |
| Allied | A95DF2E090C16*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH045BE12* | 95.0 | \$500 |
| Allied | A95DF2E110C20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH045BV12*-* | 95.0 | \$500 |
| Allied | A95DF2V045B12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH070BE12* | 95.0 | \$500 |
| Allied | A95DF2V070B16*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH070BV12*-* | 95.0 | \$500 |
| Allied | A95DF2V090C20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH090CE16* | 95.0 | \$500 |
| Allied | A95DF2V110C20*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH090CV12*-* | 95.0 | \$500 |
| Allied | A95UH1E070B12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH090CV20*-* | 95.0 | \$500 |
| Allied | A95UH1E090C16*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH110CE20* | 95.0 | \$500 |
| Allied | A95UH2E045B12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH110CV20*-* | 95.0 | \$500 |
| Allied | A95UH2E070B12*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH135DE20* | 95.0 | \$500 |
| Allied | A95UH2E090C16*-* | 95.0 | \$500 | Allied Air Enterprises | 95G2UH135DV20*-* | 95.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|------------------------|-------------------|------|--------|------------------------|------------------|------|--------|
| Allied Air Enterprises | 96G1UH030E08-* | 96.1 | \$500 | Allied Air Enterprises | A97USMV070B12S-* | 97.0 | \$700 |
| Allied Air Enterprises | 96G1UH070BE12-* | 96.1 | \$500 | Allied Air Enterprises | A97USMV090C12S-* | 97.0 | \$700 |
| Allied Air Enterprises | 96G1UH090BE16-* | 96.3 | \$500 | Allied Air Enterprises | A97USMV090C16S-* | 97.0 | \$700 |
| Allied Air Enterprises | 96G1UH110BE20-* | 96.4 | \$500 | Allied Air Enterprises | A97USMV090C20S-* | 97.0 | \$700 |
| Allied Air Enterprises | A95DF2E045B12-* | 95.0 | \$500 | Allied Air Enterprises | A97USMV110C20S-* | 97.0 | \$700 |
| Allied Air Enterprises | A95DF2E070B16-* | 95.0 | \$500 | Allied Air Enterprises | A97USMV135D20S-* | 97.0 | \$700 |
| Allied Air Enterprises | A95DF2E090C16-* | 95.0 | \$500 | Amana | ACVC950714CX | 95.0 | \$500 |
| Allied Air Enterprises | A95DF2E110C20-* | 95.0 | \$500 | Amana | ACVC950915DX | 95.0 | \$500 |
| Allied Air Enterprises | A95DF2V045B12-* | 95.0 | \$500 | Amana | ACVC960403BN | 96.1 | \$500 |
| Allied Air Enterprises | A95DF2V070B16-* | 95.0 | \$500 | Amana | ACVC960603BN | 96.1 | \$500 |
| Allied Air Enterprises | A95DF2V090C20-* | 95.0 | \$500 | Amana | ACVC960804CN | 96.1 | \$500 |
| Allied Air Enterprises | A95DF2V110C20-* | 95.0 | \$500 | Amana | ACVC961005CN | 96.1 | \$500 |
| Allied Air Enterprises | A95UH1E045B12-* | 95.0 | \$500 | Amana | ACVC961205DN | 96.1 | \$500 |
| Allied Air Enterprises | A95UH1E070B12-* | 95.0 | \$500 | Amana | ACVM960604CX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH1E090C16-* | 95.0 | \$500 | Amana | ACVM960805DX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH1E110C20-* | 95.0 | \$500 | Amana | ACVM961005DX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH1E135D20-* | 95.0 | \$500 | Amana | ACVM970603BN | 97.0 | \$700 |
| Allied Air Enterprises | A95UH2E045B12-* | 95.0 | \$500 | Amana | ACVM970803BN | 97.0 | \$700 |
| Allied Air Enterprises | A95UH2E070B12-* | 95.0 | \$500 | Amana | ACVM970804CN | 97.0 | \$700 |
| Allied Air Enterprises | A95UH2E090C16-* | 95.0 | \$500 | Amana | ACVM971005CN | 97.0 | \$700 |
| Allied Air Enterprises | A95UH2E110C20-* | 95.0 | \$500 | Amana | AMEC960302BN | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2E135D20-* | 95.0 | \$500 | Amana | AMEC960603BN | 96.0 | \$500 |
| Allied Air Enterprises | A95UH2V045B12-* | 95.0 | \$500 | Amana | AMEC961004CN | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V070B12-* | 95.0 | \$500 | Amana | AMEC961205DN | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V090C12-* | 95.0 | \$500 | Amana | AMVC950453BX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V090C16-* | 95.0 | \$500 | Amana | AMVC950704CX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V090C20-* | 95.0 | \$500 | Amana | AMVC950905CX** | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V110C16-* | 95.0 | \$500 | Amana | AMVC950905DX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V110C20-* | 95.0 | \$500 | Amana | AMVC951155DX | 96.1 | \$500 |
| Allied Air Enterprises | A95UH2V135D20-* | 95.0 | \$500 | Amana | AMVC960403BN | 96.1 | \$500 |
| Allied Air Enterprises | A96DF2E045B12-* | 96.0 | \$500 | Amana | AMVC960603BN | 96.1 | \$500 |
| Allied Air Enterprises | A96DF2E070B16-* | 96.0 | \$500 | Amana | AMVC960803BN | 96.1 | \$500 |
| Allied Air Enterprises | A96DF2E090C16-* | 96.0 | \$500 | Amana | AMVC960804CN | 96.1 | \$500 |
| Allied Air Enterprises | A96DF2E110C20-* | 96.0 | \$500 | Amana | AMVC961005CN | 96.1 | \$500 |
| Allied Air Enterprises | A96DS2V045B12-* | 96.0 | \$500 | Amana | AMVC961205DN | 96.1 | \$500 |
| Allied Air Enterprises | A96DS2V070B16-* | 96.0 | \$500 | Amana | AMVM960603BX | 96.1 | \$500 |
| Allied Air Enterprises | A96DS2V090C20-* | 96.0 | \$500 | Amana | AMVM960805CX | 96.1 | \$500 |
| Allied Air Enterprises | A96DS2V110C20-* | 96.0 | \$500 | Amana | AMVM961005DX | 96.1 | \$500 |
| Allied Air Enterprises | A96UH2E030B08-* | 96.0 | \$500 | Amana | AMVM961155DX | 96.1 | \$500 |
| Allied Air Enterprises | A96UH2E045B12-* | 95.0 | \$500 | Amana | AMVM970603BN | 97.0 | \$700 |
| Allied Air Enterprises | A96UH2E070B12-* | 96.0 | \$500 | Amana | AMVM970803BN | 97.0 | \$700 |
| Allied Air Enterprises | A96UH2E090C16-* | 96.0 | \$500 | Amana | AMVM970804CN | 97.0 | \$700 |
| Allied Air Enterprises | A96UH2E110C20-* | 96.0 | \$500 | Amana | AMVM971005CN | 97.0 | \$700 |
| Allied Air Enterprises | A96UH2E135D20-* | 96.0 | \$500 | Amana | AMVM971205DN | 97.0 | \$700 |
| Allied Air Enterprises | A96US2V045B12-* | 96.0 | \$500 | American Standard | ADH2B060A9V3VB* | 96.0 | \$500 |
| Allied Air Enterprises | A96US2V070B12-* | 96.0 | \$500 | American Standard | ADH2B080A9V3VB* | 96.0 | \$500 |
| Allied Air Enterprises | A96US2V090C12-* | 96.0 | \$500 | American Standard | ADH2B080A9V4VB* | 95.0 | \$500 |
| Allied Air Enterprises | A96US2V090C16-* | 96.0 | \$500 | American Standard | ADH2C100A9V4VB* | 96.0 | \$500 |
| Allied Air Enterprises | A96US2V090C20-* | 96.0 | \$500 | American Standard | ADH2D120A9V5VB* | 96.0 | \$500 |
| Allied Air Enterprises | A96US2V110C16-* | 96.0 | \$500 | American Standard | ADHMB060BCV3VB* | 95.0 | \$500 |
| Allied Air Enterprises | A96US2V110C20-* | 96.0 | \$500 | American Standard | ADHMB080ACV3VB* | 96.0 | \$500 |
| Allied Air Enterprises | A96US2V135D20-* | 96.0 | \$500 | American Standard | ADHMC100ACV4VB* | 96.0 | \$500 |
| Allied Air Enterprises | A97DSMV070B12S-* | 97.0 | \$700 | American Standard | ADHMD120BCV5VB* | 95.0 | \$500 |
| Allied Air Enterprises | A97DSMV090B16S-* | 97.0 | \$700 | American Standard | AUH1D120A9H51B* | 95.0 | \$500 |
| Allied Air Enterprises | A97DSMV090B20S-* | 97.0 | \$700 | American Standard | AUH2B060A9V3VB* | 97.0 | \$700 |
| Allied Air Enterprises | A97DSMV110B20S-* | 97.0 | \$700 | American Standard | AUH2B080A9V3VB* | 97.0 | \$700 |
| Allied Air Enterprises | A97US2V040B12X-* | 97.5 | \$700 | American Standard | AUH2B080A9V4VB* | 97.0 | \$700 |
| Allied Air Enterprises | A97US2V060B12X-** | 97.5 | \$700 | American Standard | AUH2C100A9V4VB* | 96.7 | \$500 |
| Allied Air Enterprises | A97US2V080C16X-* | 97.5 | \$700 | American Standard | AUH2C100A9V5VB* | 96.7 | \$500 |
| Allied Air Enterprises | A97US2V080C20X-* | 97.5 | \$700 | American Standard | AUH2D120A9V5VB* | 96.7 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|-------------------|-----------------|------|--------|---------------|-------------------|------|--------|
| American Standard | AUHMB060ACV3VB* | 97.3 | \$700 | Arcoaire | F9MXT0801716A | 96.0 | \$500 |
| American Standard | AUHMB080ACV3VB* | 96.7 | \$500 | Arcoaire | F9MXT0802120A | 96.0 | \$500 |
| American Standard | AUHMD120ACV5VB* | 97.0 | \$700 | Arcoaire | F9MXT1002120A | 96.0 | \$500 |
| American Standard | S9V2B040D3PSAA* | 96.0 | \$500 | Arcoaire | F9MXT1202422A | 96.0 | \$500 |
| American Standard | S9V2B040U3PSAA* | 96.0 | \$500 | Armstrong | A95DF2E045B12*-* | 95.0 | \$500 |
| American Standard | S9V2B060D3PSAA* | 96.0 | \$500 | Armstrong | A95DF2E070B16*-* | 95.0 | \$500 |
| American Standard | S9V2B060U3PSAA* | 96.0 | \$500 | Armstrong | A95DF2E090C16*-* | 95.0 | \$500 |
| American Standard | S9V2B060U4PSAA* | 96.0 | \$500 | Armstrong | A95DF2E110C20*-* | 95.0 | \$500 |
| American Standard | S9V2B080D3PSAA* | 96.0 | \$500 | Armstrong | A95DF2V045B12*-* | 95.0 | \$500 |
| American Standard | S9V2B080D4PSAA* | 96.0 | \$500 | Armstrong | A95DF2V070B16*-* | 95.0 | \$500 |
| American Standard | S9V2B080U3PSAA* | 96.0 | \$500 | Armstrong | A95DF2V090C20*-* | 95.0 | \$500 |
| American Standard | S9V2B080U4PSAA* | 96.0 | \$500 | Armstrong | A95DF2V110C20*-* | 95.0 | \$500 |
| American Standard | S9V2C080U5PSAA* | 96.0 | \$500 | Armstrong | A95UH2E045B12*-* | 95.0 | \$500 |
| American Standard | S9V2C100D4PSAA* | 96.0 | \$500 | Armstrong | A95UH2E070B12*-* | 95.0 | \$500 |
| American Standard | S9V2C100D5PSAA* | 96.0 | \$500 | Armstrong | A95UH2E090C16*-* | 95.0 | \$500 |
| American Standard | S9V2C100U4PSAA* | 96.0 | \$500 | Armstrong | A95UH2E110C20*-* | 95.0 | \$500 |
| American Standard | S9V2C100U5PSAA* | 96.0 | \$500 | Armstrong | A95UH2E135D20*-* | 95.0 | \$500 |
| American Standard | S9V2D120D5PSAA* | 96.0 | \$500 | Armstrong | A95UH2V045B12*-* | 95.0 | \$500 |
| American Standard | S9V2D120U5PSAA* | 96.0 | \$500 | Armstrong | A95UH2V070B12*-* | 95.0 | \$500 |
| Ameristar | M952V060BD36AA* | 96.0 | \$500 | Armstrong | A95UH2V090C12*-* | 95.0 | \$500 |
| Ameristar | M952V060BU36AA* | 97.0 | \$700 | Armstrong | A95UH2V090C16*-* | 95.0 | \$500 |
| Ameristar | M952V080BD36AA* | 96.0 | \$500 | Armstrong | A95UH2V090C20*-* | 95.0 | \$500 |
| Ameristar | M952V080BU36AA* | 97.0 | \$700 | Armstrong | A95UH2V110C16*-* | 95.0 | \$500 |
| Ameristar | M952V100CD48AA* | 96.0 | \$500 | Armstrong | A95UH2V110C20*-* | 95.0 | \$500 |
| Ameristar | M952V100CU48AA* | 96.7 | \$500 | Armstrong | A95UH2V135D20*-* | 95.0 | \$500 |
| Ameristar | M952V120DD60AA* | 96.0 | \$500 | Armstrong Air | A95UH1E070B12*-* | 95.0 | \$500 |
| Ameristar | M952V120DU60AA* | 96.7 | \$500 | Armstrong Air | A95UH1E090C16*-* | 95.0 | \$500 |
| Arcoaire | F9MAC0601714A | 97.0 | \$700 | Armstrong Air | A96DS2V045B12S*-* | 96.0 | \$500 |
| Arcoaire | F9MAC0602120A | 98.0 | \$700 | Armstrong Air | A96DS2V070B16S*-* | 96.0 | \$500 |
| Arcoaire | F9MAC0801714A | 97.0 | \$700 | Armstrong Air | A96DS2V090C20S*-* | 96.0 | \$500 |
| Arcoaire | F9MAC0802120A | 97.0 | \$700 | Armstrong Air | A96DS2V110C20S*-* | 96.0 | \$500 |
| Arcoaire | F9MAC1002122A | 97.0 | \$700 | Armstrong Air | A96US2V045B12S*-* | 96.0 | \$500 |
| Arcoaire | F9MAC1202422A | 97.0 | \$700 | Armstrong Air | A96US2V070B12S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE0601714A | 97.0 | \$700 | Armstrong Air | A96US2V090C12S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE0602120A | 98.0 | \$700 | Armstrong Air | A96US2V090C16S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE0801714A | 97.0 | \$700 | Armstrong Air | A96US2V090C20S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE0802120A | 97.0 | \$700 | Armstrong Air | A96US2V110C16S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE1002122A | 97.0 | \$700 | Armstrong Air | A96US2V110C20S*-* | 96.0 | \$500 |
| Arcoaire | F9MAE1202422A | 97.0 | \$700 | Armstrong Air | A96US2V135D20S*-* | 96.0 | \$500 |
| Arcoaire | F9MVE0401410A | 96.0 | \$500 | Armstrong Air | A97DSMV070B12S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE0401712A | 96.0 | \$500 | Armstrong Air | A97DSMV090C16S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE0601412A | 95.0 | \$500 | Armstrong Air | A97DSMV090C20S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE0601714A | 96.0 | \$500 | Armstrong Air | A97DSMV110C20S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE0801716A | 96.0 | \$500 | Armstrong Air | A97USMV070B12S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE0802120A | 96.0 | \$500 | Armstrong Air | A97USMV090C12S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE1002120A | 96.0 | \$500 | Armstrong Air | A97USMV090C16S*-* | 97.0 | \$700 |
| Arcoaire | F9MVE1202422A | 96.0 | \$500 | Armstrong Air | A97USMV090C20S*-* | 97.0 | \$700 |
| Arcoaire | F9MVT0401410A | 96.0 | \$500 | Armstrong Air | A97USMV110C20S*-* | 97.0 | \$700 |
| Arcoaire | F9MVT0601714A | 96.0 | \$500 | Armstrong Air | A97USMV135D20S*-* | 97.0 | \$700 |
| Arcoaire | F9MVT0801716A | 96.0 | \$500 | Broan | FG7MQ060*-VB | 97.0 | \$700 |
| Arcoaire | F9MVT0802120A | 96.0 | \$500 | Broan | FG7MQ080*-VC | 97.2 | \$700 |
| Arcoaire | F9MVT1002120A | 96.0 | \$500 | Broan | FG7MQ100*-VC | 97.4 | \$700 |
| Arcoaire | F9MVT1202422A | 96.0 | \$500 | Broan | FG7MQ120*-VD | 97.0 | \$700 |
| Arcoaire | F9MXE0401712A | 96.0 | \$500 | Broan | FG7TC120*-D* | 95.1 | \$500 |
| Arcoaire | F9MXE0601412A | 95.5 | \$500 | Broan | KG7TC120*-D* | 95.1 | \$500 |
| Arcoaire | F9MXE1002120A* | 96.0 | \$500 | Bryant | 922SA30040E14 | 92.0 | \$500 |
| Arcoaire | F9MXT0401410A | 96.0 | \$500 | Bryant | 922SA36040E17 | 92.0 | \$500 |
| Arcoaire | F9MXT0401712A | 96.0 | \$500 | Bryant | 922SA36060E14 | 92.0 | \$500 |
| Arcoaire | F9MXT0601412A | 95.0 | \$500 | Bryant | 922SA42060E17 | 92.0 | \$500 |
| Arcoaire | F9MXT0601714A | 96.0 | \$500 | Bryant | 922SA48080E17 | 92.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------|------------------|------|--------|--|-----------------|------|--------|
| Bryant | 922SA60080E21 | 92.0 | \$500 | Bryant | 987MA66120V24*D | 95.0 | \$500 |
| Bryant | 922SA60100E21 | 92.0 | \$500 | Bryant | 987MA66120V24A | 97.0 | \$700 |
| Bryant | 922SA60120E24 | 92.0 | \$500 | Bryant (Carrier) | 925SA30024E14 | 96.0 | \$500 |
| Bryant | 925SA30024E14 | 96.0 | \$500 | Bryant (Carrier) | 925SA30026E14*D | 95.0 | \$500 |
| Bryant | 925SA30026E14*D | 95.0 | \$500 | Bryant (Carrier) | 925SA30040E14*D | 95.0 | \$500 |
| Bryant | 925SA30040E14*D | 95.0 | \$500 | Bryant (Carrier) | 925SA30040E14A | 96.0 | \$500 |
| Bryant | 925SA30040E14A | 96.0 | \$500 | Bryant (Carrier) | 925SA36040E17*D | 95.0 | \$500 |
| Bryant | 925SA36040E17 | 96.5 | \$500 | Bryant (Carrier) | 925SA36040E17A | 96.0 | \$500 |
| Bryant | 925SA36040E17*D | 95.0 | \$500 | Bryant (Carrier) | 925SA42060E17*D | 95.0 | \$500 |
| Bryant | 925SA36060E14 | 95.5 | \$500 | Bryant (Carrier) | 925SA42060E17A | 96.0 | \$500 |
| Bryant | 925SA42060E17*D | 95.0 | \$500 | Bryant (Carrier) | 925SA48080E17 | 96.0 | \$500 |
| Bryant | 925SA42060E17A | 96.0 | \$500 | Bryant (Carrier) | 925SA60080E21 | 96.0 | \$500 |
| Bryant | 925SA48080E17 | 96.0 | \$500 | Bryant (Carrier) | 925SA60080E21*D | 95.0 | \$500 |
| Bryant | 925SA60080E21 | 96.0 | \$500 | Bryant (Carrier) | 925SA60100E21 | 96.0 | \$500 |
| Bryant | 925SA60080E21*D | 95.0 | \$500 | Bryant (Carrier) | 926TA30040V14 | 97.0 | \$700 |
| Bryant | 925SA60100E21 | 96.0 | \$500 | Bryant (Carrier) | 926TA30040V14*D | 95.0 | \$500 |
| Bryant | 925TA30040E14A | 96.2 | \$500 | Bryant (Carrier) | 926TA36040V17 | 96.0 | \$500 |
| Bryant | 925TA36040E17 | 96.0 | \$500 | Bryant (Carrier) | 926TA36040V17*D | 95.0 | \$500 |
| Bryant | 925TA36060E14 | 95.0 | \$500 | Bryant (Carrier) | 926TA36060V14 | 95.0 | \$500 |
| Bryant | 925TA42060E17A | 96.2 | \$500 | Bryant (Carrier) | 926TA36060V14*D | 95.0 | \$500 |
| Bryant | 925TA48080E17A | 96.2 | \$500 | Bryant (Carrier) | 926TA42060V17 | 96.0 | \$500 |
| Bryant | 925TA60080E21 | 96.2 | \$500 | Bryant (Carrier) | 926TA42060V17*D | 95.0 | \$500 |
| Bryant | 925TA60100E21 | 96.1 | \$500 | Bryant (Carrier) | 926TA48080V17 | 96.0 | \$500 |
| Bryant | 925TA66120E24A | 96.2 | \$500 | Bryant (Carrier) | 926TA48080V17*D | 95.0 | \$500 |
| Bryant | 926TA30040V14 | 97.0 | \$700 | Bryant (Carrier) | 926TA60080V21 | 97.0 | \$700 |
| Bryant | 926TA30040V14*D | 95.0 | \$500 | Bryant (Carrier) | 926TA60080V21*D | 95.0 | \$500 |
| Bryant | 926TA36040V17 | 96.0 | \$500 | Bryant (Carrier) | 926TA60100V21 | 96.0 | \$500 |
| Bryant | 926TA36040V17*D | 95.0 | \$500 | Bryant (Carrier) | 926TA60100V21*D | 95.0 | \$500 |
| Bryant | 926TA36060V14 | 95.0 | \$500 | Bryant (Carrier) | 926TA66120V24 | 97.0 | \$700 |
| Bryant | 926TA36060V14*D | 95.0 | \$500 | Bryant (Carrier) | 926TA66120V24*D | 95.0 | \$500 |
| Bryant | 926TA42060V17 | 96.0 | \$500 | Bryant (Carrier) | 986TB42060V17 | 96.0 | \$500 |
| Bryant | 926TA42060V17*D | 95.0 | \$500 | Bryant (Carrier) | 986TB42060V17*D | 95.0 | \$500 |
| Bryant | 926TA48080V17 | 96.0 | \$500 | Bryant (Carrier) | 986TB42080V17 | 96.0 | \$500 |
| Bryant | 926TA48080V17*D | 95.0 | \$500 | Bryant (Carrier) | 986TB42080V17*D | 95.0 | \$500 |
| Bryant | 926TA60080V21 | 97.0 | \$700 | Bryant (Carrier) | 986TB60080V21 | 97.0 | \$700 |
| Bryant | 926TA60080V21*D | 95.0 | \$500 | Bryant (Carrier) | 986TB60080V21*D | 95.0 | \$500 |
| Bryant | 926TA60100V21 | 96.0 | \$500 | Bryant (Carrier) | 986TB66100V21 | 96.0 | \$500 |
| Bryant | 926TA60100V21*D | 95.0 | \$500 | Bryant (Carrier) | 986TB66100V21*D | 95.0 | \$500 |
| Bryant | 926TA66120V24 | 97.0 | \$700 | Bryant (Carrier) | 986TB66120V24 | 97.0 | \$700 |
| Bryant | 926TA66120V24*D | 95.0 | \$500 | Bryant (Carrier) | 986TB66120V24*D | 95.0 | \$500 |
| Bryant | 986TA42060V17A-A | 96.7 | \$500 | Bryant (Carrier) | 987MA42060V17*D | 95.0 | \$500 |
| Bryant | 986TB42060V17 | 96.0 | \$500 | Bryant (Carrier) | 987MA42060V17A | 97.0 | \$700 |
| Bryant | 986TB42060V17*D | 95.0 | \$500 | Bryant (Carrier) | 987MA42080V17*D | 95.0 | \$500 |
| Bryant | 986TB42080V17 | 96.0 | \$500 | Bryant (Carrier) | 987MA42080V17A | 97.0 | \$700 |
| Bryant | 986TB42080V17*D | 95.0 | \$500 | Bryant (Carrier) | 987MA60060V21 | 98.0 | \$700 |
| Bryant | 986TB60080V21 | 97.0 | \$700 | Bryant (Carrier) | 987MA60060V21*D | 97.0 | \$700 |
| Bryant | 986TB60080V21*D | 95.0 | \$500 | Bryant (Carrier) | 987MA60080V21 | 97.0 | \$700 |
| Bryant | 986TB66100V21 | 96.0 | \$500 | Bryant (Carrier) | 987MA60080V21*D | 95.0 | \$500 |
| Bryant | 986TB66100V21*D | 95.0 | \$500 | Bryant (Carrier) | 987MA66100V21 | 97.0 | \$700 |
| Bryant | 986TB66120V24 | 97.0 | \$700 | Bryant (Carrier) | 987MA66120V24*D | 95.0 | \$500 |
| Bryant | 986TB66120V24*D | 95.0 | \$500 | Bryant (Carrier) | 987MA66120V24A | 97.0 | \$700 |
| Bryant | 987MA42060V17*D | 95.0 | \$500 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA30026E14 | 96.0 | \$500 |
| Bryant | 987MA42060V17A | 97.0 | \$700 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA36060E14*D | 95.0 | \$500 |
| Bryant | 987MA42080V17*D | 95.0 | \$500 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA48080E17*D | 95.0 | \$500 |
| Bryant | 987MA42080V17A | 97.0 | \$700 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA60100E21*D | 95.0 | \$500 |
| Bryant | 987MA60060V21 | 98.0 | \$700 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA66120E24*D | 95.0 | \$500 |
| Bryant | 987MA60060V21*D | 97.0 | \$700 | Bryant Heating and Cooling Systems (Carrier Corporation) | 925SA66120E24A | 96.2 | \$500 |
| Bryant | 987MA60080V21 | 97.0 | \$700 | | | | |
| Bryant | 987MA60080V21*D | 95.0 | \$500 | | | | |
| Bryant | 987MA66100V21 | 97.0 | \$700 | | | | |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--|--------------------|------|--------|---------------------|--------------------|------|--------|
| Bryant Heating and Cooling Systems (Carrier Corporation) | 987MA66100V21*D | 95.0 | \$500 | Carrier | 59TP6A060E14--12*D | 95.0 | \$500 |
| Carrier | 59MN7A060V17--14 | 97.0 | \$700 | Carrier | 59TP6A060E17--14 | 96.0 | \$500 |
| Carrier | 59MN7A060V17--14*D | 95.0 | \$500 | Carrier | 59TP6A060E17--14*D | 95.0 | \$500 |
| Carrier | 59MN7A060V21--20 | 99.0 | \$700 | Carrier | 59TP6A080E17--16 | 96.0 | \$500 |
| Carrier | 59MN7A060V21--20*D | 97.0 | \$700 | Carrier | 59TP6A080E17--16*D | 95.0 | \$500 |
| Carrier | 59MN7A080V17--14 | 97.0 | \$700 | Carrier | 59TP6A080E21--20 | 97.0 | \$700 |
| Carrier | 59MN7A080V17--14*D | 95.0 | \$500 | Carrier | 59TP6A080E21--20*D | 95.0 | \$500 |
| Carrier | 59MN7A080V21--20 | 97.0 | \$700 | Carrier | 59TP6A100E21--20 | 96.0 | \$500 |
| Carrier | 59MN7A080V21--20*D | 95.0 | \$500 | Carrier | 59TP6A100E21--20*D | 95.0 | \$500 |
| Carrier | 59MN7A100V21--22 | 97.0 | \$700 | Carrier | 59TP6A120E24--22 | 97.0 | \$700 |
| Carrier | 59MN7A120V24--22 | 97.0 | \$700 | Carrier | 59TP6A120E24--22*D | 95.0 | \$500 |
| Carrier | 59MN7A120V24--22*D | 95.0 | \$500 | Carrier | A2X95-030040 | 96.2 | \$500 |
| Carrier | 59SP2A040E14--10 | 92.0 | \$500 | Carrier | A2X95-036040E17 | 96.0 | \$500 |
| Carrier | 59SP2A040E17--12 | 92.0 | \$500 | Carrier | A2X95-036060E14 | 95.0 | \$500 |
| Carrier | 59SP2A060E17--14 | 92.0 | \$500 | Carrier | A2X95-048060 | 96.2 | \$500 |
| Carrier | 59SP2A080E17--16 | 92.0 | \$500 | Carrier | A2X95-048080 | 96.2 | \$500 |
| Carrier | 59SP2A080E21--20 | 92.0 | \$500 | Carrier | A2X95-060080 | 96.2 | \$500 |
| Carrier | 59SP2A100E21--20 | 96.0 | \$500 | Carrier | A2X95-060080** | 95.5 | \$500 |
| Carrier | 59SP2A120E24--20 | 96.0 | \$500 | Carrier | A2X95-060100 | 96.1 | \$500 |
| Carrier | 59SP5A026E14--10 | 96.0 | \$500 | Carrier | A2X95-060100** | 95.5 | \$500 |
| Carrier | 59SP5A026E14--10*D | 95.0 | \$500 | Carrier | A2X95-066120 | 96.2 | \$500 |
| Carrier | 59SP5A040E14--10 | 97.0 | \$700 | Carrier | A2X95-30040 | 95.5 | \$500 |
| Carrier | 59SP5A040E14--10* | 96.5 | \$500 | Carrier | A2X95-48060 | 95.5 | \$500 |
| Carrier | 59SP5A040E14--10*D | 95.0 | \$500 | Carrier | A2X95-48080 | 95.5 | \$500 |
| Carrier | 59SP5A040E17--12 | 97.0 | \$700 | Carrier | A2X95-66120 | 95.5 | \$500 |
| Carrier | 59SP5A040E17--12*D | 95.0 | \$500 | Carrier | AMV098-066120 | 97.0 | \$700 |
| Carrier | 59SP5A060E14--12 | 95.5 | \$500 | Carrier | AMV98-042060 | 97.0 | \$700 |
| Carrier | 59SP5A060E17--14 | 97.0 | \$700 | Carrier | AMV98-042080 | 97.0 | \$700 |
| Carrier | 59SP5A060E17--14* | 96.5 | \$500 | Carrier | AMV98-060060 | 98.3 | \$700 |
| Carrier | 59SP5A060E17--14*D | 95.0 | \$500 | Carrier | AMV98-060080 | 97.0 | \$700 |
| Carrier | 59SP5A080E17--16 | 97.0 | \$700 | Carrier | AMV98-066100* | 97.0 | \$700 |
| Carrier | 59SP5A080E17--16* | 96.5 | \$500 | Carrier | PG95XAT30040A | 95.0 | \$500 |
| Carrier | 59SP5A080E21--20 | 97.0 | \$700 | Carrier | PG95XAT30040A*D | 95.0 | \$500 |
| Carrier | 59SP5A080E21--20* | 96.5 | \$500 | Carrier | PG95XAT36040B* | 96.0 | \$500 |
| Carrier | 59SP5A080E21--20*D | 95.0 | \$500 | Carrier | PG95XAT36040B**D | 95.0 | \$500 |
| Carrier | 59SP5A100E21--20* | 96.3 | \$500 | Carrier | PG95XAT36060A* | 95.0 | \$500 |
| Carrier | 59TN6A060V17--14 | 96.0 | \$500 | Carrier | PG95XAT36060A**D | 95.0 | \$500 |
| Carrier | 59TN6A060V17--14*D | 95.0 | \$500 | Carrier | PG95XAT42060B | 95.0 | \$500 |
| Carrier | 59TN6A080V17--14 | 96.0 | \$500 | Carrier | PG95XAT42060B*D | 95.0 | \$500 |
| Carrier | 59TN6A080V17--14*D | 95.0 | \$500 | Carrier | PG95XAT48080B | 95.0 | \$500 |
| Carrier | 59TN6A080V21--20 | 97.0 | \$700 | Carrier | PG95XAT48080B*D | 95.0 | \$500 |
| Carrier | 59TN6A080V21--20*D | 95.0 | \$500 | Carrier | PG95XAT60080C | 95.0 | \$500 |
| Carrier | 59TN6A100V21--22 | 96.0 | \$500 | Carrier | PG95XAT60080C*D | 95.0 | \$500 |
| Carrier | 59TN6A100V21--22*D | 95.0 | \$500 | Carrier | PG95XAT60100C | 95.0 | \$500 |
| Carrier | 59TN6A120V24--22 | 97.0 | \$700 | Carrier | PG95XAT60100C*D | 95.0 | \$500 |
| Carrier | 59TN6A120V24--22*D | 95.0 | \$500 | Carrier | PG95XAT66120D | 95.0 | \$500 |
| Carrier | 59TP5A040E14--10 | 96.5 | \$500 | Carrier | PG95XAT66120D*D | 95.0 | \$500 |
| Carrier | 59TP5A040E17--12 | 96.0 | \$500 | Carrier | PG96VAT30040A | 96.0 | \$500 |
| Carrier | 59TP5A060E14--12 | 95.0 | \$500 | Carrier | PG96VAT42060B | 96.0 | \$500 |
| Carrier | 59TP5A060E17--14 | 96.3 | \$500 | Carrier | PG96VAT48080B | 96.0 | \$500 |
| Carrier | 59TP5A080E17--16 | 96.2 | \$500 | Carrier | PG96VAT60080C | 96.0 | \$500 |
| Carrier | 59TP5A080E21--20 | 96.7 | \$500 | Carrier | PG96VAT60100C | 96.0 | \$500 |
| Carrier | 59TP5A100E21--20 | 96.1 | \$500 | Carrier | PG96VAT66120D | 96.0 | \$500 |
| Carrier | 59TP5A120E24--22 | 96.7 | \$500 | Carrier Corporation | 59MN7A100V21--22*D | 95.0 | \$500 |
| Carrier | 59TP6A040E14--10 | 97.0 | \$700 | Carrier Corporation | 59SP5A026E14--10 | 96.0 | \$500 |
| Carrier | 59TP6A040E14--10*D | 95.0 | \$500 | Carrier Corporation | 59TP6A040E14--10 | 97.0 | \$700 |
| Carrier | 59TP6A040E17--12 | 96.0 | \$500 | Carrier Corporation | 59TP6A040E17--12 | 96.0 | \$500 |
| Carrier | 59TP6A040E17--12*D | 95.0 | \$500 | Carrier Corporation | 59TP6A060E14--12 | 95.0 | \$500 |
| Carrier | 59TP6A060E14--12 | 95.0 | \$500 | Carrier Corporation | 59TP6A060E17--14 | 96.0 | \$500 |
| Carrier | 59TP6A060E17--16 | 96.0 | \$500 | Carrier Corporation | 59TP6A080E17--16 | 96.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|---------------------|------------------|------|--------|--------------|-----------------|------|--------|
| Carrier Corporation | 59TP6A080E21--20 | 97.0 | \$700 | Concord | 95G2DF045BE12* | 95.0 | \$500 |
| Carrier Corporation | 59TP6A100E21--20 | 96.0 | \$500 | Concord | 95G2DF070BE16* | 95.0 | \$500 |
| Carrier Corporation | 59TP6A120E24--22 | 97.0 | \$700 | Concord | 95G2DF090CE16* | 95.0 | \$500 |
| Century | GUH95T120D5XE | 95.1 | \$500 | Concord | 95G2DF110CE20* | 95.0 | \$500 |
| Coleman | CP9C060B12MP12 | 97.5 | \$700 | Concord | 95G2UH045BE12* | 95.0 | \$500 |
| Coleman | CP9C060B12MP12CA | 97.5 | \$700 | Concord | 95G2UH045BV12-* | 95.0 | \$500 |
| Coleman | CP9C080B12MP12 | 97.5 | \$700 | Concord | 95G2UH070BE12* | 95.0 | \$500 |
| Coleman | CP9C080B12MP12CA | 97.5 | \$700 | Concord | 95G2UH070BV12-* | 95.0 | \$500 |
| Coleman | CP9C080C16MP12 | 97.7 | \$700 | Concord | 95G2UH090CE16* | 95.0 | \$500 |
| Coleman | CP9C080C16MP12CA | 97.7 | \$700 | Concord | 95G2UH090CV12-* | 95.0 | \$500 |
| Coleman | CP9C100C16MP12 | 97.7 | \$700 | Concord | 95G2UH090CV20-* | 95.0 | \$500 |
| Coleman | CP9C100C16MP12CA | 97.7 | \$700 | Concord | 95G2UH110CE20* | 95.0 | \$500 |
| Coleman | CP9C100C20MP12 | 97.7 | \$700 | Concord | 95G2UH110CV20-* | 95.0 | \$500 |
| Coleman | CP9C100C20MP12CA | 97.7 | \$700 | Concord | 95G2UH135DE20* | 95.0 | \$500 |
| Coleman | CP9C120D20MP12 | 98.0 | \$700 | Concord | 95G2UH135DV20-* | 95.0 | \$500 |
| Coleman | CP9C120D20MP12CA | 98.0 | \$700 | Continental | CPV040T2B | 96.0 | \$500 |
| Coleman | MG9S060B12MP11B | 95.5 | \$500 | Continental | CPV060T3B | 96.0 | \$500 |
| Coleman | TP9C120D20MP12 | 98.0 | \$700 | Continental | CPV080T3B | 96.0 | \$500 |
| Comfort-Aire | GUH95T120D5XE | 95.1 | \$500 | Continental | CPV080T4B | 96.0 | \$500 |
| Comfortmaker | G9MAC0601714A | 97.0 | \$700 | Continental | CPV100T5B | 96.0 | \$500 |
| Comfortmaker | G9MAC0602120A | 98.0 | \$700 | Continental | CPV120T5B | 96.0 | \$500 |
| Comfortmaker | G9MAC0801714A | 97.0 | \$700 | Continental | CPX030S2B | 95.0 | \$500 |
| Comfortmaker | G9MAC0802120A | 97.0 | \$700 | Continental | CPX040S2B | 95.0 | \$500 |
| Comfortmaker | G9MAC1002122A | 97.0 | \$700 | Continental | CPX060S3B | 95.0 | \$500 |
| Comfortmaker | G9MAC1202422A | 97.0 | \$700 | Continental | CPX080S3B | 95.0 | \$500 |
| Comfortmaker | G9MAE0601714A | 97.0 | \$700 | Continental | CPX080S4B | 95.0 | \$500 |
| Comfortmaker | G9MAE0602120A | 98.0 | \$700 | Continental | CPX100S5B | 95.0 | \$500 |
| Comfortmaker | G9MAE0801714A | 97.0 | \$700 | Continental | CPX120AS5A | 95.0 | \$500 |
| Comfortmaker | G9MAE0802120A | 97.0 | \$700 | Continental | CPX120S5A | 95.0 | \$500 |
| Comfortmaker | G9MAE1002122A | 97.0 | \$700 | Continental | CPX120S5B | 95.0 | \$500 |
| Comfortmaker | G9MAE1202422A | 97.0 | \$700 | Continental | CTV040T2B | 97.0 | \$700 |
| Comfortmaker | G9MVE0401410A | 96.0 | \$500 | Continental | CTV060T3B | 97.0 | \$700 |
| Comfortmaker | G9MVE0401712A | 96.0 | \$500 | Continental | CTV080T3B | 97.0 | \$700 |
| Comfortmaker | G9MVE0601412A | 95.0 | \$500 | Continental | CTV080T4B | 97.0 | \$700 |
| Comfortmaker | G9MVE0601714A | 96.0 | \$500 | Continental | CTV100T5B | 97.0 | \$700 |
| Comfortmaker | G9MVE0801716A | 96.0 | \$500 | Continental | CTV120T5B | 97.0 | \$700 |
| Comfortmaker | G9MVE0802120A | 96.0 | \$500 | Daikin | DC96MC0604CX | 96.1 | \$500 |
| Comfortmaker | G9MVE1002116A | 96.0 | \$500 | Daikin | DC96MC0805DX | 96.1 | \$500 |
| Comfortmaker | G9MVE1002120A | 96.0 | \$500 | Daikin | DC96MC1005DX | 96.1 | \$500 |
| Comfortmaker | G9MVE1202422A | 96.0 | \$500 | Daikin | DC96VC0403BN | 96.1 | \$500 |
| Comfortmaker | G9MVT0401410A | 96.0 | \$500 | Daikin | DC96VC0603BN | 96.1 | \$500 |
| Comfortmaker | G9MVT0601714A | 96.0 | \$500 | Daikin | DC96VC0714CX | 95.0 | \$500 |
| Comfortmaker | G9MVT0801716A | 96.0 | \$500 | Daikin | DC96VC0804CN | 96.1 | \$500 |
| Comfortmaker | G9MVT0802120A | 96.0 | \$500 | Daikin | DC96VC0915DX | 95.0 | \$500 |
| Comfortmaker | G9MVT1002120A | 96.0 | \$500 | Daikin | DC96VC1005CN | 96.1 | \$500 |
| Comfortmaker | G9MVT1202422A | 96.0 | \$500 | Daikin | DC96VC1205DN | 96.1 | \$500 |
| Comfortmaker | G9MXE0401410A | 96.0 | \$500 | Daikin | DC97MC0603BN | 97.0 | \$700 |
| Comfortmaker | G9MXE0401712A* | 96.0 | \$500 | Daikin | DC97MC0803BN | 97.0 | \$700 |
| Comfortmaker | G9MXE0601412A* | 95.5 | \$500 | Daikin | DC97MC0804CN | 97.0 | \$700 |
| Comfortmaker | G9MXE0601714A | 96.0 | \$500 | Daikin | DC97MC1005CN | 97.0 | \$700 |
| Comfortmaker | G9MXE0801716A | 96.0 | \$500 | Daikin | DM96MC0603BX | 96.1 | \$500 |
| Comfortmaker | G9MXE0802120A | 96.0 | \$500 | Daikin | DM96MC0805CX | 96.1 | \$500 |
| Comfortmaker | G9MXT0401410A | 96.0 | \$500 | Daikin | DM96MC1005DX | 96.1 | \$500 |
| Comfortmaker | G9MXT0601714A | 96.0 | \$500 | Daikin | DM96MC1155DX | 96.1 | \$500 |
| Comfortmaker | G9MXT0801716A | 96.0 | \$500 | Daikin | DM96VC0403BN | 96.1 | \$500 |
| Comfortmaker | G9MXT0802120A | 96.0 | \$500 | Daikin | DM96VC0453BX | 96.1 | \$500 |
| Comfortmaker | G9MXT1002120A | 96.0 | \$500 | Daikin | DM96VC0603BN | 96.1 | \$500 |
| Comfortmaker | G9MXT1202422A | 96.0 | \$500 | Daikin | DM96VC0704CX | 96.1 | \$500 |
| Concord | 95G1UH070BE12-* | 95.0 | \$500 | Daikin | DM96VC0803BN | 96.1 | \$500 |
| Concord | 95G1UH090CE16-* | 95.0 | \$500 | Daikin | DM96VC0804CN | 96.1 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------|----------------|------|--------|-------------------------|------------------|------|--------|
| Daikin | DM96VC0905CX | 96.1 | \$500 | Dettson | C120-2-V* | 95.7 | \$500 |
| Daikin | DM96VC0905DX | 96.1 | \$500 | Dettson | C120-M-V | 97.0 | \$700 |
| Daikin | DM96VC1005CN | 96.1 | \$500 | Dettson | C120-M-V* | 97.0 | \$700 |
| Daikin | DM96VC1155DX | 96.1 | \$500 | Dettson | C30-M-V | 95.3 | \$500 |
| Daikin | DM96VC1205DN | 96.1 | \$500 | Dettson | C30-M-V* | 95.3 | \$500 |
| Daikin | DM96VE0302BN | 96.1 | \$500 | Dettson | C45-2-V | 95.0 | \$500 |
| Daikin | DM96VE0603BN | 96.1 | \$500 | Dettson | C45-2-V* | 95.0 | \$500 |
| Daikin | DM96VE0803BN | 96.1 | \$500 | Dettson | C45-M-V | 96.0 | \$500 |
| Daikin | DM97MC1005CN | 97.0 | \$700 | Dettson | C45-M-V* | 95.7 | \$500 |
| Daikin | DM97MC1205DN | 97.0 | \$700 | Dettson | C60-2-V | 95.0 | \$500 |
| Day & Night | G9MAC0601714A | 97.0 | \$700 | Dettson | C60-2-V* | 95.1 | \$500 |
| Day & Night | G9MAC0602120A | 98.0 | \$700 | Dettson | C60-M-V | 96.0 | \$500 |
| Day & Night | G9MAC0801714A | 97.0 | \$700 | Dettson | C60-M-V* | 96.0 | \$500 |
| Day & Night | G9MAC0802120A | 97.0 | \$700 | Dettson | C75-2-V | 95.0 | \$500 |
| Day & Night | G9MAC1002122A | 97.0 | \$700 | Dettson | C75-2-V* | 95.3 | \$500 |
| Day & Night | G9MAC1202422A | 97.0 | \$700 | Dettson | C75-M-V | 96.0 | \$500 |
| Day & Night | G9MAE0601714A | 97.0 | \$700 | Dettson | C75-M-V* | 96.0 | \$500 |
| Day & Night | G9MAE0602120A | 98.0 | \$700 | Dettson Industries Inc. | C15-M-V | 97.3 | \$700 |
| Day & Night | G9MAE0801714A | 97.0 | \$700 | Ducane | 95G1UH070BE12-* | 95.0 | \$500 |
| Day & Night | G9MAE0802120A | 97.0 | \$700 | Ducane | 95G1UH090CE16-* | 95.0 | \$500 |
| Day & Night | G9MAE1002122A | 97.0 | \$700 | Ducane | 95G2DF045BE12* | 95.0 | \$500 |
| Day & Night | G9MAE1202422A | 97.0 | \$700 | Ducane | 95G2DF070BE16* | 95.0 | \$500 |
| Day & Night | G9MVE0401410A | 96.0 | \$500 | Ducane | 95G2DF090CE16* | 95.0 | \$500 |
| Day & Night | G9MVE0401712A | 96.0 | \$500 | Ducane | 95G2DF110CE20* | 95.0 | \$500 |
| Day & Night | G9MVE0601412A | 95.0 | \$500 | Ducane | 95G2UH045BE12* | 95.0 | \$500 |
| Day & Night | G9MVE0601714A | 96.0 | \$500 | Ducane | 95G2UH045BV12-* | 95.0 | \$500 |
| Day & Night | G9MVE0801716A | 96.0 | \$500 | Ducane | 95G2UH070BE12* | 95.0 | \$500 |
| Day & Night | G9MVE0802120A | 96.0 | \$500 | Ducane | 95G2UH070BV12-* | 95.0 | \$500 |
| Day & Night | G9MVE1002116A | 96.0 | \$500 | Ducane | 95G2UH090CE16* | 95.0 | \$500 |
| Day & Night | G9MVE1002120A | 96.0 | \$500 | Ducane | 95G2UH090CV12-* | 95.0 | \$500 |
| Day & Night | G9MVE1202422A | 96.0 | \$500 | Ducane | 95G2UH090CV20-* | 95.0 | \$500 |
| Day & Night | G9MVT0401410A | 96.0 | \$500 | Ducane | 95G2UH110CE20* | 95.0 | \$500 |
| Day & Night | G9MVT0601714A | 96.0 | \$500 | Ducane | 95G2UH110CV20-* | 95.0 | \$500 |
| Day & Night | G9MVT0801716A | 96.0 | \$500 | Ducane | 95G2UH135DE20* | 95.0 | \$500 |
| Day & Night | G9MVT0802120A | 96.0 | \$500 | Ducane | 95G2UH135DV20-* | 95.0 | \$500 |
| Day & Night | G9MVT1002120A | 96.0 | \$500 | DuroGuard | D95TA0601317MSA | 95.0 | \$500 |
| Day & Night | G9MVT1202422A | 96.0 | \$500 | DuroGuard | D95TA1151524MSA | 95.0 | \$500 |
| Day & Night | G9MXE0401410A | 96.0 | \$500 | DuroGuard | D96VA0402317MSA | 96.0 | \$500 |
| Day & Night | G9MXE0401712A* | 96.0 | \$500 | DuroGuard | D96VA0602317MSA | 96.0 | \$500 |
| Day & Night | G9MXE0601412A* | 95.5 | \$500 | DuroGuard | D96VA0702317MSA | 96.0 | \$500 |
| Day & Night | G9MXE0601714A | 96.0 | \$500 | DuroGuard | D96VA0852521MSA | 96.0 | \$500 |
| Day & Night | G9MXE0801716A | 96.0 | \$500 | DuroGuard | D96VA1002521MSA | 96.0 | \$500 |
| Day & Night | G9MXE0802120A | 96.0 | \$500 | Elect-Aire | KG7TC120*-D* | 95.1 | \$500 |
| Day & Night | G9MXT0401410A | 96.0 | \$500 | Evcon | RGF19060BE12MP12 | 95.0 | \$500 |
| Day & Night | G9MXT0601714A | 96.0 | \$500 | Evcon | RGF19080BE12MP12 | 95.0 | \$500 |
| Day & Night | G9MXT0801716A | 96.0 | \$500 | Evcon | RGF19080CE16MP12 | 95.0 | \$500 |
| Day & Night | G9MXT0802120A | 96.0 | \$500 | Evcon | RGF19100CE16MP12 | 95.0 | \$500 |
| Day & Night | G9MXT1002120A | 96.0 | \$500 | Evcon | RGF19100CE20MP12 | 95.0 | \$500 |
| Day & Night | G9MXT1202422A | 96.0 | \$500 | Evcon | RGF19120DE20MP12 | 95.0 | \$500 |
| Dettson | 60-M-V* | 96.0 | \$500 | Evcon | TP9C060B12MP12CA | 97.5 | \$700 |
| Dettson | 75-M-V* | 95.7 | \$500 | Evcon | TP9C080B12MP12CA | 97.5 | \$700 |
| Dettson | C030-M-V* | 95.3 | \$500 | Evcon | TP9C080C16MP12CA | 97.7 | \$700 |
| Dettson | C045-2-V | 95.1 | \$500 | Evcon | TP9C100C16MP12CA | 97.7 | \$700 |
| Dettson | C060-2-V | 95.1 | \$500 | Evcon | TP9C100C20MP12CA | 97.7 | \$700 |
| Dettson | C075-2-V | 96.3 | \$500 | Evcon | TP9C120D20MP12 | 98.0 | \$700 |
| Dettson | C105-2-V | 95.0 | \$500 | Evcon | TP9C120D20MP12CA | 98.0 | \$700 |
| Dettson | C105-2-V* | 95.0 | \$500 | Fraser - Johnston | TP9C060B12MP12CA | 97.5 | \$700 |
| Dettson | C105-M-V | 96.0 | \$500 | Fraser - Johnston | TP9C080B12MP12CA | 97.5 | \$700 |
| Dettson | C105-M-V* | 96.0 | \$500 | Fraser - Johnston | TP9C080C16MP12CA | 97.7 | \$700 |
| Dettson | C120-2-V | 96.0 | \$500 | Fraser - Johnston | TP9C100C16MP12CA | 97.7 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|-------------------------------------|--------------|------|--------|-------------------------------------|------------------|------|--------|
| Company L.P. | | | | Goodman Manufacturing Company, L.P. | AMVM971005CN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | DC96VE0403BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | AMVM971205DN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | DC96VE0603BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC96VC0403BN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | DC96VE0803BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC96VC0603BN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | DC96VE1005CN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC96VC0804CN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | DM96VE0603AN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC96VC1005CN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | GCEC960403BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC96VC1205DN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | GCEC960603BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC97MC0603BN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | GCEC960803BN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC97MC0803BN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | GCEC961005CN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC97MC0804CN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | GMEC960303AN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DC97MC1005CN | 97.0 | \$700 |
| Goodman Manufacturing Company L.P. | GMEC960403AN | 96.1 | \$500 | Goodman Manufacturing Company, L.P. | DM96VE0603BN | 96.0 | \$500 |
| Goodman Manufacturing Company L.P. | GMEC960603AN | 96.1 | \$500 | Grandaire | KG7TC120*-D* | 95.1 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVC960403BN | 96.0 | \$500 | Great Lakes | 95G1UH070BE12-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVC960603BN | 96.0 | \$500 | Great Lakes | 95G1UH090CE16-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVC960804CN | 96.0 | \$500 | Great Lakes | 95G2DF045BE12* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVC961005CN | 96.0 | \$500 | Great Lakes | 95G2DF070BE16* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVC961205DN | 96.0 | \$500 | Great Lakes | 95G2DF090CE16* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVM970603BN | 97.0 | \$700 | Great Lakes | 95G2DF110CE20* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVM970803BN | 97.0 | \$700 | Great Lakes | 95G2UH045BE12* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVM970804CN | 97.0 | \$700 | Great Lakes | 95G2UH045BV12-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | ACVM971005CN | 97.0 | \$700 | Great Lakes | 95G2UH070BE12* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC960302BN | 96.0 | \$500 | Great Lakes | 95G2UH070BV12-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC960402BN | 96.0 | \$500 | Great Lakes | 95G2UH090CE16* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC960603BN | 96.0 | \$500 | Great Lakes | 95G2UH090CV12-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC960803BN | 96.0 | \$500 | Great Lakes | 95G2UH090CV20-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC960804CN | 96.0 | \$500 | Great Lakes | 95G2UH110CE20* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC961004CN | 96.0 | \$500 | Great Lakes | 95G2UH110CV20-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC961005CN | 96.0 | \$500 | Great Lakes | 95G2UH135DE20* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMEC961205DN | 96.0 | \$500 | Great Lakes | 95G2UH135DV20-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960403BN | 96.0 | \$500 | Great Lakes | A95DF2V045B12*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960603BN | 96.0 | \$500 | Great Lakes | A95DF2V070B16*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960803BN | 96.0 | \$500 | Great Lakes | A95DF2V090C20*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960804CN | 96.0 | \$500 | Great Lakes | A95DF2V110C20*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961005CN | 96.0 | \$500 | Great Lakes | A95UH1E070B12-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961005DN | 96.0 | \$500 | Great Lakes | A95UH1E090C16-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961205DN | 96.0 | \$500 | Great Lakes | A95UH2E045B12*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960403BN | 96.0 | \$500 | Great Lakes | A95UH2V045B12*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960603BN | 96.0 | \$500 | Great Lakes | A95UH2V070B12*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960803BN | 96.0 | \$500 | Great Lakes | A95UH2V090C12*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC960804CN | 96.0 | \$500 | Great Lakes | A95UH2V090C16*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961005CN | 96.0 | \$500 | Great Lakes | A95UH2V090C20*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961005DN | 96.0 | \$500 | Great Lakes | A95UH2V110C16*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVC961205DN | 96.0 | \$500 | Great Lakes | A95UH2V110C20*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVM970603BN | 98.0 | \$700 | Great Lakes | A95UH2V135D20*-* | 95.0 | \$500 |
| Goodman Manufacturing Company, L.P. | AMVM970803BN | 97.0 | \$700 | Great Lakes | A97DSMV070B12S-* | 97.0 | \$700 |
| Goodman Manufacturing Company, L.P. | AMVM970804CN | 98.0 | \$700 | Great Lakes | A97DSMV090C16S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97DSMV090C20S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97DSMV110C20S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97USMV070B12S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97USMV090C12S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97USMV090C16S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97USMV090C20S-* | 97.0 | \$700 |
| | | | | Great Lakes | A97USMV110C20S-* | 97.0 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|----------------------|------------------|------|--------|--------------------------------------|----------------|------|--------|
| Great Lakes | A97USMV135D20S-* | 97.0 | \$700 | Heil | G9MXE0801716A | 96.0 | \$500 |
| Guardian | RGF19060BE12MP12 | 95.0 | \$500 | Heil | G9MXE0802120A | 96.0 | \$500 |
| Guardian | RGF19080BE12MP12 | 95.0 | \$500 | Heil | G9MXT0401410A | 96.0 | \$500 |
| Guardian | RGF19080CE16MP12 | 95.0 | \$500 | Heil | G9MXT0601714A | 96.0 | \$500 |
| Guardian | RGF19100CE16MP12 | 95.0 | \$500 | Heil | G9MXT0801716A | 96.0 | \$500 |
| Guardian | RGF19100CE20MP12 | 95.0 | \$500 | Heil | G9MXT0802120A | 96.0 | \$500 |
| Guardian | RGF19120DE20MP12 | 95.0 | \$500 | Heil | G9MXT1002120A | 96.0 | \$500 |
| Heat Controller Inc. | GDD95C045B3* | 95.0 | \$500 | Heil | G9MXT1202422A | 96.0 | \$500 |
| Heat Controller Inc. | GDD95C070B4* | 95.0 | \$500 | ICP Commercial | F9MAC0601714A | 97.0 | \$700 |
| Heat Controller Inc. | GDD95C090C4* | 95.0 | \$500 | ICP Commercial | F9MAC0801714A | 97.0 | \$700 |
| Heat Controller Inc. | GDD95C110C5* | 95.0 | \$500 | ICP Commercial | F9MAC1202422A | 97.0 | \$700 |
| Heat Controller Inc. | GDD95T070B4* | 96.0 | \$500 | ICP Commercial | F9MAE0601714A | 97.0 | \$700 |
| Heat Controller Inc. | GDD95T090C5* | 96.0 | \$500 | ICP Commercial | F9MAE0801714A | 97.0 | \$700 |
| Heat Controller Inc. | GDD95T110C5* | 96.0 | \$500 | ICP Commercial | F9MAE1202422A | 97.0 | \$700 |
| Heat Controller Inc. | GUH95C045B3* | 95.0 | \$500 | ICP Commercial | F9MVE0401410A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95C070B3* | 95.0 | \$500 | ICP Commercial | F9MVE0401712A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95C090C4* | 95.0 | \$500 | ICP Commercial | F9MVE0601412A | 95.0 | \$500 |
| Heat Controller Inc. | GUH95C110C5* | 95.0 | \$500 | ICP Commercial | F9MVE0601714A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95C135D5* | 95.0 | \$500 | ICP Commercial | F9MVE0801716A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T045B3* | 96.0 | \$500 | ICP Commercial | F9MVE1202422A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T060B4XE | 96.0 | \$500 | ICP Commercial | F9MVT0401410A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T070B3* | 96.0 | \$500 | ICP Commercial | F9MVT0601714A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T080C5XE | 96.0 | \$500 | ICP Commercial | F9MVT0801716A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T090C3* | 96.0 | \$500 | ICP Commercial | F9MVT1202422A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T090C5* | 96.0 | \$500 | ICP Commercial | F9MXE0401410A* | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T100C5XE | 96.0 | \$500 | ICP Commercial | F9MXE0401712A | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T110C5* | 96.0 | \$500 | ICP Commercial | F9MXE0601412A | 95.5 | \$500 |
| Heat Controller Inc. | GUH95T120D5XE | 96.0 | \$500 | ICP Commercial | F9MXE0601714A* | 96.0 | \$500 |
| Heat Controller Inc. | GUH95T135D5* | 96.0 | \$500 | ICP Commercial | F9MXE0801716A* | 96.0 | \$500 |
| Heil | G9MAC0601714A | 97.0 | \$700 | ICP Commercial | F9MXT0401410A | 96.0 | \$500 |
| Heil | G9MAC0602120A | 98.0 | \$700 | ICP Commercial | F9MXT0401712A | 96.0 | \$500 |
| Heil | G9MAC0801714A | 97.0 | \$700 | ICP Commercial | F9MXT0601412A | 95.0 | \$500 |
| Heil | G9MAC0802120A | 97.0 | \$700 | ICP Commercial | F9MXT0601714A | 96.0 | \$500 |
| Heil | G9MAC1002122A | 97.0 | \$700 | ICP Commercial | F9MXT0801716A | 96.0 | \$500 |
| Heil | G9MAC1202422A | 97.0 | \$700 | ICP Commercial | F9MXT1202422A | 96.0 | \$500 |
| Heil | G9MAE0601714A | 97.0 | \$700 | ICP Commercial | G9MAC0601714A | 97.0 | \$700 |
| Heil | G9MAE0602120A | 98.0 | \$700 | ICP Commercial | G9MAC0801714A | 97.0 | \$700 |
| Heil | G9MAE0801714A | 97.0 | \$700 | ICP Commercial | G9MAC1202422A | 97.0 | \$700 |
| Heil | G9MAE0802120A | 97.0 | \$700 | ICP Commercial | G9MAE0601714A | 97.0 | \$700 |
| Heil | G9MAE1002122A | 97.0 | \$700 | ICP Commercial | G9MAE0801714A | 97.0 | \$700 |
| Heil | G9MAE1202422A | 97.0 | \$700 | ICP Commercial | G9MAE1202422A | 97.0 | \$700 |
| Heil | G9MVE0401410A | 96.0 | \$500 | ICP Commercial | G9MVE0401410A | 96.0 | \$500 |
| Heil | G9MVE0401712A | 96.0 | \$500 | ICP Commercial | G9MVE0601714A | 96.0 | \$500 |
| Heil | G9MVE0601412A | 95.0 | \$500 | ICP Commercial | G9MVE0801716A | 96.0 | \$500 |
| Heil | G9MVE0601714A | 96.0 | \$500 | ICP Commercial | G9MVE1002116A | 96.0 | \$500 |
| Heil | G9MVE0801716A | 96.0 | \$500 | ICP Commercial | G9MVE1202422A | 96.0 | \$500 |
| Heil | G9MVE0802120A | 96.0 | \$500 | ICP Commercial | G9MVT0401410A | 96.0 | \$500 |
| Heil | G9MVE1002116A | 96.0 | \$500 | ICP Commercial | G9MVT0601714A | 96.0 | \$500 |
| Heil | G9MVE1002120A | 96.0 | \$500 | ICP Commercial | G9MVT0801716A | 96.0 | \$500 |
| Heil | G9MVE1202422A | 96.0 | \$500 | ICP Commercial | G9MVT1202422A | 96.0 | \$500 |
| Heil | G9MVT0401410A | 96.0 | \$500 | ICP Commercial | G9MXE0401410A | 96.0 | \$500 |
| Heil | G9MVT0601714A | 96.0 | \$500 | ICP Commercial | G9MXE0601714A | 96.0 | \$500 |
| Heil | G9MVT0801716A | 96.0 | \$500 | ICP Commercial | G9MXE0801716A | 96.0 | \$500 |
| Heil | G9MVT0802120A | 96.0 | \$500 | ICP Commercial | G9MXE0802120A | 96.0 | \$500 |
| Heil | G9MVT1002120A | 96.0 | \$500 | ICP Commercial | G9MXT0401410A | 96.0 | \$500 |
| Heil | G9MVT1202422A | 96.0 | \$500 | ICP Commercial | G9MXT0601714A | 96.0 | \$500 |
| Heil | G9MXE0401410A | 96.0 | \$500 | ICP Commercial | G9MXT0801716A | 96.0 | \$500 |
| Heil | G9MXE0401712A* | 96.0 | \$500 | ICP Commercial | G9MXT1202422A | 96.0 | \$500 |
| Heil | G9MXE0601412A* | 95.5 | \$500 | International Comfort Products (ICP) | 926TA30040V14A | 97.0 | \$700 |
| Heil | G9MXE0601714A | 96.0 | \$500 | | | | |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------|----------------|------|--------|--------------|--------------------|------|--------|
| Keeprite | G9MXE0601412A* | 95.5 | \$500 | Kenmore | G9MVE0401410A | 96.0 | \$500 |
| Keeprite | G9MXE0601714A | 96.0 | \$500 | Kenmore | G9MVE0401712A | 96.0 | \$500 |
| Keeprite | G9MXE0801716A | 96.0 | \$500 | Kenmore | G9MVE0601412A | 95.0 | \$500 |
| Keeprite | G9MXE0802120A | 96.0 | \$500 | Kenmore | G9MVE0601714A | 96.0 | \$500 |
| Keeprite | G9MXT0401410A | 96.0 | \$500 | Kenmore | G9MVE0801716A | 96.0 | \$500 |
| Keeprite | G9MXT0601714A | 96.0 | \$500 | Kenmore | G9MVE0802120A | 96.0 | \$500 |
| Keeprite | G9MXT0801716A | 96.0 | \$500 | Kenmore | G9MVE1002116A | 96.0 | \$500 |
| Keeprite | G9MXT0802120A | 96.0 | \$500 | Kenmore | G9MVE1002120A | 96.0 | \$500 |
| Keeprite | G9MXT1002120A | 96.0 | \$500 | Kenmore | G9MVE1202422A | 96.0 | \$500 |
| Keeprite | G9MXT1202422A | 96.0 | \$500 | Kenmore | G9MVT0401410A | 96.0 | \$500 |
| Kelvinator | KG7TC120*-D* | 95.1 | \$500 | Kenmore | G9MVT0601714A | 96.0 | \$500 |
| Kenmore | F9MAC0601714A | 97.0 | \$700 | Kenmore | G9MVT0801716A | 96.0 | \$500 |
| Kenmore | F9MAC0602120A | 98.0 | \$700 | Kenmore | G9MVT0802120A | 96.0 | \$500 |
| Kenmore | F9MAC0801714A | 97.0 | \$700 | Kenmore | G9MVT1002120A | 96.0 | \$500 |
| Kenmore | F9MAC0802120A | 97.0 | \$700 | Kenmore | G9MVT1202422A | 96.0 | \$500 |
| Kenmore | F9MAC1002122A | 97.0 | \$700 | Kenmore | G9MXE0401410A | 96.0 | \$500 |
| Kenmore | F9MAC1202422A | 97.0 | \$700 | Kenmore | G9MXE0401712A* | 96.0 | \$500 |
| Kenmore | F9MAE0601714A | 97.0 | \$700 | Kenmore | G9MXE0601412A* | 95.5 | \$500 |
| Kenmore | F9MAE0602120A | 98.0 | \$700 | Kenmore | G9MXE0601714A | 96.0 | \$500 |
| Kenmore | F9MAE0801714A | 97.0 | \$700 | Kenmore | G9MXE0801716A | 96.0 | \$500 |
| Kenmore | F9MAE0802120A | 97.0 | \$700 | Kenmore | G9MXE0802120A | 96.0 | \$500 |
| Kenmore | F9MAE1002122A | 97.0 | \$700 | Kenmore | G9MXT0401410A | 96.0 | \$500 |
| Kenmore | F9MAE1202422A | 97.0 | \$700 | Kenmore | G9MXT0601714A | 96.0 | \$500 |
| Kenmore | F9MVE0401410A | 96.0 | \$500 | Kenmore | G9MXT0801716A | 96.0 | \$500 |
| Kenmore | F9MVE0401712A | 96.0 | \$500 | Kenmore | G9MXT0802120A | 96.0 | \$500 |
| Kenmore | F9MVE0601412A | 95.0 | \$500 | Kenmore | G9MXT1002120A | 96.0 | \$500 |
| Kenmore | F9MVE0601714A | 96.0 | \$500 | Kenmore | G9MXT1202422A | 96.0 | \$500 |
| Kenmore | F9MVE0801716A | 96.0 | \$500 | Lennox | 95G2DF045BV12-* | 95.0 | \$500 |
| Kenmore | F9MVE0802120A | 96.0 | \$500 | Lennox | 95G2DF070BV16-* | 95.0 | \$500 |
| Kenmore | F9MVE1002120A | 96.0 | \$500 | Lennox | 95G2DF090CV20-* | 95.0 | \$500 |
| Kenmore | F9MVE1202422A | 96.0 | \$500 | Lennox | 95G2DF110CV20-* | 95.0 | \$500 |
| Kenmore | F9MVT0401410A | 96.0 | \$500 | Lennox | EL195UH030XE24B* | 95.0 | \$500 |
| Kenmore | F9MVT0601714A | 96.0 | \$500 | Lennox | EL195UH045XE24B* | 95.0 | \$500 |
| Kenmore | F9MVT0801716A | 96.0 | \$500 | Lennox | EL195UH045XE36B | 95.0 | \$500 |
| Kenmore | F9MVT0802120A | 96.0 | \$500 | Lennox | EL195UH045XE36B-* | 95.0 | \$500 |
| Kenmore | F9MVT1002120A | 96.0 | \$500 | Lennox | EL195UH070XE36B-* | 95.0 | \$500 |
| Kenmore | F9MVT1202422A | 96.0 | \$500 | Lennox | EL195UH090XE48C-* | 95.0 | \$500 |
| Kenmore | F9MXE0401712A | 96.0 | \$500 | Lennox | EL195UH110XE60C-* | 95.0 | \$500 |
| Kenmore | F9MXE0601412A | 95.5 | \$500 | Lennox | EL195UH110XE60C-06 | 95.0 | \$500 |
| Kenmore | F9MXE1002120A* | 96.0 | \$500 | Lennox | EL195UH135XE60D-* | 95.0 | \$500 |
| Kenmore | F9MXT0401410A | 96.0 | \$500 | Lennox | EL296DF045XE36B-* | 96.0 | \$500 |
| Kenmore | F9MXT0401712A | 96.0 | \$500 | Lennox | EL296DF045XV36B-* | 96.0 | \$500 |
| Kenmore | F9MXT0601412A | 95.0 | \$500 | Lennox | EL296DF070XE48B-* | 96.0 | \$500 |
| Kenmore | F9MXT0601714A | 96.0 | \$500 | Lennox | EL296DF070XV48B-* | 96.0 | \$500 |
| Kenmore | F9MXT0801716A | 96.0 | \$500 | Lennox | EL296DF090XE48C-* | 96.0 | \$500 |
| Kenmore | F9MXT0802120A | 96.0 | \$500 | Lennox | EL296DF090XV60C-* | 96.0 | \$500 |
| Kenmore | F9MXT1002120A | 96.0 | \$500 | Lennox | EL296DF110XE60C-* | 96.0 | \$500 |
| Kenmore | F9MXT1202422A | 96.0 | \$500 | Lennox | EL296DF110XV60C-* | 96.0 | \$500 |
| Kenmore | G9MAC0601714A | 97.0 | \$700 | Lennox | EL296UH045XE36B-* | 96.0 | \$500 |
| Kenmore | G9MAC0602120A | 98.0 | \$700 | Lennox | EL296UH045XV36B-* | 96.0 | \$500 |
| Kenmore | G9MAC0801714A | 97.0 | \$700 | Lennox | EL296UH070XE36B-* | 96.0 | \$500 |
| Kenmore | G9MAC0802120A | 97.0 | \$700 | Lennox | EL296UH070XV36B-* | 96.0 | \$500 |
| Kenmore | G9MAC1002122A | 97.0 | \$700 | Lennox | EL296UH090XE48C-* | 96.0 | \$500 |
| Kenmore | G9MAC1202422A | 97.0 | \$700 | Lennox | EL296UH090XV36C-* | 96.0 | \$500 |
| Kenmore | G9MAE0601714A | 97.0 | \$700 | Lennox | EL296UH090XV48C-* | 96.0 | \$500 |
| Kenmore | G9MAE0602120A | 98.0 | \$700 | Lennox | EL296UH090XV60C-* | 96.0 | \$500 |
| Kenmore | G9MAE0801714A | 97.0 | \$700 | Lennox | EL296UH110XE60C-* | 96.0 | \$500 |
| Kenmore | G9MAE0802120A | 97.0 | \$700 | Lennox | EL296UH110XV48C-* | 96.0 | \$500 |
| Kenmore | G9MAE1002122A | 97.0 | \$700 | Lennox | EL296UH110XV60C-* | 96.0 | \$500 |
| Kenmore | G9MAE1202422A | 97.0 | \$700 | Lennox | EL296UH135XE60D-* | 96.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|-------------------|-------------------|------|--------|--------------------|-------------------|------|--------|
| Lennox | EL296UH135XV60D-* | 96.0 | \$500 | Lennox Industries | SL297UH040NV36B-* | 97.5 | \$700 |
| Lennox | SLP98DF070XV36B-* | 96.0 | \$500 | Lennox Industries | SL297UH060NV36B-* | 97.5 | \$700 |
| Lennox | SLP98DF070XV36B-* | 97.5 | \$700 | Lennox Industries | SL297UH080NV48C-* | 97.5 | \$700 |
| Lennox | SLP98DF090XV36C-* | 98.0 | \$700 | Lennox Industries | SL297UH080NV60C-* | 97.5 | \$700 |
| Lennox | SLP98DF090XV36C-* | 97.5 | \$700 | Luxaire | LP9C060B12MP12 | 97.5 | \$700 |
| Lennox | SLP98DF090XV48C-* | 98.0 | \$700 | Luxaire | LP9C060B12MP12CA | 97.5 | \$700 |
| Lennox | SLP98DF090XV48C-* | 97.5 | \$700 | Luxaire | LP9C080B12MP12 | 97.5 | \$700 |
| Lennox | SLP98DF090XV60C-* | 98.0 | \$700 | Luxaire | LP9C080B12MP12CA | 97.5 | \$700 |
| Lennox | SLP98DF090XV60C-* | 97.5 | \$700 | Luxaire | LP9C080C16MP12 | 97.7 | \$700 |
| Lennox | SLP98DF110XV60C-* | 98.0 | \$700 | Luxaire | LP9C080C16MP12CA | 97.7 | \$700 |
| Lennox | SLP98DF110XV60C-* | 98.2 | \$700 | Luxaire | LP9C100C16MP12 | 97.7 | \$700 |
| Lennox | SLP98UH070XV36B-* | 98.0 | \$700 | Luxaire | LP9C100C16MP12CA | 97.7 | \$700 |
| Lennox | SLP98UH070XV36B-* | 97.4 | \$700 | Luxaire | LP9C100C20MP12 | 97.7 | \$700 |
| Lennox | SLP98UH090XV36C-* | 98.0 | \$700 | Luxaire | LP9C100C20MP12CA | 97.7 | \$700 |
| Lennox | SLP98UH090XV36C-* | 98.0 | \$700 | Luxaire | LP9C120D20MP12 | 98.0 | \$700 |
| Lennox | SLP98UH090XV48C-* | 98.0 | \$700 | Luxaire | LP9C120D20MP12CA | 98.0 | \$700 |
| Lennox | SLP98UH090XV48C-* | 97.5 | \$700 | Luxaire | TP9C120D20MP12 | 98.0 | \$700 |
| Lennox | SLP98UH090XV60C-* | 99.0 | \$700 | Maytag | MGC2TC120D-*D* | 95.1 | \$500 |
| Lennox | SLP98UH090XV60C-* | 98.2 | \$700 | Maytag | PGC2MQ060*-VB | 97.0 | \$700 |
| Lennox | SLP98UH110XV60C-* | 98.0 | \$700 | Maytag | PGC2MQ080*-VC | 97.2 | \$700 |
| Lennox | SLP98UH110XV60C-* | 97.5 | \$700 | Maytag | PGC2MQ100*-VC | 97.4 | \$700 |
| Lennox | SLP98UH135XV60D-* | 98.0 | \$700 | Maytag | PGC2MQ120*-VD | 97.0 | \$700 |
| Lennox | SLP98UH135XV60D-* | 97.5 | \$700 | Maytag | PGC2TC120*-D* | 95.1 | \$500 |
| Lennox Elite 90 | EL195UH070XE36B-* | 95.0 | \$500 | Miller | FG7TC120*-D* | 95.1 | \$500 |
| Lennox Elite 90 | EL195UH090XE48C-* | 95.0 | \$500 | Napoleon | NPV040T2B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF045XE36B-* | 96.0 | \$500 | Napoleon | NPV060T3B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF045XV36B-* | 96.0 | \$500 | Napoleon | NPV080T3B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF070XE48B-* | 95.9 | \$500 | Napoleon | NPV080T4B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF070XV48B-* | 96.0 | \$500 | Napoleon | NPV100T5B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF090XE48C-* | 96.0 | \$500 | Napoleon | NPV120T5B | 96.0 | \$500 |
| Lennox Elite 90 | EL296DF090XV60C-* | 96.0 | \$500 | Napoleon | NPX030S2B | 95.0 | \$500 |
| Lennox Elite 90 | EL296DF110XE60C-* | 96.0 | \$500 | Napoleon | NPX040S2B | 95.0 | \$500 |
| Lennox Elite 90 | EL296DF110XV60C-* | 96.0 | \$500 | Napoleon | NPX060S3B | 95.0 | \$500 |
| Lennox Elite 90 | EL296UH045XE36B-* | 96.0 | \$500 | Napoleon | NPX080S3B | 95.0 | \$500 |
| Lennox Elite 90 | EL296UH045XV36B-* | 96.0 | \$500 | Napoleon | NPX080S4B | 95.0 | \$500 |
| Lennox Elite 90 | EL296UH070XE36B-* | 95.5 | \$500 | Napoleon | NPX100S5B | 95.0 | \$500 |
| Lennox Elite 90 | EL296UH070XV36B-* | 96.0 | \$500 | Napoleon | NPX120S5B | 95.0 | \$500 |
| Lennox Elite 90 | EL296UH090XE48C-* | 96.0 | \$500 | Napoleon | NUV040T2B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH090XV36C-* | 96.0 | \$500 | Napoleon | NUV060T3B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH090XV48C-* | 96.0 | \$500 | Napoleon | NUV080T3B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH090XV60C-* | 96.0 | \$500 | Napoleon | NUV080T4B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH110XE60C-* | 96.0 | \$500 | Napoleon | NUV100T5B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH110XV48C-* | 96.0 | \$500 | Napoleon | NUV120T5B | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH110XV60C-* | 96.0 | \$500 | Nordyne | FG7MQ060*-VB | 97.0 | \$700 |
| Lennox Elite 90 | EL296UH135XE60D-* | 96.0 | \$500 | Nordyne | FG7MQ080*-VC | 97.2 | \$700 |
| Lennox Elite 90 | EL296UH135XV60D-* | 96.0 | \$500 | Nordyne | FG7MQ100*-VC | 97.4 | \$700 |
| Lennox Industries | 95G2DF045BV12-* | 95.0 | \$500 | Nordyne | FG7MQ120*-VD | 97.0 | \$700 |
| Lennox Industries | 95G2DF070BV16-* | 95.0 | \$500 | Nordyne | FG7TC120*-D* | 95.1 | \$500 |
| Lennox Industries | 95G2DF090CV20-* | 95.0 | \$500 | Nordyne | KG7MQ060*-VB | 97.0 | \$700 |
| Lennox Industries | 95G2DF110CV20-* | 95.0 | \$500 | Nordyne | KG7MQ080*-VC | 97.2 | \$700 |
| Lennox Industries | 96G1UH030BE08-* | 96.1 | \$500 | Nordyne | KG7MQ100*-VC | 97.4 | \$700 |
| Lennox Industries | EL196DF045XE36B-* | 96.1 | \$500 | Nordyne | KG7MQ120*-VD | 97.0 | \$700 |
| Lennox Industries | EL196DF070XE48B-* | 96.1 | \$500 | Nordyne | KG7TC120*-D* | 95.1 | \$500 |
| Lennox Industries | EL196DF090XE48C-* | 96.1 | \$500 | Nortek Global HVAC | FG7MQ 060*-VB | 97.0 | \$700 |
| Lennox Industries | EL196UH030XE24B-* | 96.1 | \$500 | Nortek Global HVAC | FG7MQ 080*-VC | 97.0 | \$700 |
| Lennox Industries | EL196UH045XE24B-* | 96.4 | \$500 | Nortek Global HVAC | FG7MQ 100*-VC | 97.0 | \$700 |
| Lennox Industries | EL196UH045XE36B-* | 96.6 | \$500 | Nortek Global HVAC | FG7MQ 120*-VD | 97.0 | \$700 |
| Lennox Industries | EL196UH070XE36B-* | 96.1 | \$500 | Nortek Global HVAC | FG7TC 060*-B* | 95.0 | \$500 |
| Lennox Industries | EL196UH090XE48C-* | 96.3 | \$500 | Nortek Global HVAC | FG7TC 080*-C* | 95.0 | \$500 |
| Lennox Industries | EL196UH110XE60C-* | 96.4 | \$500 | Nortek Global HVAC | FG7TC 100*-C* | 95.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------------|-----------------|------|--------|--------------|------------------|------|--------|
| Nortek Global HVAC | FG7TC 120*-*D* | 95.0 | \$500 | Philco | FG7TC120*-*D* | 95.1 | \$500 |
| Nortek Global HVAC | FG7TL 060*-*B* | 95.0 | \$500 | Philco | KG7TC120*-*D* | 95.1 | \$500 |
| Nortek Global HVAC | FG7TL 080*-*C* | 95.0 | \$500 | Rheem | D96VA0852521MSA | 96.0 | \$500 |
| Nortek Global HVAC | FG7TL 100*-*C* | 95.0 | \$500 | Rheem | R95TA0601317MSA | 95.0 | \$500 |
| Nortek Global HVAC | KG7TC 060*-*B* | 95.0 | \$500 | Rheem | R95TA1151524MSA | 95.0 | \$500 |
| Nortek Global HVAC | KG7TC 080*-*C* | 95.0 | \$500 | Rheem | R96VA0402317MSA | 96.0 | \$500 |
| Nortek Global HVAC | KG7TC 100*-*C* | 95.0 | \$500 | Rheem | R96VA0602317MSA | 96.0 | \$500 |
| Nortek Global HVAC | KG7TC 120*-*D* | 95.0 | \$500 | Rheem | R96VA0702317MSA | 96.0 | \$500 |
| Nortek Global HVAC | KG7TL 060*-*B* | 95.0 | \$500 | Rheem | R96VA0852521MSB | 96.0 | \$500 |
| Nortek Global HVAC | KG7TL 080*-*C* | 95.0 | \$500 | Rheem | R96VA1002521MSA | 95.0 | \$500 |
| Nortek Global HVAC | KG7TL 100*-*C* | 95.0 | \$500 | Rheem | R96VA1152524MSA | 96.0 | \$500 |
| Nortek Global HVAC | MGC2TC060D-*B* | 95.0 | \$500 | Rheem | R97VA060M317KSA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TC080D-*C* | 95.0 | \$500 | Rheem | R97VA060M317USA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TC100D-*C* | 95.0 | \$500 | Rheem | R97VA070M317KSA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TC120D-*D* | 95.0 | \$500 | Rheem | R97VA070M317USA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TL060*-*B* | 95.0 | \$500 | Rheem | R97VA085M521KSA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TL080*-*C* | 95.0 | \$500 | Rheem | R97VA085M521USA | 97.0 | \$700 |
| Nortek Global HVAC | MGC2TL100*-*C* | 95.0 | \$500 | Rheem | R97VA100M521KSA | 97.0 | \$700 |
| Nortek Global HVAC | PGC2MQ 060*-*VB | 97.0 | \$700 | Rheem | R97VA100M521USA | 97.0 | \$700 |
| Nortek Global HVAC | PGC2MQ 080*-*VC | 97.0 | \$700 | Rheem | R97VA115M524KSA | 97.0 | \$700 |
| Nortek Global HVAC | PGC2MQ 100*-*VC | 97.0 | \$700 | Rheem | R97VA115M524USA | 97.0 | \$700 |
| Nortek Global HVAC | PGC2MQ 120*-*VD | 97.0 | \$700 | Rheem | R97VA115M524USA | 97.0 | \$700 |
| Nortek Global HVAC | PGC2TC060*-*B* | 95.0 | \$500 | Rheem | R98VA060M317USA | 98.7 | \$700 |
| Nortek Global HVAC | PGC2TC080*-*C* | 95.0 | \$500 | Rheem | R98VA070M317USA | 98.3 | \$700 |
| Nortek Global HVAC | PGC2TC100*-*C* | 95.0 | \$500 | Rheem | R98VA085M521USA | 98.1 | \$700 |
| Nortek Global HVAC | PGC2TC120*-*D* | 95.0 | \$500 | Rheem | R98VA100M521USA | 98.1 | \$700 |
| Nortek Global HVAC | PGC2TL060D-*B* | 95.0 | \$500 | Rheem | R98VA115M524USA | 98.6 | \$700 |
| Nortek Global HVAC | PGC2TL080D-*C* | 95.0 | \$500 | Rheem | RGFG-06EMCKS | 96.0 | \$500 |
| Nortek Global HVAC | PGC2TL100D-*C* | 95.0 | \$500 | Rheem | RGFG-07EMCKS | 95.3 | \$500 |
| Nortek Global HVAC | VG7TC 060*-*B* | 95.0 | \$500 | Rheem | RGFG-09EZCMS | 95.1 | \$500 |
| Nortek Global HVAC | VG7TC 080*-*C* | 95.0 | \$500 | Rheem | RGRM-06(E,N)MAES | 95.0 | \$500 |
| Nortek Global HVAC | VG7TC 100*-*C* | 95.0 | \$500 | Rheem | RGRM-07(E,N)MAES | 95.0 | \$500 |
| Nortek Global HVAC | VG7TC 120*-*D* | 95.0 | \$500 | Rheem | RGRM-10(E,N)ZAJ | 95.0 | \$500 |
| NTI | GF 200 | 97.1 | \$700 | Rheem | S96VA0852521MSA | 96.0 | \$500 |
| NuTone | FG7MQ060*-*VB | 97.0 | \$700 | Rheem | U96VA0852521MSA | 96.0 | \$500 |
| NuTone | FG7MQ080*-*VC | 97.2 | \$700 | Rheem | W96VA0852521MSA | 96.0 | \$500 |
| NuTone | FG7MQ100*-*VC | 97.4 | \$700 | Rheem Ruud | R95TC0601317MSA | 95.0 | \$500 |
| NuTone | FG7MQ120*-*VD | 97.0 | \$700 | Rheem Ruud | R95TC1151524MSA | 95.0 | \$500 |
| NuTone | FG7TC120*-*D* | 95.1 | \$500 | Rheem-Ruud | D95TA0601317MSA | 95.0 | \$500 |
| NuTone | KG7TC120*-*D* | 95.1 | \$500 | Rheem-Ruud | D95TA1151524MSA | 95.0 | \$500 |
| NY Thermal Inc. | GF 200 | 97.1 | \$700 | Rheem-Ruud | D95TC0601317MSA | 95.0 | \$500 |
| Olsen | G95V100-5 | 95.0 | \$500 | Rheem-Ruud | D95TC1151524MSA | 95.0 | \$500 |
| Payne | PG95XAT30040A | 95.5 | \$500 | Rheem-Ruud | D96VA0402317MSA | 96.0 | \$500 |
| Payne | PG95XAT36040B | 96.0 | \$500 | Rheem-Ruud | D96VA0602317MSA | 96.0 | \$500 |
| Payne | PG95XAT36060A | 95.0 | \$500 | Rheem-Ruud | D96VA0702317MSA | 96.0 | \$500 |
| Payne | PG95XAT42060B | 95.5 | \$500 | Rheem-Ruud | D96VA1002521MSA | 95.0 | \$500 |
| Payne | PG95XAT48080B | 95.5 | \$500 | Rheem-Ruud | D96VA1152524MSA | 96.0 | \$500 |
| Payne | PG95XAT60080C | 95.5 | \$500 | Rheem-Ruud | R95TA0601317MSA | 95.0 | \$500 |
| Payne | PG95XAT60100C | 95.5 | \$500 | Rheem-Ruud | R95TA1151524MSA | 95.0 | \$500 |
| Payne | PG95XAT66120D | 95.5 | \$500 | Rheem-Ruud | R95TC0601317MSA | 95.0 | \$500 |
| Payne | PG96VAT30040A | 96.0 | \$500 | Rheem-Ruud | R95TC1151524MSA | 95.0 | \$500 |
| Payne | PG96VAT42060B | 96.0 | \$500 | Rheem-Ruud | R96VA0402317MSA | 96.0 | \$500 |
| Payne | PG96VAT48080B | 96.0 | \$500 | Rheem-Ruud | R96VA0602317MSA | 96.0 | \$500 |
| Payne | PG96VAT60080C | 96.0 | \$500 | Rheem-Ruud | R96VA0702317MSA | 96.0 | \$500 |
| Payne | PG96VAT60100C | 96.0 | \$500 | Rheem-Ruud | R96VA1002521MSA | 95.0 | \$500 |
| Payne | PG96VAT66120D | 96.0 | \$500 | Rheem-Ruud | R96VA1152524MSA | 96.0 | \$500 |
| Philco | FG7MQ060*-*VB | 97.0 | \$700 | Rheem-Ruud | R97VA060M317USA | 97.0 | \$700 |
| Philco | FG7MQ080*-*VC | 97.2 | \$700 | Rheem-Ruud | R97VA070M317USA | 97.0 | \$700 |
| Philco | FG7MQ100*-*VC | 97.4 | \$700 | Rheem-Ruud | R97VA085M521USA | 97.0 | \$700 |
| Philco | FG7MQ120*-*VD | 97.0 | \$700 | Rheem-Ruud | R97VA100M521USA | 97.0 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------------------|------------------|------|--------|--------------------------|------------------|------|--------|
| Rheem-Ruud | R97VA115M524USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | R92TA1001521MSA | 95.0 | \$500 |
| Rheem-Ruud | RGFG-06EMCKS | 96.0 | \$500 | Rheem-Ruud Manufacturing | R92TA1151524MSA | 95.0 | \$500 |
| Rheem-Ruud | RGFG-07EMCKS | 95.0 | \$500 | Rheem-Ruud Manufacturing | R95TC0601317MSA | 95.0 | \$500 |
| Rheem-Ruud | RGFG-09EZCMS | 95.0 | \$500 | Rheem-Ruud Manufacturing | R95TC1151524MSA | 95.0 | \$500 |
| Rheem-Ruud | RGJF-06(E,N)MCKS | 95.0 | \$500 | Rheem-Ruud Manufacturing | R96VA0402317MSA | 96.0 | \$500 |
| Rheem-Ruud | S95TA0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R96VA0602317MSA | 96.0 | \$500 |
| Rheem-Ruud | S95TA1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R96VA0702317MSA | 96.0 | \$500 |
| Rheem-Ruud | S95TC0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R96VA1002521MSA | 95.0 | \$500 |
| Rheem-Ruud | S95TC1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R96VA1152524MSA | 96.0 | \$500 |
| Rheem-Ruud | S96VA0402317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VA060M317USA | 97.0 | \$700 |
| Rheem-Ruud | S96VA0602317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VA070M317USA | 97.0 | \$700 |
| Rheem-Ruud | S96VA0702317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VA085M521USA | 97.0 | \$700 |
| Rheem-Ruud | S96VA1002521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R97VA100M521USA | 97.0 | \$700 |
| Rheem-Ruud | S96VA1152524MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VA115M524USA | 97.0 | \$700 |
| Rheem-Ruud | TZ95MSX060B30C | 95.0 | \$500 | Rheem-Ruud Manufacturing | R97VB060M317USA | 97.0 | \$700 |
| Rheem-Ruud | TZ95MSX115D50C | 95.0 | \$500 | Rheem-Ruud Manufacturing | R97VB070M317USA | 97.0 | \$700 |
| Rheem-Ruud | TZ96MDV040B30A | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VB085M521USA | 97.0 | \$700 |
| Rheem-Ruud | TZ96MDV115D50A | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VB100M521USA | 97.0 | \$700 |
| Rheem-Ruud | U96VA0402317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R97VB115M524USA | 97.0 | \$700 |
| Rheem-Ruud | U96VA0602317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R98VB060M317USA | 98.7 | \$700 |
| Rheem-Ruud | U96VA0702317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R98VB070M317USA | 98.3 | \$700 |
| Rheem-Ruud | U96VA1002521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | R98VB085M521USA | 98.1 | \$700 |
| Rheem-Ruud | U96VA1152524MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | R98VB100M521USA | 98.1 | \$700 |
| Rheem-Ruud | U97VA060M317USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | R98VB115M524USA | 98.6 | \$700 |
| Rheem-Ruud | U97VA070M317USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | RGFG-06EMCKS | 96.0 | \$500 |
| Rheem-Ruud | U97VA085M521USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | RGFG-07EMCKS | 95.0 | \$500 |
| Rheem-Ruud | U97VA100M521USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | RGGE-06(E,N)MCKS | 92.0 | \$500 |
| Rheem-Ruud | U97VA115M524USA | 97.0 | \$700 | Rheem-Ruud Manufacturing | RGGE-07(E,N)MCKS | 90.0 | \$500 |
| Rheem-Ruud | W95TA0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGGE-09(E,N)ZCMS | 92.0 | \$500 |
| Rheem-Ruud | W95TA1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGGE-10(E,N)ZCMS | 91.0 | \$500 |
| Rheem-Ruud | W95TC0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGGE-12(E,N)RCMS | 92.0 | \$500 |
| Rheem-Ruud | W95TC1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGJF-06(E,N)MCKS | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA0401317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGJF-07(E,N)MCKS | 93.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGJF-09(E,N)ZCMS | 90.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA0701317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGJF-10(E,N)ZCMS | 90.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA0851521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | RGJF-12(E,N)RCMS | 92.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA1001521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA0401317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D92TA1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA0601317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC0401317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA0701317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA0851521MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC0701317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA1001521MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC0851521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S92TA1151524MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC1001521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S95TC0601317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D95TC1151524MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S95TC0701317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA0402317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S95TC1001521MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA0602317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S95TC1151524MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA0702317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA0402317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA0852521MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA0602317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA1002521MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA0702317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA1152524MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA0852521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96TA1152524MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA1002521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96VA0402317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96TA1152524MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96VA0602317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96VA0402317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96VA0702317MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96VA0602317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96VA1002521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S96VA0702317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | D96VA1152524MSA | 96.0 | \$500 | Rheem-Ruud Manufacturing | S96VA1002521MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | R92TA0401317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | S96VA1152524MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | R92TA0601317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | TZ92MSX040B30A | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | R92TA0701317MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | TZ92MSX060B30A | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | R92TA0851521MSA | 95.0 | \$500 | Rheem-Ruud Manufacturing | TZ92MSX070B30A | 95.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--------------------------|-----------------|------|--------|------------------|------------------|------|--------|
| Rheem-Ruud Manufacturing | TZ92MSX085C50A | 95.0 | \$500 | Rheem/RUUD | R96TA1002521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ92MSX100C50A | 95.0 | \$500 | Rheem/RUUD | R96TA1152524MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ92MSX115D50A | 95.0 | \$500 | Ruud | R95TA0601317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX040B30C | 95.0 | \$500 | Ruud | R95TA1151524MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX060B30C | 95.0 | \$500 | Ruud | RGFG-06EMCKS | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX070B30C | 95.0 | \$500 | Ruud | RGFG-07EMCKS | 95.3 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX085C50C | 95.0 | \$500 | Ruud | RGFG-09EZCMS | 95.1 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX100C50C | 95.0 | \$500 | Ruud | RGRM-06(E,N)MAES | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ95MSX115D50C | 95.0 | \$500 | Ruud | RGRM-07(E,N)MAES | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDV040B30A | 96.0 | \$500 | Ruud | RGRM-10(E,N)ZAJ | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDV085C50B | 96.0 | \$500 | Ruud | U96VA0402317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDV115D50A | 96.0 | \$500 | Ruud | U96VA0602317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDX040B30A | 96.0 | \$500 | Ruud | U96VA0702317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDX060B30A | 96.0 | \$500 | RUUD | U96VA0852521MSB | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDX070B30A | 96.0 | \$500 | Ruud | U96VA1002521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDX085C50A | 96.0 | \$500 | Ruud | U96VA1152524MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | TZ96MDX100C50A | 96.0 | \$500 | RUUD | U97VA060M317KSA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | TZ96MDX115D50A | 96.0 | \$500 | Ruud | U97VA060M317USA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U96VA0402317MSA | 96.0 | \$500 | RUUD | U97VA070M317KSA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U96VA0602317MSA | 96.0 | \$500 | Ruud | U97VA070M317USA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U96VA0702317MSA | 96.0 | \$500 | RUUD | U97VA085M521KSA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U96VA1002521MSA | 95.0 | \$500 | Ruud | U97VA085M521USA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U96VA1152524MSA | 96.0 | \$500 | RUUD | U97VA100M521KSA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U97VA060M317USA | 97.0 | \$700 | Ruud | U97VA100M521USA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U97VA070M317USA | 97.0 | \$700 | RUUD | U97VA115M524KSA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U97VA085M521USA | 97.0 | \$700 | Ruud | U97VA115M524USA | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | U97VA100M521USA | 97.0 | \$700 | RUUD | U98VA060M317USA | 98.7 | \$700 |
| Rheem-Ruud Manufacturing | U97VA115M524USA | 97.0 | \$700 | RUUD | U98VA070M317USA | 98.3 | \$700 |
| Rheem-Ruud Manufacturing | U97VB060M317USA | 97.0 | \$700 | RUUD | U98VA085M521USA | 98.1 | \$700 |
| Rheem-Ruud Manufacturing | U97VB070M317USA | 97.0 | \$700 | RUUD | U98VA100M521USA | 98.1 | \$700 |
| Rheem-Ruud Manufacturing | U97VB085M521USA | 97.0 | \$700 | RUUD | U98VA115M524USA | 98.6 | \$700 |
| Rheem-Ruud Manufacturing | U97VB100M521USA | 97.0 | \$700 | Style Crest Inc. | VMC1-50DV3 | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | U97VB115M524USA | 97.0 | \$700 | Style Crest Inc. | VMC1-75DV3 | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | U98VB060M317USA | 98.7 | \$700 | Stylecrest Inc. | VMA1-75N | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | U98VB070M317USA | 98.3 | \$700 | Sure | B96VA0602317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | U98VB085M521USA | 98.1 | \$700 | Sure | B96VA0702317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | U98VB100M521USA | 98.1 | \$700 | Sure | B96VA0852521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | U98VB115M524USA | 98.6 | \$700 | Sure | B96VA1002521MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA0401317MSA | 95.0 | \$500 | Sure | GF902U060CS36 | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA0601317MSA | 95.0 | \$500 | Sure | GF902U075CS36 | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA0701317MSA | 95.0 | \$500 | Sure | GF902U105CS60 | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA0851521MSA | 95.0 | \$500 | Sure | S95TA0601317MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA1001521MSA | 95.0 | \$500 | Sure | S95TA1151524MSA | 95.0 | \$500 |
| Rheem-Ruud Manufacturing | W92TA1151524MSA | 95.0 | \$500 | Sure | S96VA0402317MSA | 96.0 | \$500 |
| Rheem-Ruud Manufacturing | W95TC0601317MSA | 95.0 | \$500 | Tappan | FG7MQ060*-VB | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | W95TC1151524MSA | 95.0 | \$500 | Tappan | FG7MQ080*-VC | 97.2 | \$700 |
| Rheem-Ruud Manufacturing | W96TA0402317MSA | 96.0 | \$500 | Tappan | FG7MQ100*-VC | 97.4 | \$700 |
| Rheem-Ruud Manufacturing | W96TA0602317MSA | 96.0 | \$500 | Tappan | FG7MQ120*-VD | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | W96TA0702317MSA | 96.0 | \$500 | Tappan | FG7TC120*-*D* | 95.1 | \$500 |
| Rheem-Ruud Manufacturing | W96TA0852521MSA | 96.0 | \$500 | Tappan | KG7TC120*-*D* | 95.1 | \$500 |
| Rheem-Ruud Manufacturing | W96TA1002521MSA | 96.0 | \$500 | Tempstar | F9MAC0601714A | 97.0 | \$700 |
| Rheem-Ruud Manufacturing | W96TA1152524MSA | 96.0 | \$500 | Tempstar | F9MAC0602120A | 98.0 | \$700 |
| Rheem/RUUD | R95TC0401317MSA | 95.0 | \$500 | Tempstar | F9MAC0801714A | 97.0 | \$700 |
| Rheem/RUUD | R95TC0701317MSA | 95.0 | \$500 | Tempstar | F9MAC0802120A | 97.0 | \$700 |
| Rheem/RUUD | R95TC0851521MSA | 95.0 | \$500 | Tempstar | F9MAC1002122A | 97.0 | \$700 |
| Rheem/RUUD | R95TC1001521MSA | 95.0 | \$500 | Tempstar | F9MAC1202422A | 97.0 | \$700 |
| Rheem/RUUD | R96TA0402317MSA | 96.0 | \$500 | Tempstar | F9MAE0601714A | 97.0 | \$700 |
| Rheem/RUUD | R96TA0602317MSA | 96.0 | \$500 | Tempstar | F9MAE0602120A | 98.0 | \$700 |
| Rheem/RUUD | R96TA0702317MSA | 96.0 | \$500 | Tempstar | F9MAE0801714A | 97.0 | \$700 |
| Rheem/RUUD | R96TA0852521MSA | 96.0 | \$500 | Tempstar | F9MAE0802120A | 97.0 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|---------------------|------------------|------|--------|---------------------------|-----------------|------|--------|
| Tempstar | F9MAE1002122A | 97.0 | \$700 | Trane | S9V2D120D5PS*** | 96.0 | \$500 |
| Tempstar | F9MAE1202422A | 97.0 | \$700 | Trane | S9V2D120U5PS*** | 96.0 | \$500 |
| Tempstar | F9MVE0401410A | 96.0 | \$500 | Trane | TDH2B060A9V3VB* | 96.0 | \$500 |
| Tempstar | F9MVE0401712A | 96.0 | \$500 | Trane | TDH2B080A9V3VB* | 96.0 | \$500 |
| Tempstar | F9MVE0601412A | 95.0 | \$500 | Trane | TDH2B080A9V4VB* | 95.0 | \$500 |
| Tempstar | F9MVE0601714A | 96.0 | \$500 | Trane | TDH2C100A9V4VB* | 96.0 | \$500 |
| Tempstar | F9MVE0801716A | 96.0 | \$500 | Trane | TDH2D120A9V5VB* | 96.0 | \$500 |
| Tempstar | F9MVE0802120A | 96.0 | \$500 | Trane | TDHMB060BCV3VB* | 95.0 | \$500 |
| Tempstar | F9MVE1002120A | 96.0 | \$500 | Trane | TDHMB080ACV3VB* | 96.0 | \$500 |
| Tempstar | F9MVE1202422A | 96.0 | \$500 | Trane | TDHMC100ACV4VB* | 96.0 | \$500 |
| Tempstar | F9MVT0401410A | 96.0 | \$500 | Trane | TDHMD120BCV5VB* | 95.0 | \$500 |
| Tempstar | F9MVT0601714A | 96.0 | \$500 | Trane | TUH1D120A9H51B* | 95.0 | \$500 |
| Tempstar | F9MVT0801716A | 96.0 | \$500 | Trane | TUH2B060A9V3VB* | 97.0 | \$700 |
| Tempstar | F9MVT0802120A | 96.0 | \$500 | Trane | TUH2B080A9V3VB* | 97.0 | \$700 |
| Tempstar | F9MVT1002120A | 96.0 | \$500 | Trane | TUH2B080A9V4VB* | 97.0 | \$700 |
| Tempstar | F9MVT1202422A | 96.0 | \$500 | Trane | TUH2C100A9V4VB* | 96.7 | \$500 |
| Tempstar | F9MXE0401712A | 96.0 | \$500 | Trane | TUH2C100A9V5VB* | 96.7 | \$500 |
| Tempstar | F9MXE0601412A | 95.5 | \$500 | Trane | TUH2D120A9V5VB* | 96.7 | \$500 |
| Tempstar | F9MXE1002120A* | 96.0 | \$500 | Trane | TUHMB060ACV3VB* | 97.3 | \$700 |
| Tempstar | F9MXT0401410A | 96.0 | \$500 | Trane | TUHMB080ACV3VB* | 96.7 | \$500 |
| Tempstar | F9MXT0401712A | 96.0 | \$500 | Trane | TUHMD120ACV5VB* | 97.0 | \$700 |
| Tempstar | F9MXT0601412A | 95.0 | \$500 | Trane & American Standard | ADH2B060A9V3VB* | 96.0 | \$500 |
| Tempstar | F9MXT0601714A | 96.0 | \$500 | Trane & American Standard | ADH2B080A9V3VB* | 96.0 | \$500 |
| Tempstar | F9MXT0801716A | 96.0 | \$500 | Trane & American Standard | ADH2B080A9V4VB* | 95.0 | \$500 |
| Tempstar | F9MXT0802120A | 96.0 | \$500 | Trane & American Standard | ADH2C100A9V4VB* | 96.0 | \$500 |
| Tempstar | F9MXT1002120A | 96.0 | \$500 | Trane & American Standard | ADH2D120A9V5VB* | 96.0 | \$500 |
| Tempstar | F9MXT1202422A | 96.0 | \$500 | Trane & American Standard | ADHMB060BCV3VB* | 95.0 | \$500 |
| Thermal Zone | TZ92UP105T(A,AX) | 95.0 | \$500 | Trane & American Standard | ADHMB080ACV3VB* | 96.0 | \$500 |
| Thermal Zone | TZ92UP603T(A,AX) | 95.0 | \$500 | Trane & American Standard | ADHMD120BCV5VB* | 95.0 | \$500 |
| Thermal Zone | TZ95MSX060B30A | 95.0 | \$500 | Trane & American Standard | AUH1D120A9H51B* | 95.0 | \$500 |
| Thermal Zone | TZ95MSX115D50A | 95.0 | \$500 | Trane & American Standard | AUH2B060A9V3VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDV040B30A | 96.0 | \$500 | Trane & American Standard | AUH2B080A9V3VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDV060B30A | 96.0 | \$500 | Trane & American Standard | AUH2B080A9V4VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDV070B30A | 96.0 | \$500 | Trane & American Standard | AUH2C100A9V4VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDV100C50A | 96.0 | \$500 | Trane & American Standard | AUH2C100A9V5VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDVA060B30A | 96.0 | \$500 | Trane & American Standard | AUH2D120A9V5VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDVA070B30A | 96.0 | \$500 | Trane & American Standard | AUHMB060ACV3VB* | 97.0 | \$700 |
| Thermal Zone | TZ96MDVA100C50A | 96.0 | \$500 | Trane & American Standard | AUHMB080ACV3VB* | 97.0 | \$700 |
| Thermo Products | CLHS1-075T42N | 95.0 | \$500 | Trane & American Standard | AUHMD120ACV5VB* | 97.0 | \$700 |
| Thermo Products | CLHS1-100T48N | 95.0 | \$500 | Trane & American Standard | M952V060BD36AB* | 96.0 | \$500 |
| Thermo Products | CMC1-50DV3 | 95.0 | \$500 | Trane & American Standard | M952V060BU36AB* | 97.0 | \$700 |
| Thermo Products | CMC1-75DV3 | 95.0 | \$500 | Trane & American Standard | M952V080BD36AB* | 96.0 | \$500 |
| Thermo Products LLC | CLQS1-050T36N | 95.0 | \$500 | Trane & American Standard | M952V080BU36AB* | 97.0 | \$700 |
| Thermo Products LLC | CLQS1-075T42N | 95.0 | \$500 | Trane & American Standard | M952V100CD48AB* | 96.0 | \$500 |
| Thermo Products LLC | CLQS1-100T48N | 95.0 | \$500 | Trane & American Standard | M952V100CU48AB* | 97.0 | \$700 |
| Thermo Products LLC | CLQS1-125T60N | 95.0 | \$500 | Trane & American Standard | M952V120DD60AB* | 96.0 | \$500 |
| Trane | S9V2B040D3PS*** | 96.0 | \$500 | Trane & American Standard | M952V120DU60AB* | 97.0 | \$700 |
| Trane | S9V2B040U3PS*** | 96.0 | \$500 | Trane & American Standard | TDH2B060A9V3VB* | 96.0 | \$500 |
| Trane | S9V2B060D3PS*** | 96.0 | \$500 | Trane & American Standard | TDH2B080A9V3VB* | 96.0 | \$500 |
| Trane | S9V2B060U3PS*** | 96.0 | \$500 | Trane & American Standard | TDH2B080A9V4VB* | 95.0 | \$500 |
| Trane | S9V2B060U4PS*** | 96.0 | \$500 | Trane & American Standard | TDH2C100A9V4VB* | 96.0 | \$500 |
| Trane | S9V2B080D3PS*** | 96.0 | \$500 | Trane & American Standard | TDH2D120A9V5VB* | 96.0 | \$500 |
| Trane | S9V2B080D4PS*** | 96.0 | \$500 | Trane & American Standard | TDHMB060BCV3VB* | 95.0 | \$500 |
| Trane | S9V2B080U3PS*** | 96.0 | \$500 | Trane & American Standard | TDHMB080ACV3VB* | 96.0 | \$500 |
| Trane | S9V2B080U4PS*** | 96.0 | \$500 | Trane & American Standard | TDHMD120BCV5VB* | 95.0 | \$500 |
| Trane | S9V2C080U5PS*** | 96.0 | \$500 | Trane & American Standard | TUH1D120A9H51B* | 95.0 | \$500 |
| Trane | S9V2C100D4PS*** | 96.0 | \$500 | Trane & American Standard | TUH2B060A9V3VB* | 97.0 | \$700 |
| Trane | S9V2C100D5PS*** | 96.0 | \$500 | Trane & American Standard | TUH2B080A9V4VB* | 97.0 | \$700 |
| Trane | S9V2C100U4PS*** | 96.0 | \$500 | Trane & American Standard | TUH2C100A9V4VB* | 97.0 | \$700 |
| Trane | S9V2C100U5PS*** | 96.0 | \$500 | Trane & American Standard | TUH2C100A9V5VB* | 97.0 | \$700 |

| Manufacturer | Model | AFUE | Rebate | Manufacturer | Model | AFUE | Rebate |
|--|-----------------|------|--------|--------------|----------------|------|--------|
| Trane and American Standard Heating and Air Conditioning | TDH1C085A9H41B* | 95.0 | \$500 | Wolf Steel | CTV040T2B | 97.0 | \$700 |
| Trane and American Standard Heating and Air Conditioning | TDH1D110A9H51B* | 95.0 | \$500 | Wolf Steel | CTV060T3A | 97.1 | \$700 |
| Trane and American Standard Heating and Air Conditioning | TUH1B060A9H31** | 95.0 | \$500 | Wolf Steel | CTV060T3B | 97.0 | \$700 |
| Trane and American Standard Heating and Air Conditioning | TUH1B080A9H31** | 95.0 | \$500 | Wolf Steel | CTV080T3A | 97.0 | \$700 |
| Trane and American Standard Heating and Air Conditioning | TUH1C100A9H41** | 95.0 | \$500 | Wolf Steel | CTV080T3B | 97.0 | \$700 |
| Trane and American Standard Heating and Air Conditioning | TUHMC100ACV4V** | 96.0 | \$500 | Wolf Steel | CTV100T5A | 97.0 | \$700 |
| United Refrigeration | TZ96MDVA085C50A | 96.0 | \$500 | Wolf Steel | CTV100T5B | 97.0 | \$700 |
| Weatherking | W95TA0601317MSA | 95.0 | \$500 | Wolf Steel | CTV120T5A | 97.0 | \$700 |
| Weatherking | W95TA1151524MSA | 95.0 | \$500 | Wolf Steel | CTV120T5B | 97.0 | \$700 |
| WeatherKing | W95TC0401317MSA | 95.0 | \$500 | Wolf Steel | NEV040T2A | 95.0 | \$500 |
| WeatherKing | W95TC0601317MSA | 95.0 | \$500 | Wolf Steel | NEV060T3A | 95.0 | \$500 |
| WeatherKing | W95TC0701317MSA | 95.0 | \$500 | Wolf Steel | NEV080T3A | 95.0 | \$500 |
| WeatherKing | W95TC0851521MSA | 95.0 | \$500 | Wolf Steel | NEV080T4A | 95.0 | \$500 |
| WeatherKing | W95TC1001521MSA | 95.0 | \$500 | Wolf Steel | NEV100T5A | 95.0 | \$500 |
| WeatherKing | W95TC1151524MSA | 95.0 | \$500 | Wolf Steel | NEV120T5A | 95.0 | \$500 |
| Weatherking | W96VA0402317MSA | 96.0 | \$500 | Wolf Steel | NPV040T2B | 96.0 | \$500 |
| Weatherking | W96VA0602317MSA | 96.0 | \$500 | Wolf Steel | NPV045T2A | 95.3 | \$500 |
| Weatherking | W96VA0702317MSA | 96.0 | \$500 | Wolf Steel | NPV060T3A | 95.3 | \$500 |
| Weatherking | W96VA1002521MSA | 96.0 | \$500 | Wolf Steel | NPV060T3B | 96.0 | \$500 |
| Westinghouse | FG7MQ060*-VB | 97.0 | \$700 | Wolf Steel | NPV080T3A | 95.3 | \$500 |
| Westinghouse | FG7MQ080*-VC | 97.2 | \$700 | Wolf Steel | NPV080T3B | 96.0 | \$500 |
| Westinghouse | FG7MQ100*-VC | 97.4 | \$700 | Wolf Steel | NPV080T4B | 96.0 | \$500 |
| Westinghouse | FG7MQ120*-VD | 97.0 | \$700 | Wolf Steel | NPV100T5A | 96.0 | \$500 |
| Westinghouse | FG7TC120*-D* | 95.1 | \$500 | Wolf Steel | NPV100T5B | 96.0 | \$500 |
| Westinghouse | KG7TC120*-D* | 95.1 | \$500 | Wolf Steel | NPV120T5A | 95.3 | \$500 |
| Whirlpool Gold | WGFM295090V5C | 96.1 | \$500 | Wolf Steel | NPV120T5B | 96.0 | \$500 |
| Wolf Steel | CEV040T2A | 95.0 | \$500 | Wolf Steel | NPX030S2B | 95.0 | \$500 |
| Wolf Steel | CEV060T3A | 95.0 | \$500 | Wolf Steel | NPX040S2B | 95.0 | \$500 |
| Wolf Steel | CEV080T3A | 95.0 | \$500 | Wolf Steel | NPX045S2A | 95.0 | \$500 |
| Wolf Steel | CEV080T4A | 95.0 | \$500 | Wolf Steel | NPX060S3A | 95.0 | \$500 |
| Wolf Steel | CEV100T5A | 95.0 | \$500 | Wolf Steel | NPX060S3B | 95.0 | \$500 |
| Wolf Steel | CEV120T5A | 95.0 | \$500 | Wolf Steel | NPX080S3A | 95.0 | \$500 |
| Wolf Steel | CPV045T2A | 95.3 | \$500 | Wolf Steel | NPX080S3B | 95.0 | \$500 |
| Wolf Steel | CPV060T3A | 95.3 | \$500 | Wolf Steel | NPX100S5A | 95.0 | \$500 |
| Wolf Steel | CPV060T3B | 96.0 | \$500 | Wolf Steel | NPX100S5B | 95.0 | \$500 |
| Wolf Steel | CPV080T3A | 95.3 | \$500 | Wolf Steel | NPX120S5A | 95.0 | \$500 |
| Wolf Steel | CPV080T3B | 96.0 | \$500 | Wolf Steel | NPX120S5B | 95.0 | \$500 |
| Wolf Steel | CPV100T5A | 96.0 | \$500 | Wolf Steel | NSX045T2A | 95.3 | \$500 |
| Wolf Steel | CPV100T5B | 96.0 | \$500 | Wolf Steel | NSX060T3A | 95.3 | \$500 |
| Wolf Steel | CPV120T5A | 95.3 | \$500 | Wolf Steel | NSX080T3A | 95.3 | \$500 |
| Wolf Steel | CPV120T5B | 96.0 | \$500 | Wolf Steel | NSX100T5A | 96.0 | \$500 |
| Wolf Steel | CPX030S2B | 95.0 | \$500 | Wolf Steel | NSX120T5A | 95.3 | \$500 |
| Wolf Steel | CPX040S2B | 95.0 | \$500 | Wolf Steel | NUV040T2B | 97.0 | \$700 |
| Wolf Steel | CPX045S2A | 95.0 | \$500 | Wolf Steel | NUV060T3A | 97.1 | \$700 |
| Wolf Steel | CPX060S3A | 95.0 | \$500 | Wolf Steel | NUV060T3B | 97.0 | \$700 |
| Wolf Steel | CPX060S3B | 95.0 | \$500 | Wolf Steel | NUV080T3A | 97.0 | \$700 |
| Wolf Steel | CPX080S3A | 95.0 | \$500 | Wolf Steel | NUV080T3B | 97.0 | \$700 |
| Wolf Steel | CPX080S3B | 95.0 | \$500 | Wolf Steel | NUV100T5A | 97.0 | \$700 |
| Wolf Steel | CPX100S5A | 95.0 | \$500 | Wolf Steel | NUV120T5A | 97.0 | \$700 |
| Wolf Steel | CPX100S5B | 95.0 | \$500 | York | CP9C060B12MP12 | 98.0 | \$700 |
| Wolf Steel | CPX120S5A | 95.0 | \$500 | York | CP9C080B12MP12 | 98.0 | \$700 |
| Wolf Steel | CPX120S5B | 95.0 | \$500 | York | CP9C080C16MP12 | 98.0 | \$700 |
| Wolf Steel | CSX045T2A | 95.3 | \$500 | York | CP9C100C16MP12 | 98.0 | \$700 |
| Wolf Steel | CSX060T3A | 95.3 | \$500 | York | CP9C100C20MP12 | 98.0 | \$700 |
| Wolf Steel | CSX080T3A | 95.3 | \$500 | York | LP9C060B12MP12 | 98.0 | \$700 |
| Wolf Steel | CSX100T5A | 96.0 | \$500 | York | LP9C080B12MP12 | 98.0 | \$700 |
| Wolf Steel | CSX120T5A | 95.3 | \$500 | York | LP9C080C16MP12 | 98.0 | \$700 |
| | | | | York | LP9C100C16MP12 | 98.0 | \$700 |
| | | | | York | LP9C100C20MP12 | 98.0 | \$700 |
| | | | | York | TM9E040A10MP11 | 95.0 | \$500 |

| Manufacturer | Model | AFUE | Rebate |
|--------------|------------------|------|--------|
| York | TM9E060B12MP11 | 95.0 | \$500 |
| York | TM9E080B12MP11 | 95.0 | \$500 |
| York | TM9E080C16MP11 | 95.0 | \$500 |
| York | TM9E100C16MP11 | 95.0 | \$500 |
| York | TM9E100C20MP11 | 95.0 | \$500 |
| York | TM9E120D20MP11 | 95.0 | \$500 |
| York | TM9V040A10MP11 | 96.0 | \$500 |
| York | TM9V060B12MP11 | 96.0 | \$500 |
| York | TM9V080B12MP11 | 96.0 | \$500 |
| York | TM9V080C16MP11 | 96.0 | \$500 |
| York | TM9V100C16MP11 | 96.0 | \$500 |
| York | TM9V100C20MP11 | 96.0 | \$500 |
| York | TM9V120D20MP11 | 96.0 | \$500 |
| York | TM9Y040A10MP11 | 96.0 | \$500 |
| York | TM9Y060B12MP11 | 95.0 | \$500 |
| York | TM9Y080B12MP11 | 96.0 | \$500 |
| York | TM9Y080C16MP11 | 96.0 | \$500 |
| York | TM9Y100C16MP11 | 96.0 | \$500 |
| York | TM9Y100C20MP11 | 96.0 | \$500 |
| York | TM9Y120D20MP11 | 96.0 | \$500 |
| York | TP9C060B12MP12 | 98.0 | \$700 |
| York | TP9C080B12MP12 | 98.0 | \$700 |
| York | TP9C080C16MP12 | 98.0 | \$700 |
| York | TP9C100C16MP12 | 98.0 | \$700 |
| York | TP9C100C20MP12 | 98.0 | \$700 |
| York | TP9C120D20MP12 | 98.0 | \$700 |
| York | YP9C060B12MP12 | 98.0 | \$700 |
| York | YP9C060B12MP12CA | 97.5 | \$700 |
| York | YP9C080B12MP12 | 98.0 | \$700 |
| York | YP9C080B12MP12CA | 97.5 | \$700 |
| York | YP9C080C16MP12 | 98.0 | \$700 |
| York | YP9C080C16MP12CA | 97.7 | \$700 |
| York | YP9C100C16MP12 | 98.0 | \$700 |
| York | YP9C100C16MP12CA | 97.7 | \$700 |
| York | YP9C100C20MP12 | 98.0 | \$700 |
| York | YP9C100C20MP12CA | 97.7 | \$700 |
| York | YP9C120D20MP12 | 98.0 | \$700 |
| York | YP9C120D20MP12CA | 98.0 | \$700 |